What Home Buyers Want to Know

Home Address: 2722 Green Falls Ln. Richmond TX 77406

Electricity Costs: High: \$265.00 Low: \$93.00

Gas Costs: High: \$72.00 Low: \$28.00

Age of Roof: 19 years

1. A/C Unit One: New—September 2017

2. A/C Unit Two: New-September 2019

3. 80 Series Thermostat-September 2019 - EMERSON

4. Furnace: New—September 2019

5. Water Heater—Approximately 2011

6. Water Softener

7. Reverse Osmosis System at kitchen sink with connection to refrigerator

8. Bosch Dishwasher March 2018

9. New Microwave October 2020

10. New kitchen sink February 2011

11. New Disposal February 2011

12. New Garage Door Springs August 2014

13. Floating Wood Flooring installed February 2015—can be sanded once

14. New Kitchen Faucet August 2017—GROHE 30306DC0 Eurosmart

15. Wired Smoke Detectors replaced November 2017

16. Roof repair above Kitchen and Breakfast Room March 2017

17. New carpet in three bedrooms July 2019

18. Chandelier Lighting Fixture in Dining Room November 2020

19. Recessed Lighting in Living Room

20. Kitchen Island Lighting

21. Wiring for light over Breakfast Room Table

22. Gas Logs installed in fireplace

23. New Fireplace Mantel

24. New slate tile around fireplace

25. Ceiling fans in all bedrooms, 2 bathrooms, living room and front office (8)

26. All Curtain Rods

27. Re-stained decking 2020

28. Added to Sprinkler System along back of back garden

29. Added garden faucet at garage side door—tied to sprinkler system

- 30. Gutters on Garage
- 31. Two Dual Flush Toilets
- 32. Mirror and Lighting fixture in Powder Room
- 33. Powder Room Faucet
- 34. Tubular Skylight Sun Tunnel in Secondary Bathroom
- 35. Towel Racks in Secondary Bathroom and Powder Room
- 36. Electric Warming Towel Rack in Master Bathroom—gets very hot—keep towels on it.
- 37. Framed Glass Enclosure in Master Bathroom with Cardinal 10 Surface Protection Glass November 2020 installed by The Glass Store, Inc. 21925 Franz Rd., Suite 604, Katy, TX 77449 Phone: 281-347-2211
- 38. Master Bath Sink Faucets
- 39. Master Bath Shower Faucet
- 40. Roof and Ceiling Repair in back bedroom by bathroom

Included with the house:

Rug in Front Entryway
Mirror in Dining Room
Washing Machine Hoses
Kitchen Under Cabinet Light
Step Ladder
Hat Rack at Back Door

Pecan Lakes is a very quiet neighborhood with retirees and young families.