

PHONE: 866.772.8813

INFO@TRUELINETECH.COM WWW.TRUELINFTFCH.COM

Page 1 of 2 in order 94593 File number: 7440-17-1087

Lender:

Buyer: ERIC BROUSSARD AND JULIE BROUSSARD

Seller: PAUL LOCK AND CHRISTINA LOCK

Completed: 3/15/2017 Surveyed: 3/13/2017

COMMUNITY NUMBER:

PANEL: 48201C0645L SUFFIX:

INDEX DATE: F.I.R.M DATE:

ZONE: X

Premises: 10034 BAYOU GLEN ROAD, HOUSTON, TEXAS 77042 HARRIS

Description of encroachments, violations or other points of interest at the time of the inspection:

NONE VISIBLE



CERTIFIED TO:

TEXAS AMERICAN TITLE COMPANY,

LEGAL DESCRIPTION: LOT 810, BLOCK 30, BRIARGROVE PARK, 1, AS PER PLAT THEREOF AS RECORDED IN PLAT BOOK . PAGE OF THE PUBLIC RECORD OF COUNTY HARRIS. TEXAS.

TRUELINE TECHNOLOGIES LLC: THE FOLLOWING PRODUCT HAS BEEN COMPLETED BY THE STATE LICENSED LAND SURVEYING FIRM AS INDICATED ON THE FOLLOWING PAGE. TRUELINE TECHNOLOGIES LLC PROVIDES THE DIGITAL TRANSMISSION AND ARCHIVING OF THE PRODUCT, AND IS NOT INVOLVED IN ANY FACET OF THE TECHNICAL FIELD WORK PERFORMED AND MAKES NO WARRANTIES AS TO THE ACCURACY OF SUCH WORK, ALL TRANSMISSIONS OF THE PRODUCT ARE VIA A SECURE 'SHAL'! SECURE HASH MESSAGE DIGEST AUTHENTICATION CODE WITHIN ITS SIGNATURE FILE. A MANUALLY SIGNED AND SEALED LOG OF THIS SURVEY'S SIGNATURE FILE IS KEPT ON FILE AT THE PERFORMING SURVEYORS OFFICE.

PRINTING PROCEDURES: BECAUSE THIS FILE HAS BEEN SENT ELECTRONICALLY, IT IS IMPERATIVE THAT THE PRINT SETTINGS BE CORRECT IN ORDER TO DEPICT AN ACCURATE REPRESENTATION OF THIS DOCUMENT ON PAPER. INSTRUCTIONS: WHILE VIEWING THE PRODUCT IN ADOBE READER, SELECT PRINT UNDER THE FILE TAB, SELECT COLOR PRINTER. UNDER PRINT RANGE - SELECT ALL. UNDER PAGE HANDLING, SELECT NONE FOR PAGE SCALING AND UNCHECK AUTO ROTATE AND CENTER. CHOOSE PAPER SOURCE BY PDF SIZE. CLICK PRINT.

10034 Bayou Glen Road


Being Lot 810, in Block 30, of Briargrove Park, Section One (1), a Subdivision in Harris County, Texas, according to the Map or Plat thereof, recorded in Volume 72, Page 19 of the Map Records of Harris County, Texas.

LEGEND

- O 1/2" ROD FOUND ⊗ 1/2" ROD SET ○ 5/8" ROD FOUN
- X" FOUND/SET
- FENCE POST
- CM CONTROLLING
- AC AIR CONDITIONER
- PE POOL EQUIPMENT
- TE TRANSFORMER
- COLUMN
- POWER POLE
 UNDERGROUND
 ELECTRIC
- △ OVERHEAD ELECTRIC
- OVERHEAD ELECTRIC POWER
- -OFS-OVERHEAD ELECTRIC SERVICE
- -0-CHAIN LINK
- пп WOOD FENCE 0.5'
- IRON FENCE
- BARBED WIRE
- DOUBLE SIDED WOOD FENCE
- EDGE OF ASPHALT
- EDGE OF GRAVEL CONCRETE

COVERED AREA





EXCEPTIONS:

Date:

NOTE: PROPERTY SUBJECT TO TERMS, CONDITIONS, AND EASEMENTS CONTAINED IN INSTRUMENTS RECORDED IN VOL. 72, PG. 19; VOL. 4055, PG. 247; VOL. 4055, PG. 8061; VOL. 4055, PG. 547; CCF# J821548; K631370; M056949; R916342; U212262; V208914; V505544; W108019; M056949; 20090500942; 20110548176; 20130243715; 20140534358; 20150326450;

NOTE: BEARINGS, EASEMENTS AND BUILDING LINES ARE BY RECORDED PLAT UNLESS OTHERWISE NOTED.

FLOOD NOTE: According to the F.I.R.M. No. 48201C0645L, this property does lie in Zone X and DOES NOT lie within the 100 year flood zone.

This survey is made in conjunction with the information provided by Trueline Technologies. Use of this survey by any other parties and/or for other purposes shall be at user's own risk and any loss resulting from other use shall not be the responsibility of the undersigned. This is to certify that I have on this date made a careful and accurate survey on the ground of the subject property. The plot hereon is a correct and accurate representation of the property lines and dimensions are as indicated; location and type of buildings are as shown; and EXCEPT AS SHOWN, there are no visible and apparent encroachments or protrusions on the ground.

	Drawn By: LED	CDC SE OF
	Scale: 1" = 30'	SURVEYING IN
	Date: 03/14/17	THOMAS WILLIAM MAUK ONW-HOUST AUSTN-SW ANTOXO-EST WHY ELEVISITE COST WHY ELEVISION COST W
Purchaser	GF No.: 	12025 Shiloh Road, Ste. 230 Dallas, TX 75228 P 214,349,9485 F 214,349,2216
Purchaser	Job No. 1704788	Firm No. 10168800 www.cbginctx.com RPIS NO. 5119

Accepted by: