Maintenance and improvements to 6923 Oak Hill Drive, Houston, TX

- 1. Replace first row cedar shingles
- 2. Paint entire house inside and out
- 3. Replace and repair sheetrock throughout house
- 4. Remove hardwood flooring and replace with new tile flooring through out
- 5. Replace and paint new interior doors
- 6. Replace all baseboard
- 7. Install vent hood, granite countertops, new sink, faucet and backsplash
- 8. Clean and refurbish kitchen cabinets
- 9. New electric throughout house
- 10. Move stove and gas to new wall
- 11. Open wall from living space to kitchen
- 12. Re-pipe plumbing in house
- 13. Level breakfast room with concrete
- 14. Replace exterior wall in breakfast room
- 15. Replace door from breakfast room to garage
- 16. Replace water heater
- 17. Remove storage closet in connected garage to open up
- 18. New metal fencing and gate across back of yard
- 19. New siding on separate garage building
- 20. Replace bottom plates under separate garage walls
- 21. New personnel door for separate garage
- 22. Two new windows in separate garage
- 23. Rewire separate garage electrical system
- 24. Repaint separate garage to match house
- 25. Walls of main house are now insulated
- 26. New lighting fixtures
- 27. New central air and heat and associated ductwork