## COMPLETED REPAIRS / UPDATES 4404 FLOYD ST.

## **Regular Inspection:**

Pg 8: Carpet replaced (all) and wood floors refinished (all) Pg 8-Doors: Replaced laundry room and office doors. Pg 9-All windows sealed and all window trims repainted

## Stucco Inspection:

Pages 6-9—When we met the stucco inspector at the house, he explained that the high moisture levels showing were from water penetration at the windows. He said we had to use professional caulking to seal all windows and then repaint all the window trims. That was done.

## **Updates**:

Aug-Full interior paint
Dec-New Carpet
Dec-Refinish wood floors
Dec-Paint kitchen cabinets white
Dec-Refinish wood stair treads and paint risers
Dec-New laundry & office doors

