-		
	Company	Insured Location
	American Bankers Insurance Company	Michael and Ida Sullivan 5518 Regal Landing Dr. Kingwood
Adjuster Name	4	Date of Report Date of Loss Policy Number
Mac McDougali	096084 SIS-096084	12/20/2017 8/28/2017 87051000055001

### MORTGAGE COMPANY

#### None.

## ORIGIN OF FLOODING

Upon assignment we contacted the insured on 9/9/2017 and made arrangements to inspect the loss with the Insured. Our inspection on 9/16/2017 found there to be a general condition of flooding on 8/28/2017 The flood was caused by rain water accumulation that overflowed the San Jacinto River which flooded the risk and the adjacent properties.

The exterior water height was 15" and the interior water height was 8". The flood water remained in the risk for over three days. These facts are also listed on the NFIP Preliminary Report.

There was no damage from any cause other than flood seen at the time of our inspection.

# PRIOR LOSS INFORMATION

The loss notice **does not** list a prior loss. The survey form, filled out and signed by the Insured **does not** list a prior loss at this location.

#### COVERAGE

Coverage was verified by a copy of the loss notice provided at the time of assignment. The flood loss occurred on 8/28/2017 which falls in between the policy effective dates of 5/2/2017

The Insured carries a homeowner's policy with Homeowners insurance Co. The Insured has confirmed their policy with Homeowners Insurance Co. does not cover flood damage. There are no additional policies that cover flood damage.

BUILDING ADJUSTMENT