

5402 Highland Falls Lane – Home Improvements

Roof Replaced	2012
Replaced and upsized both AC/Furnace units to 3.5 ton, 13 Seer	May, 2010
Replastered the pool and refinished the pool decking	2020
Replaced pool pump, heater, and spa air blower	2020
Replaced all pool cartridge filters and the manifold	2019
Entire perimeter backyard fence replaced	2020
Replaced both water heaters (50 gallon)	2013
Installed water softener and reverse osmosis water system (kitchen)	2013
Installed plank “woodlike” tile in Master bedroom, Dining Room, and Living room	2016
Replaced kitchen countertops with high end granite	2016
Replaced dishwasher	2015
Refinished kitchen cabinets	2016
Replaced kitchen fixtures and sink	2016
Installed cabinet and high end granite countertops in downstairs half bath	2016
Installed granite countertops in all secondary bathrooms	2016
Master bathroom – installed granite countertops and fixtures	2016
Plush carpet installed	2016
Installed recessed LED lights in kitchen, family room, and upstairs great room	2020
Refinished secondary bathroom bathtubs	2016
Landscape lighting installed in front and back yards	2019