ALL BUILDING LINES AND EASEMENTS
ARE PER THE PECORDED PLAT, UNLESS
OTHERWISE NOTED. (PER PLAT) R=60.00' D= 58'56'55" L=61.73' Ch=S60'31'50'E 59 04' R=60.00' D= 59'01'19" FOUND 5/8" L=61.81' Ch=S60'35'51"E 59.11 276.94") LOT 17 FOUND 5/8 REFERENCE N58.39'2 TO BELOW LAN CONTROL MONUMENT FOUND 5/8 IRON ROD A. 10:01.4 00 146. LOT 15 NO0'00'00' LOT16 NOO'02'22'E PR PE BLOCK TWO WESTERN. PER (CCF# 2007-045131 & CCF# 2008-083890) ASSESS ASSESSED. POWER POLE PLAT: N90'00'00"W 171.00') N89'59'59"W 170.98' FOUND 5/8 LOT 10 LOT 9 SCALE: 1" = 60' DATE: 2/9/2009 REV: 6/9/2009 FINAL SURVEY

I hereby certify to Dennis L. Beisert, Baker Mortgage Company, Inc., and to Stewart Title Guaranty Company that this plat is a true representation of an on the ground survey made on 2/5/2009 of Lot 16, Block 2, McCall Sound Section One, a subdivision in the John H. Edwards Survey, A-13, Montgomery County, Texas, a correct map of which is recorded in Cabinet Z, Sheet 544, of the Map Records of Montgomery County, Texas. Unless otherwise shown, there are no encroachments on this property and all improvements were within the boundaries at the time of this survey. This professional service substantially conforms to the current Texas Surveyors Association Standards and Specifications for a Category 1A, Condition III survey.

This property is located in Zone X and is not within the 100-year floodplain as shown on FIRM Community Panel Number 48339C0655 F, effective date December 19, 1996.

This survey was completed with the benefit of a title commitment furnished by Stewart Title Guaranty Company, G.F.# 09400441, effective date May 17, 2009.

Hol Moyer, R.P. S. Texas Registration No. 5656

TEXAS BOARD OF PROFESSIONAL LAND SURVEYING
12100 PARK 35 CRICLE
BLOG A SUITE 156, MC-230
AUSTIN, TEXAS FORMS
PACING 512-238-5263
FAX 512-238-5253



JOB NO 09127 JOB NO 09024