

- 12) SHORT FORM BLANKET EASEMENT BY H.C.C.F. NO. 2006052620.
- 13.) THIS SURVEY IS NOT TO BE USED FOR FUTURE CONSTRUCTION PURPOSES.

l	5. U.E. ON WEST SIDE OF SUBJECT PROPERTY BY F.B.C.C.F. NO. 2017 7.) FENCE LOCATIONS SHOWN HEREON ARE FROM APPROXIMATE CENTER & ARE SUBJECT TO CHANGE DUE TO ENVIRONMENTAL CONDITIONS, WARPING, LEANING SUBJECT TO CHANGE DUE TO ENVIRONMENTAL CONCESS MAY MEANDER BETWEEN	CONSTRUCTION PORPOSES.					
SUBJECT TO CHANGE DUE TO ENVIRONMENTAL CONTROL BETWEEN CHANGES FROM RECONSTRUCTION, ETC. FENCES MAY MEANDER BETWEEN MEASURED LOCATIONS.	CURVE	RADIUS	DELTA	ARC	BEARING	CHORD	
ı		C1	580.00'	04"46"22"	48.31	S 66'44'12" E	48.30'
ı	BUYER'S ACKNOWLEDGMENT		FLOOR	NOTE			

BUYER'S ACKNOWLEDGMENT_ SUBDIVISION SECTION LAKES OF BELLA TERRA SURVEY STATE COUNTY RECORDATION A-435/A-93 TEXAS FORT BEND PLAT NO. 20100180, F.B.C.P.R. TITLE CO. LENDER CO. DHI TITLE COMPANY JOB NO.

6.) 5' U.E. ON WEST SIDE OF SUBJECT PROPERTY BY F.B.C.C.F. NO. 2011015810.

ACCORDING TO THE FEDERAL EMERGENCY MANAGEMENT AGENCY (FEMA) FLOOD INSURANCE RATE MAP (FIRM) FOR FORT BEND COUNTY, TEXAS, MAP NO. 4815TC 0085L, DATED JANUARY 3, 1997. THE SUBJECT TRACT APPEARS TO LIE WITHIN UNSHADED ZONE "Y". THIS DETERMINATION WAS DONE BY GRAPHIC PLOTTING AND IS APPROXIMATE ONLY AND HAS NOT BEEN FIELD VERIFIED. THIS FLOOD STATEMENT DOES NOT IMPLY THAT THE PROPERTY OR STRUCTURES THEREON WILL BE FREE FROM FLOODING OR FLOOD CAMBE. ON RARE OCCASIONS FLOODS CAN AND WILL OCCUR AND FLOOD CAUSES. THIS FLOOD STATEMENT SHALL NOT CREATE LIABILITY ON THE PART OF WINDROSE LAND SERVICES, INC.

24143 VIA RENATA DRIVE ADDRESS

COPYRIGHT 2012 WINDROSE LAND SERVICES, INC. ALL RIGHTS RESERVED.

5.) 7' REAR U.E. BY F.B.C.C.F. NO. 2010108601.

	REVISION	
KEY MAP NO.	524 N	THE P
CHECKED BY	03-13-12	JB
DRAFTED BY	03-13-12	DH
FIELD WORK	03-12-12	DB

I do hereby certify for this transaction only, that this survey under my supervision was this day made on the ground and that this plot correctly represents the property legally described hereon (or on attached sheet). That the facts found at the time of this survey show the improvements and that there are no visible encroachments apparent on the ground, except as shown, to the best of my knowledge.

Windrose Land Services, Inc. 3200 Wilcrest Dr. Suite 325 Houston, Texas 77042 Phone (713) 458-2282 Fax (713) 461-1151

Professional Development Consultants Land Surveying, Platting, Project Management, GIS Services