

C.M.R.	Li	S 4701 25 E	28.00	1
	1.2	5 42"58"35" W	25.29'	
ID R THIS SITE.	L3	S 87'09'34" W	55.97'	1
& ARE LEANING,	L4	N 47"01"25" W	40.44	1
EN	1.5	N 87'09'34" E	73.82	1.
	L.6	N 42'58'35" E	12.49	1

BUYER'S ACKNOWLEDGMENT_	arc	party s	the state of the s		
LOT 2	BLOCK	SECTION 1	SUBDIVISION CONNERS TRAIL AMENDING PLAT NO. 1 REPLAT NO.1 AND EXTENSION	ACCORDING TO THE FEDERAL EMERGENCY MANAGEMENT	
RECORDATION FILM CODE # 650289 H.C.M.	COUNTY R. HAR	DANS CONTRACTOR	SURVEY JOHN AUSTIN A-1	ACENCY (FEMA) FLOOD INSURANCE RATE MAP (FIRM) HARRIS COUNTY, TEXAS MAP NO. 48201C 0570L D JUNE 18, 2007. THE SUBJECT TRACT APPEARS IT WITHIN UNSHADED ZONE "X". THIS DETERMINATION WAS	
LENDER CO.	1.0	TITLE	1	BY GRAPHIC PLOTTING AND IS APPROXIMATE ONLY AND HAS NOT BEEN FIELD VEHIFLED, THIS FLOOD STATEMENT DOES NOT IMPLY THAT THE PROPERTY OR STRUCTURES THEREON HILL BE FREE FROM FLOODING OR FLOOD DAMAGE, ON RARE	
PURCHASER - ADDRESS 538 OXFORD ST	REET		JOB NO. 50483	OCCASIONS FLOODS CAN AND WILL OCCUR AND FLOOD HEIGHTS MAY BE INGRESSED BY MAN-MADE OR NATURAL CAUSES. THIS FLOOD STATEMENT SHALL NOT OREATE LIABILITY ON THE PART OF WINDROSE LAND SERVICES, INC.	

MIKE KURKOWSKI

COPYRIGHT 2014 WNDROSE LAND SERVICES, INC. ALL RIGHTS RESERVED.

B) THIS SURVEY IS NOT FOR FUTURE CONSTRUCTION PURPOSES.

11/1-

141.1

REVISION					
KEY MAP NO.	493 A				
CHECKED BY	05-22-14	JB.			
DRAFTED BY	05-22-14	MED			
FIELD WORK	05-21-14	DB			

I do hereby certify for this transaction only, that this survey under my supervision was this day made on the ground and that this pick correctly represents the property legally described hereon (or on attached sheet). That the facts found at the time of this survey show the improvements and that there are no visible ancroachments apparent on the ground, except as shown, to the best of my knowledge.

Windrose Land Services, Inc. 3200 Wilcrest Drive, Sulte 325

Houston, Texas 77042 Phone (113) 458-2282 Fax (713) 481-1151

Professional Development Consultants Land Surveying, Platting, Project Management, GIS Services Firm Registration No., 10108800