Bill Moore 11951 Cedar Pass Dr. Houston, TX 77077

281-313-8535 cellamoore3844@gmail.com

4403

General Notes:

- Foundation Repair.
- Single Family (Contiguous Non-Post Tension Foundation).
- ->4.1" overall elevation variance (within 15ft)[with heaving].
- Load analysis calculation basis / load vs. soil composition (charted)[non-specific].

