

PROMULGATED BY THE TEXAS REAL ESTATE COMMISSION (TREC)

11-2-2015

AMENDMENT

TO CONTRACT CONCERNING THE PROPERTY AT

4611 Knoxville St A	-В	Houston
	(Street Address and City)	
B. Sum of financing describ	n 3 of the contract is: ice payable by Buyer at closing	\$ \$
(2) In addition to any repairs a	nd treatments otherwise require following repairs and treatments & Thermostat□	ed by the contract, Seller, at Seller's
3. Replace damaged Rear of4. Repair/Replace damage5. Repair/Replace damage	door□ d siding at rear and sides of he d shingles on roof□ n Repairs and Treatments 1	ouse□ ,
(4) The amount in Paragraph 12	A(1)(b) of the contract is change	
as follows: \$	•	by Buyer.
(6) Buyer has paid Seller an add unrestricted right to	litional Option Fee of \$	for an extension of the n or before 5:00 p.m. or
(8) The date for Buyer to give set forth in the Third Party Fi	d right to terminate the contract written notice to Seller that Buy nancing Addendum is changed	for which the Option Fee was paid. yer cannot obtain Buyer Approval as to, siness details applicable to this sale.
XECUTED the 12th day of DATE OF FINAL ACCEPTANCE.)	ecember,	2021 . (BROKER: FILL IN THE
States	CARL J	EANPIERRE 12/12/2021
uyer Abisola Adekunie	Seiler 10 2013 Authentis	Geannalure T GN' 12/12/2021
luyer	Sellerizeak	ii e.oalexarrypoisme
forms. Such approval relates to this form No representation is made as to the legal	only. TREC forms are intended for use validity or adequacy of any provision in tate Commission, P.O. Box 12188, Aus	similarly approved or promulgated contract only by trained real estate license holders. any specific transactions. It is not intended stin, TX 78711-2188, 512-936-3000 (http://

(TXR-1903) TREC NO. 39-8

ADDENDUM

PROPERTY: 4611 Knoxville St A-B, Houston, TX 7	7051-2669
1) Repairs and Treatments □	
6. Replace cracked window in upstairs bedroom	
7. Repair sheetrock damage in roof caused by pre	
8. Repair damaged flooring in Kitchen ☐	
9. Install anti-siphon devices on all exterior faucet	s 🕝 🧻
10 Replace missing Window Screens CJ	
11. Replace missing Smoke detectors	
12. Replace missing fence boards ☐	
Unit B:	
1. Repair/Replace dishwasher	
2. Repair damaged pull down stairs leading to Atti	
3. Replace missing Insulation in attic ☐4. Install anti-siphon devices on all exterior faucet	
5. Replace rotting baseboards in upstairs bathroo	
6. Replaced damaged/Missing siding on sides and	
7. Replace Foam Sleeve on suction line of A/C Uni	
8. Replace faulty Faucet in upstairs bath	
o. Replace launty Ladoot in apotano batin	
	12/12/2021
Date:	Date:
Docusigned by:	Authorison
September 1	CARL JEANPIERRE
Signature BC7F95E583234CC	Sig 12/12/12/1 6:01:58 PM CST
-	12/12/2021
Date:	Date:
	Authentisica
	Jacke Kupu
Signature	Signatures 1 6:03:27 PM CST