

8945 Solon Road, Houston, TX 77064 • (713)	641-4844 • Fax (713) 928-5221 • AtlasFoundation.net
	EMENT Date: 4/4/22
ATLAS FOUNDATION REPAIR COMPANY, called the Contractor a	and SEEL SHAH , Owner, agree that Contractor
will provide foundation repair services for the sum of \$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	and related to the an agreed schedule or completion of the work. Contractor will
the fellowing described work to the described building or	structure located at O'
City State X Zip	Priorie #5. <u>6.30 , 4,0</u>
RECOMMENDED REPAIR PLAN (SEE ADDENDUM):	OWNER INITIAL HERE:
☐ Foundation Plus™	☐ Tunneling Linear Feet
ExteriorInteriorTotal Pilings	☐ Drainage ☐ ☐ Drainage ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐
Foundation Plus [™] HD Exterior Interior Interior Total Pilings	☐ Drainage Pipe Linear Feet Linear Feet
Lifetime transferable warrancy	☐ Surface Drain Basin #
Piers: Bell Bottom	□ Down Spout Extension #
Warranty: 10 year unconditional; After 10 years \$per pier service fee Conventional:	☐ Previous Work Adjustment
☐ Conventional ☐ Sill Beam ☐ Other One-Year Limited Warranty	☐ Other
OWNER HAS ELECTED THE FOLLOWING REPAIR PLAN	N (SEE ADDENDUM): OWNER INITIAL HERE:
Foundation Plus™ Pilings Exterior Inte	eriorTotal OTHER: Amount \$
Foundation Plus™ HD Pilings 1. Contractor may need to remove plants and shrubbery which obtained by the plants are shrubbery which obtained by the plants are plants.	estruct installation areas. Any item removed will be replanted, but
Contractor does not guarantee longevity of plants and cannot be	held responsible for the landscaping of the yard.
2. Contractor is not responsible for damage to plumbing resulting only repair damage to water and sewer lines hit by Contractor wh during movement, leveling, or stabilization of the structure are the	from deterioration or pre-existing problems and leaks. Contractor will ile excavating for piling installation. In addition, leaks which may occur sole responsibility of the Owner.
2. Assess halos in the slab, walks, porches or driveways created	by Contractor will be patched with concrete. Owner is responsible for ercommended, Contractor will only replace hardwood flooring with
4. Any existing piers that must be chipped and cut away will be ch	narged to the owner at a cost of \$150 each.
IN FOUNDATION ADJUSTMENTS, CONDITIONS MIGHT APPELESTIMATE WAS SUBMITTED, SUCH AS INSUFFICIENT REINFFOUNDATION STRUCTURAL DEFICIENCY. IN SUCH CASES 1	FORCING STEEL, IN CONCRETE SLAB AND/OR OTHER ORIGINAL THE WARRANTY BECOMES INVALID.
repairs, decoration, electrical work, plumbing work, framing, carp materials unless expressly specified in this Agreement.	materials may crack or shift. Contractor is not responsible or liable for et, tile, hardwood flooring, cabinetry or the replacement or repair of any
6. Owner is responsible for clearly marking the existence of any i data, etc. that is not part of the main service at the structure. If not ma	nstalled line such as sprinkler, septic, electrical, phone, gas, propane, arked, Contractor is not responsible for any damages or repairs.
7. On all Lifetime Warranties, a New-Owner Transfer fee is required to the contractor, and new owner must notify Contractor with Failure to comply with these requirements within the 3 months with the second contractor with the second contractor.	nin three (3) months of taking ownership of the existing property. Ill result in the warranty being voided.
arbitration laws in this state and in accordance with this agreeme	g out of this Agreement shall be resolved by mandatory and binding ent and the rules the American Arbitration Association (AAA). Parties binding arbitration shall be administered by AAA. All costs shall be
Upon start of work, some factors may be present that were no with Owner.	t noticeable during the evaluation. Contractor will discuss further action
10. EXCLUSIONS TO THE LIFETIME TRANSFERABLE WARR.(1) Heave or upward movement of the foundation due to soil exp(2) All areas outside the area of influence.(3) Damage caused by catastrophic occurrences.	pansion.
in any manner. (5) Plumbing/water leaks. (6) Structural changes.	, or any work performed by Contractor that has been tampered with
from the performance of this contract. If you have a complaint of contract and the defect has not been corrected through normal was contractor by certified mail, return receipt requested, not later the court of law. The notice must refer to Chapter 27 Property Code contractor, you must provide the contractor an opportunity to institute the contractor of the contractor o	pect and cure the defect as provided by Section 27.004, Property Code.
within 2 days from the date shown above. Checks should be	
Special Provisions TSO DEP 100 110	rat 10 JEHEDUUNG.
	1. 1

ATLAS FOUNDATION REPAIR COMPANY

Owner

Owner

ATLAS™ Res Agrmnt 0820

TTAS TTAS T	DATE: 4/4/23 NAME: NEEL SHAH ADDRESS: 8102 SOLARA READ CITY: HOUSTON ZIPMOS3 PH: 832607 CL22 OTHER: NSHAH & NETSTING. COM S102
ELECT DO.	-1.0 -1.0 -1.2 -1.2 -1.2 -1.2 -1.2 -1.2 -1.2 -1.2
MINIMALLIET & STABILIZE (2 BREAVERS)	DEIVENING
TOTAL NUMBER OF PILINGS: EXTERIOR	LEGEND: EXTERIOR PILINGS

EXISTING BELL BOTTOM PIERS O 1 INCH = 10 FEET