

8906 Cardwell Lane Enhancements & Major Repairs

- 10/11 Paint interior of house
- 10/11 Lay ¾" plywood flooring in 2nd floor attic
- 10/11 Install French door & arched transom in upstairs game room

- 4/12 Install Hunter Douglas blinds for bedroom exterior door

- 7/13 Renovate both upstairs bathrooms
- 8/13 Replace pool booster pump

- 5/14 Install lighting in 2nd floor attic

- 4/15 Replace garage door opener
- 11/15 Backyard fire pit
- 12/15 Replace gas log fireplace
- 12/15 Landscape backyard

- 6/16 Upgrade pool pump
- 6/16 Replace upstairs air conditioning system

- 9/18 New smoke and carbon monoxide detectors

- 6/19 Install separate meter for irrigation water line (significant water bill savings)
- 6/19 Replace pool heater
- 10/19 Replace both 40-gallon water heaters
- 11/19 Replace built-in microwave
- 12/19 Replace pool filter

- 3/21 Install stone walkway behind pool
- 11/21 New Garage Door

- 4/22 Replace downstairs air conditioning system
- 4/22 Upgrade backyard lighting
- 4/22 Paint exterior of house