



LEGEND

These standard symbols will be found in the drawing.

- BOUNDARY LINE
- EASEMENT LINE
- BUILDING SETBACK LINE
- WOOD FENCE
- FOUND IRON ROD
- FOUND "X" ON CONCRETE
- LIGHT POLE
- WATER VALVE
- MAILBOX
- CABLE TV BOX
- FIRE HYDRANT
- CONTROL MONUMENT



GRAPHIC SCALE



FLOOD INFORMATION
 FIRM: 48201C PANEL: 0235 M
 REV. DATE: 10/16/2013
 ZONE: "X"

FLOOD INFORMATION PROVIDED HEREON IS BASED ON SCALING THE LOCATION OF THE SUBJECT TRACT ON THE FLOOD INSURANCE RATE MAPS. THE INFORMATION SHOULD BE USED TO DETERMINE FLOOD INSURANCE RATES ONLY AND IS NOT INTENDED TO IDENTIFY SPECIFIC FLOODING CONDITIONS. WE ARE NOT RESPONSIBLE FOR THE F.I.R.M.'S ACCURACY.

SURVEYOR'S NOTE(S)

THIS SURVEY MEETS THE CURRENT STANDARDS OF THE TEXAS SOCIETY OF PROFESSIONAL SURVEYORS STANDARDS AND SPECIFICATION FOR A CATEGORY 1A, CONDITION II SURVEY.

THE SETBACKS AND EASEMENTS SHOWN ON THIS DRAWING ARE THE BEST INTERPRETATION OF THE SURVEYORS BASED ON THE INFORMATION AVAILABLE TO US AT THE TIME OF THE DRAWING.

THIS SURVEY IS BASED ON A TITLE COMMITMENT REPORT ISSUED BY FIRST AMERICAN TITLE GUARANTY COMPANY OF NO. 22012352-1B ISSUED ON 10/21/22

I, LUTHER J. DALY, a Registered Professional Land Surveyor in the State of Texas, do hereby certify to TRULY TITLE, INC. and NOBLE MORTGAGE & INVESTMENTS

that the above map is true and correct according to an actual field survey, made by me or under my supervision, of the property shown hereon or described by field notes accompanying this drawing. I further certify that all easements and rights-of-way of which I have been advised are shown hereon and that, except as shown, there are no apparent visible encroachments, no apparent visible overlapping of improvements and no apparent discrepancies or conflicts in the boundary lines, as of the date of the field survey.

Borrower/Owner: TOHOSA TWOFEATHERS
 Address: 8318 ENCINITAS COVE DR., TOMBALL, TX 77375 OF No. 22012352-18

Legal Description of the Land: LOT 5, BLOCK 1, OF MIRAMAR LAKE, SECTION 2, AMENDING PLAT NO. 1, A SUBDIVISION IN HARRIS COUNTY, TEXAS, ACCORDING TO THE MAP OR PLAT THEREOF RECORDED IN FILM CODE NO. 533209, OF THE MAP AND/OR PLAT RECORDS OF HARRIS COUNTY, TEXAS.

SUBJECT TO RESTRICTIVE COVENANTS AND/OR EASEMENTS RECORDED IN: FILM CODE NOS. 527113, 533209, MAP AND/OR PLAT RECORDS, HARRIS COUNTY, TEXAS CLERK'S FILE NOS. V702964, W153029, W485842, W621412, W723822, 20120046678, 20120046679, 20120046681, 20120046682, 20120046683, 20140564151, RP-2016-54945, RP-2016-492564, RP-2016-520018, RP-2016-388704, RP-2020-41007, OFFICIAL PUBLIC RECORDS, HARRIS COUNTY, TEXAS

PROPERTY PHOTOGRAPH:



LAND TITLE SURVEY

JOB NO.:	2211037247	NO.	REVISION	DATE
DATE:	11/02/22			
DRAWN BY:	DBT			
APPROVED BY:	LJD			



FIRM REGISTRATION NO. 10190700
LUTHER J. DALY, R.P.L.S.
 Registered Professional Land Surveyor
 Registration No. 6150

Overland Consortium Inc.
Surveyors

Tel: 281-940-8869 Fax: 281-207-6476

999 E. BASSE ROAD, SUITE 180 BOX 521, SAN ANTONIO, TEXAS 78212

COPYRIGHT ALL RIGHTS RESERVED TO OVERLAND CONSORTIUM INC