

Mickey Blake 404 Reinerman St. Houston, Texas 77007

March 10, 2023

Repair hardwood floor

- Repair existing hardwood floors where the black spots are
- Replace the damage wood and tie in new floors
- Sand and finish with 1 coat stain & 1 coat universal sealer
- Finish with 2 coats of polyurethane

Screening & re-coat steps

- Screening and re-coat existing steps with light buffing to abraded
- Apply a single coat of oil base polyurethane

Total \$1070