

City of Brenham
 A. Harrington Survey
 A-55
 Washington County, Texas

Scenic Estates
 Section I, Block VI
 Amended Plat
 321A Plat File

0.182 Ac.

Address: 307 Brookside
 Brenham, Texas 77803


Brookside Drive

Subject to Restrictive Covenants of Record

Flood Hazard Statement:
 It has been determined that subject property does not lie within the 100-Year Flood Boundary as indicated by Flood Boundary and Floodway Map compiled by Federal Emergency Management Agency F.I.A., Community-Panel No. 480 648 0001B, dated August 17, 1961, City of Brenham, Washington County, Texas.

Mortgagor: Bobby B. Boykin and Wife,
 Melissa H. Boykin
 Mortgagee: Cendant Mortgage Corporation

Surveyor Certification:
 Subject To: All underground easements, the existence of which may arise by virtue of unrecorded grant or use.




E:\Projects\PLATS\SUB\REVE\1031701471.dwg 03/22/00 09:41:25 AM

I, William M. Reue, Registered Professional Land Surveyor, do hereby certify that the plat and/or description shown hereon accurately represents the results of an on the ground survey made under my direction and supervision on 3/22/00 and all corners are as shown hereon. There are no conflicts, or protrusions apparent on the ground except as shown.

This survey was performed in connection with the transaction described in the G.F. Number 20000311 of Brenham Abstract 1 Title Company.

Use of this survey for any other purposes or by other parties shall be at their own risk and the undersigned surveyor is not responsible for any loss resulting therefrom.

William M. Reue
 William M. Reue
 Registered Professional Land Surveyor No. 1070



**GILBERT ZIENTEK
 D/B/A ZIENTEK HOMES**

**Pledger and Associates
 Reue Land Surveyors**

1000 South Bay Street
 P.O. Box 1736 Brenham, Texas 77803
 Tele: (409)326-1822 Fax: (409)326-6888

Surveyor	William W. Reue	County	Washington	Field Crew	W.S.
R.P.L.S. No.	1070	Survey	N.P.	Computations	W.P.
Date	3/22/00	City	Brenham	Drafting	W.P.
Update		Section	Scenic Estates, Section 1	Work Order	14757