

THIS PROPERTY DOES NOT LIE WITHIN THE
100 YEAR FLOOD PLAIN AS PER FIRM
PANEL NO. 48201C 0610 L
MAP REVISION: 06/18/07
ZONE X
BASED ONLY ON VISUAL EXAMINATION OF MAPS.
INACCURACIES OF FEMA MAPS PREVENT EXACT
DETERMINATION WITHOUT DETAILED FIELD STUDY

A SUBSURFACE INVESTIGATION
WAS BEYOND THE SCOPE OF THIS SURVEY

D.C.L. = DIRECTIONAL CONTROL LINE RECORD BEARING: VOL. 224, PG. 77, H.C.M.R. I HEREBY CERTIFY THAT THIS SURVEY WAS MADE ON THE GROUND, THAT THIS PLAT CORRECTLY REPRESENTS THE FACTS FOUND AT THE TIME OF SURVEY AND THAT THERE ARE NO ENCROACHMENTS APPARENT ON THE GROUND, EXCEPT AS SHOWN HEREON. THIS SURVEY IS CERTIFIED FOR THIS TRANSACTION ONLY AND ABSTRACTING PROVIDED IN THE ABOVE REFERENCED TITLE COMMITMENT WAS RELIED UPON IN PREPARATION OF THIS SURVEY.

GEORGE GALE PROFESSIONAL LAND SURVEYOR NO. 4678 JOB NO. 12-03744 MAY 4, 2012



CHECKED BY: RC DRAWN BY: GV



Fidelity National Title

LUIS RODRIGUEZ 281-240-2808





1-800-LANDSURVEY www.precisionsurveyors.com

281--496--1586 FAX 281--496--1867 950 THREADNEEDLE STREET SUITE 150 HOUSTON, TEXAS 77079 210-829-4941 FAX 210-829-1555-1777 NE LOOP 410 SUITE 600 SAN ANTONIO, TEXAS 78217

/0/