




stewart
title
CATHY ORSAK
281.341.0404



PRECISION
surveyors

1-800-LANDSURVEY
www.precisionsurveyors.com
281-496-1566
850 THEKENDRICK STREET SUITE 150 HOUSTON, TEXAS 77079
FAX 281-496-1867
210-829-4941
1777 NE LOOP 410 SUITE 800 SAN ANTONIO, TEXAS 78217
FORM NO. 10063700



CF NO. 1515747486 STEWART TITLE
ADDRESS: 10318 READING ROAD
RICHMOND, TEXAS 77469
BORROWER: CASEY MCALPIN AND
TIFFANY DAWN JOBE

**LOT 4, BLOCK 7
BRIDLEWOOD ESTATES, SECTION 1**

ACCORDING TO THE MAP OR PLAT THEREOF RECORDED
IN SLIDE NOS. 1560/A & B, 1561/A & B AND
1562/A & B, OF THE PLAT RECORDS
OF FORT BEND COUNTY, TEXAS



NOTE: A BUILDING LINE A MINIMUM DISTANCE OF TEN FEET SHALL BE MAINTAINED BETWEEN RESIDENTIAL DWELLINGS, AS REFLECTED BY RECORDED PLAT OF SAID SUBDIVISION.

THIS PROPERTY DOES NOT LIE WITHIN THE
100 YEAR FLOOD PLAIN AS PER FINAL
FLOOD MAP REVISION: 04/02/2014
BASED ONLY ON VISUAL EXAMINATION OF MAPS.
IRREGULARITIES OR FEMA MAPS PREVENT EXACT
DETERMINATION WITHOUT DETAILED FIELD STUDY.
A SURFACE INVESTIGATION
WAS BEYOND THE SCOPE OF THIS SURVEY

D.C.L. = DIRECTIONAL CONTROL LINE
RECORD BOOKING SLIDE NOS. 1560/A&B, 1561/A&B & 1562/A&B, PROJECT: DOWNEY BR-10

I HEREBY CERTIFY THAT THIS SURVEY WAS MADE
IN ACCORDANCE WITH THE RULES AND REGULATIONS
OF THE BOARD OF SURVEYORS AND LAND RECORDS
OF THE STATE OF TEXAS, AND THAT THE FACTS
REPRESENTED IN THE MAPS AND PLATS OF THIS
SURVEY ARE TRUE AND CORRECT TO THE BEST OF
MY KNOWLEDGE AND BELIEF. EXCEPT AS SHOWN
HEREON, THIS SURVEY IS NOT TO BE CONSIDERED
AS A GUARANTEE OF THE ACCURACY OF THE
DIMENSIONS AND AREAS THEREON. THE SURVEY
WAS MADE IN ACCORDANCE WITH THE RULES AND
REGULATIONS OF THE BOARD OF SURVEYORS AND
LAND RECORDS OF THE STATE OF TEXAS.
GEORGE OGLE
PROFESSIONAL LAND SURVEYOR
NO. 409 NO. 15-07149
APRIL 30, 2015

