Work Completed on

281 Denson Reed Road

• **Broken Arrow Pest Control** (936.327.7484) August 24, 2023: Clean-Out Treatment (Residence - Interior & Exterior)

MATERIAL / EPA #	QTY UNITS	DILUTION	IPM	LOCATION	TARGET	AREA
Talstar P 499-444	0.5 gal	.06%			Roaches, Spiders, Carpenter Ants	
Talstar P 499-444	15 gal	.05%			Roaches, Spiders, Carpenter Ants	

- A-1 Carpet & Fine Floors (281.592.5393) August 25, 2023: Tan carpet installed in 3 rooms and closets
- Rayburn's Roofing 832.339.5922 (05/01/2023)

Stroot 281 Dengen Reed RJ. Job Location:
City, State and Zip Code: 77.27 %
1. Remove existing layer(s) of composition roofing. Haul away. (1) Comp (1) Fetter in the support of the suppor
1. Remove existing layer(s) of composition rooming. The same state of the same state
2 Penjace all dallidged decking.
3 Apply # 15 felt as underlayment. Khimo Koot
4. Install metal edging along roof perimeter. 2"×2" Bluck
5. Apply starter shingle course and extend drip edge. Starter Shingle
6 Install double-coverage valleys, Ira & water Shield
7. Reroof with Certain Iced Lundmark composition shingles. (Weather Vol.)
8. Install self-sealing matching ridge. XT-25 (133 sq) & Ridge vent
9. Replace all vents and stacks. 3nd & motal Base
10. Waterproof all flashing. NP-1 & weather shield
11. Rustproof and paint all vents, stacks and flashings. Color March
12. Clean-up debris and haul away. Magnetic sweep.
13. Professional job supervision. Secure walls.
14. 10 Year guarantee on labor / LT year guarantee on material.

• R & D Water Wells LLC (936.258.2828) April 28, 2023:

Item
Standard Service Call standard service call
Pull/Replace w/open access
1/2 hp 10-20 gpm submersible pump bottom suction
1" sch 80 drop pipe
#12/2 w/G Pump Cable
4"x1" Simmons Well Seal
1" Тор Тее
3/4" RV 75 Relief Valve
FL12 - 35gal
Pressure Switch
Pressure Gauge
1/4" fittings

•

• Trejo's Electrical Service (832.414.1391)

281 Denson Reed Rd Cleveland Tx 77328

DESCRIPTION

1-replace 100amps main panel, replace wiring from outside 100 amp breaker to the inside panel, reroute wires, and install new breakers on all the circuits

281 Denson Reed Rd Cleveland Tx 77328

DESCRIPTION

1-run a new 120v circuit for pool equipment, replace GFCI outlet pull new wire to it, replaced the pigtail from the pump motor to reach to gfci plug 2-troubleshooting on circuit outlets and fix the problems replace outlets, change boxes wire up right on outlets tight down outlets. Some of it was loose at GFCI outlet on the bathroom replace outlets on couple different spots.