



**SURVEYOR'S NOTE(S):**

THIS SURVEY MEETS THE CURRENT STANDARDS OF THE TEXAS SOCIETY OF PROFESSIONAL SURVEYORS STANDARDS AND SPECIFICATION FOR A CATEGORY 1A, CONDITION II SURVEY.

THE SETBACKS SHOWN ON THIS DRAWING ARE THE BEST INTERPRETATION OF THE SURVEYORS BASED ON THE INFORMATION AVAILABLE TO US AT THE TIME OF THE DRAWING.

THIS SURVEY IS BASED ON A TITLE COMMITMENT REPORT ISSUED BY OLD REPUBLIC NATIONAL TITLE INSURANCE COMPANY GF NO. SW0003754 ISSUED ON 10/26/22.

NO RECORDED BUILDING LINES FOUND. FUTURE DEVELOPMENTS SHOULD REFER TO JURISDICTIONAL AGENCIES FOR REQUIREMENTS.

THE PLATTED/DEEDED BEARINGS AND DISTANCES DO NOT REPRESENT A MATHEMATICALLY CLOSED FIGURE; THE BOUNDARY, AS DEPICTED HEREON, IS BASED UPON THE MONUMENTATION AS FOUND ON-THE-GROUND, AND THE APPARENT INTENT OF THE SUBD. PLAT.

FLOOD INFORMATION  
 FIRM: 48339C PANEL: 0240 G  
 REV. DATE: 08/18/2014  
 ZONE: "X"

FLOOD INFORMATION PROVIDED HEREON IS BASED ON SCALING THE LOCATION OF THE SUBJECT TRACT ON THE FLOOD INSURANCE RATE MAPS, THE INFORMATION SHOULD BE USED TO DETERMINE FLOOD INSURANCE RATES ONLY AND IS NOT INTENDED TO IDENTIFY SPECIFIC FLOODING CONDITIONS. WE ARE NOT RESPONSIBLE FOR THE F.I.R.M.'S ACCURACY.

**W. MARLIN ST.**

(MIN. 50' VARIABLE WIDTH R.O.W.-PER PLAT)  
 (AS PER PLAT MARTIN ST.)

**LEGEND**

These standard symbols will be found in the drawing.

- BOUNDARY LINE
- EASEMENT LINE
- OVERHEAD ELECTRIC
- PLATTED LOT LINE
- SET 1/2" IRON ROD
- FOUND IRON ROD
- FOUND METAL PIPE
- WATER METER
- GAS METER
- ELECTRIC METER
- SP/W- LIGHT POLE
- WATER VALVE
- FIRE HYDRANT
- CONTROL MONUMENT

FND. 5/8"  
 I.R. WITH  
 CAP STAMPED  
 "TPS 100834 00"

HOLLAND ST.  
 LOTS 5 & 6  
 BLOCK 4

**GRAPHIC SCALE**



I, RODRIC R REESE, a Registered Professional Land Surveyor in the State of Texas, do hereby certify to SECURED TITLE OF TEXAS, LLC and TERRA HOME SOLUTIONS, LLC

that the above map is true and correct according to an actual field survey, made by me or under my supervision, of the property shown hereon or described by field notes accompanying this drawing. I further certify that all easements and rights-of-way of which I have been advised are shown hereon and that, except as shown, there are no apparent visible encroachments, no apparent visible overlapping of improvements and no apparent discrepancies or conflicts in the boundary lines, as of the date of the field survey.

Borrower/Owner: TERRA HOME SOLUTIONS, LLC  
 Address: 0 (102 TURNER), WILLIS, TEXAS 77378 GF No. SW0003754

**Legal Description of the Land:** Lot 1 & 2, Block 1, of Turner Heights, a subdivision in Montgomery County, Texas, as shown by the plat of said subdivision recorded in Volume 7, Pages 101-103, of the Map Records of Montgomery County, Texas.

**LAND TITLE SURVEY**

JOB NO.:	2211037295	NO.	1	REVISION	UPDATED SURVEY	DATE	11/07/22
DATE:	05/12/22						
DRAWN BY:	CP						
APPROVED BY:	RRR			(REFER JOB NO. 2205034190)			



*Rodric R. Reese*

FIRM REGISTRATION NO. 10190700  
 THIS SURVEY IS CONTRACTED TO RODRIC R REESE, RPLS  
 PHONE NUMBER 713-647-1315

RODRIC R REESE, R.P.L.S.  
 Registered Professional Land Surveyor  
 Registration No. 5883

COPYRIGHT ALL RIGHTS RESERVED TO OVERLAND CONSORTIUM INC.

SUBJECT TO RESTRICTIVE COVENANTS AND/OR EASEMENTS RECORDED IN: VOLUME 7, PAGES 101-103, MAP RECORDS, MONTGOMERY COUNTY, TEXAS

PROPERTY PHOTOGRAPH:



**Overland Consortium Inc. Surveyors**

Tel: 281-940-8869 Fax: 281-207-6476

999 E. BASSE ROAD, SUITE 180 BOX 521, SAN ANTONIO, TEXAS 78212