

cm = control monument  
 pp = power failed pole  
 ac = ac conditioner unit  
 wh = well house  
 cd = concrete drive  
 gd = gravel drive  
 BL = building line  
 UE = utility equipment  
 OEH = overhead electric/utility line  
 g = guy wire anchor

A portion of the tract shown herein does lie within the Special Flood Hazard Area according to the DHID/FIA Flood Hazard Boundary Map for Washington County, Texas, Community Panel No. 481788 0008 A, effective date May 24, 1977.  
 The special flood hazard boundary is approximately shown herein per said map.

The subject tract shown herein may be subject to the requirement in favor of Bluebonnet Electric Cooperative, Inc. recorded in Volume 873, Page 828 of the Official Records of Washington County, Texas (15' each side of the centerline of the electric distribution line or system).


The tract shown herein may be subject to the following easements:

- 1) Easement in favor of Harold R. Andersen recorded in 435/194 D.R.W.C.
- 2) Easement in favor of Larache Anderson recorded in 239/279 D.R.W.C.
- 3) Easement in favor of Bluebonnet Electric Cooperative, Inc., recorded in 201/820 D.R.W.C.
- 4) Easement in favor of Bluebonnet Electric Cooperative, Inc., recorded in 1273/815 D.R.W.C.

All found 1/2" iron rods are considered control monuments for this survey.

This plat prepared for mortgage purposes.

Phillip Coe Survey  
 Abstract No. 31  
 Washington County, Texas



Pecan Glen Subdivision  
 Plat Cabinet File No. 444B-446B  
 Plat Records of Washington County, Texas

(formerly Cedar Glen Subdivision  
 Plat Cabinet File No. 220B-223A  
 Plat Records of Washington County, Texas)

MORTGAGEE: BANK OF BRENHAM, N.A.  
 MORTGAGOR: DANIEL L. BULLER  
 TAMARA L. BULLER

An improvement survey of Lot 46 of Pecan Glen Subdivision (a 446A-B of the Plat Records of Washington County, Texas) (formerly referred to as Cedar Glen Subdivision, as recorded in Plat Cabinet File No. 220B-223A of the Plat Records of Washington County, Texas), situated in Washington County, Texas, being out of the Phillip Coe Survey, Abstract No. 31, and being the same lot or tract described in a deed from Mike McLennan, et ux to Daniel L. Buller and Tamara L. Buller, dated February 6, 2008, and recorded in Volume 1270, Page 026 of the Official Records of Washington County, Texas.

To: Daniel L. Buller and Tamara L. Buller, Bank of Brenham, N.A., and Washington County Abstract Company, G.F. No. S080829.

I, Michael J. Blakey, Registered Professional Land Surveyor, do hereby certify that this survey was made on September 4, 2008, on the ground of the property, legally described herein, and is correct; and that there are no discrepancies, conflicts, shortages of area, boundary line conflicts, encroachments at ground level, overlapping of improvements, easements, or apparent rights-of-way, except as shown herein, and said property has access to and from a dedicated roadway, except as shown herein.

Daniel L. Buller, et ux

Blakey Land Surveying

RPLS 4062 RPLS 6936

4850 Wilkinson Lane  
Burton, Texas 77836

(876) 228-3800

Michael J. Blakey  
 Registered Professional Land Surveyor No. 5935

W.O. #281381