

NOTE: THIS LOT FORMERLY KNOWN AS 10034 LAKEWOOD CIRCLE, HOLLY LAKE RANCH, TX 75735, HOWEVER, THE DESIGNATED ADDRESS WAS CHANGED TO 203 LAKEWOOD CIRCLE WHEN WOOD COUNTY IMPLEMENTED ITS "911" SYSTEM. NOTE: BEARINGS AS SHOWN HEREON ARE "TRUE BEARINGS" AS DETERMINED BY SOLAR OBSERVATION.

SUBDIVISION PLAT OF RECORD AT VOL. 9, PG. 34, PLAT RECORDS, WOOD COUNTY, TEXAS.

REFERENCE: W4365-44.DAT

CAD FILE: W4368-44.ZAK LAYER: LOT34_ FINAL DISK3

We, Turner Surveying Co., L.L.C., do hereby certify that this plat was prepared from an actual survey made on the ground under our supervision during the month of June, 2005.

There are no descrepancies, apparent conflicts, shortages in area, visible boundary line conflicts, encroachments, or overtapping of improvements, no visible easements or rights-of-way, except as shown hereon.

the improvements on this trect do not lie and in the Holl of of a "SPECIAL FLOOD HAZARD AREADS SOUTH OF THE HAZARD BOUNDARY MAP, COMMUNITY FUNEL MAY 481055 0009 A, effective date May 31/1974

PLAT SHOWING SURVEY OF LOT 34, SECTION X HOLLY LAKE RANCH

> 203 LAKEWOOD CIRCLE HOLLY LAKE RANCH, TX 75765

Bruce W. Rupar R.P.L.S. No. 5781

TURNER SURVEYING CO., L.L.C. QUITMAN, TEXAS

81 DATE: 06-24-05 SCALE: 1" = 50" W6022 REVISED OF TABLE ADDRESS EXPLANATION ADDED.