
MAG NAIL FOUND (C.M.)



THIS PROPERTY DOES NOT LIE WITHIN THE 100 YEAR FLOOD PLAIN AS PER FIRM PANEL NO. 4801C 0420 N MAP REVISION: 06/09/2014 ZONE X SOLD VISUAL EXAMINATION OF MAPS. INACCURACIES OF FEMA MAPS PREVENT EXACT DETERMINATION WITHOUT DETAILED FIELD STUDY

A SUBSURFACE INVESTIGATION WAS BEYOND THE SCOPE OF THIS SURVEY

D.C.L. = DIRECTIONAL CONTROL LINE
RECORD BEARING: FILM CODE NO. 543133, M.R.H.C.

I HEREBY CERTIFY THAT THIS SURVEY WAS MADE ON THE GROUND, THAT THIS PLAT CORRECTLY REPRESENTS THE FACTS FOUND AT THE TIME OF SURVEY AND THAT THERE ARE NO ENCROACHMENTS APPARENT ON THE GROUND, EXCEPT AS SHOWN HEREON, THIS SURVEY IS CERTIFIED FOR THIS TRANSACTION ONLY AND ABSTRACTING PROVIDED IN THE ABOVE REFERENCED TITLE COMMITMENT WAS RELIED UPON IN PREPARATION OF THIS SURVEY.

JAMES P. WALKOYAK PROFESSIONAL LAND SURVEYOR NO. 5971 JOB NO. 14–05333 JUNE 16, 2014







DRAWN BY: TM

CARLA GINN 281-893-6110



PRECISION Surveyors

1-800-LANDSURVEY www.precisionsurveyors.com

281-496-1586 FAX 281-496-1867 281-496-1380 FAX 201-490-1307 950 THREADNEEDLE STREET SUITE 150 HOUSTON, TEXAS 77079 1777 NE FIRM NO. 10063700

210-829-4941 1777 NE LOOP 410 SUITE 600 SAN ANTONIO, TEXAS 78217

FAX 210-829-1555