RAM MAINTENANCE SERVICES

9050 COOK RD. #200 HOUSTON, TX 77099-1457 rum879@sbcglobal.net 281-217-5200



ANDY AU 3519 SANTA ROSA SUGAR LAND TX 77479 MAR 28 2624 atauph a aut.com Cell 713-382-5386



PRICE ITEM DESCRIPTION

CODE: 1010

PAGE LOF I

- \$ 95.00 I. ROTTEN SOFT WOOD AT THE BASE OF THE KITCHEN CABINET.
- 5 175.00 2. REPLACE 3 MISSING & TORN SCREENS
- \$ 75.00 3. REPAIR THE GATE TO OPEN & SHUT PROPERLY.
- \$ 165.00 4. REPLACE THE BREAKER ON THE A/C UNIT, THE ONE IT HAS IS WRONG SIZE.
- \$ 85.00 S. REPLACE THE INSULATION ON THE A/C PIPES.
- \$ 145.00 6. INSTALL A DRIP LEG ON THE GAS HOT WATER HEATER.
- \$ 475.00 7. SERVICE THE DOWNSTAIRS A/C UNIT, IT MAY NEED FREEON.
- 5 95.00 8. REPAIR THE WIRING AT THE DISCONNECT ON A/C UNIT.
- 5 75.00 9. INSTALL ANTI TIP FOR THE GAS RANGE.
- \$ 300.00 10. 2 PARTS OF THE FENCE OF FENCE IS LEANING ON THE RIGHT SIDE.
- § 45.00 11. REPLACE A FEW PICKETS ON THE REAR CORNER OF THE FENCE.
 \$ 1,730.00 --- TOTAL
 - FREE 12. Made high loop on dishwasher

THANK YOU!

The above prices, specifications & conditions are satisfactory and hereby accepted. You are authorized to do the work a Payment will be made upon completion, however if you choose to pay after 30 days of the invoiced date, the charge is than what is listed for this job. ALL WORK HAS A TYR. LABOR WARRANTY EXCEPT NEW WINDOWS HAVE A LIFETIM