# TEXAS REALTORS

## SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2022

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

CONCERNING THE PROPERTY AT 5010 SHALE GROVE COURT, RICHMOND, TX 77407

THIS NOTICE IS A DISCLOSURE OF SELLER'S KNOWLEDGE OF THE CONDITION OF THE PROPERTY AS OF THE DATE SIGNED BY SELLER AND IS NOT A SUBSTITUTE FOR ANY INSPECTIONS OR WARRANTIES THE BUYER MAY WISH TO OBTAIN. IT IS NOT A WARRANTY OF ANY KIND BY SELLER, SELLER'S AGENTS, OR ANY OTHER AGENT.

Seller  $\Box$  is  $\blacksquare$  is not occupying the Property. If unoccupied (by Seller), how long since Seller has occupied the Property?  $\blacksquare 2 \text{ MONTHS}$  (approximate date) or  $\Box$  never occupied the Property

### Section 1. The Property has the items marked below: (Mark Yes (Y), No (N), or Unknown (U).)

This notice does not establish the items to be conveyed. The contract will determine which items will & will not convey.

		U		Item			Y		U		Item	Υ	Ν	U
				Natu	ral Gas Li	nes					Pump: Sump			
				Fuel	Gas Pipin	g:			Z		Rain Gutters			
				-Bla	k Iron Pip	е					Range/Stove			
				-Cop	per						Roof/Attic Vents	Ν		
				-Corrugated Stainless							Sauna			
				Hot	Tub						Smoke Detector			
				Intercom System					V		Smoke Detector – Hearing Impaired			
				Micr	owave						Spa			
				Outdoor Grill				V		Trash Compactor				
		V		Patie	/Decking						TV Antenna			
				Plumbing System						Washer/Dryer Hookup				
				Pool							Window Screens			
				Pool	Equipmer	nt					Public Sewer System			
				Pool Maint. Accessories			2							
				Poo	Heater									
				11	1						-			_
					Image: Constraint of the second state of the second sta	Image: Constraint of the second state of the second sta	Image: Natural Gas Lines         Image: Natural Gas Lines         Image: Fuel Gas Piping:         Image: Plack Iron Pipe         Image: Plack I	Image: Constraint of the second state of the second sta	Image: Natural Gas Lines   Image: Natural Gas Lines   Image: Natural Gas Piping:   Image: Natural Gas Piping: Natural Gas Piping:   Image: Natural Gas Piping: N	Image: Natural Gas Lines   Image: Natural Gas Lines   Image: Fuel Gas Piping:   Image: Pilon Gas Piping: Pilon Gas P	Image: Natural Gas Lines   Image: Natural Gas Lines   Fuel Gas Piping:   Image: Natural Gas Lines   Fuel Gas Piping:   Image: Natural Gas Lines   Image: Natural Gas Lines   Image: Natural Gas Piping:   Image: Natural Gas Piping: Natural Gas Piping:   Image: Natural Gas Piping: Natural Gas P	Image: State of the state	Image: Steel Tubing   Image: Steel Tubing	Image: Second state in the second s

item	T	U	Additional information
Central A/C			electric 🛛 gas number of units: 2
Evaporative Coolers			number of units:
Wall/Window AC Units			number of units:
Attic Fan(s)			if yes, describe:
Central Heat			🗖 electric 🚺 gas number of units: 2
Other Heat			if yes describe:
Oven			number of ovens: electric gas other:
Fireplace & Chimney			🗆 wood 🖉 gas logs 🗆 mock 🗆 other:
Carport			□ attached □ not attached
Garage			☑ attached □ not attached
Garage Door Openers			number of units: 2 number of remotes: _2
Satellite Dish & Controls			□ owned □ leased from
Security System			□ owned □ leased from
(TXR-1406) 07-10-23	Initialed by:	Buyer	r:and Seller:
HomeSmart International - Houston Galleria	1001 West I	Loop So	dotloop verified Princewill Zeblon

dotloop signature verification: dtlp.us/haf4-4Q5f-69ul

Но

Concerning the Property at 5010 SHALE GROVE COURT, RICHMOND, TX 77407

Solar Panels			□ owned □ leased from
Water Heater	Þ		electric 🗹 gas 🛛 other: number of units:
Water Softener			□ owned □ leased from
Other Leased Item(s)			if yes, describe:
Underground Lawn Sprinkler			automatic manual areas covered:
Septic / On-Site Sewer Facility			if yes, attach Information About On-Site Sewer Facility (TXR-1407)

Water supply provided by: City well MUD co-op unknown other:

Was the Property built before 1978? Uses In our unknown

(If yes, complete, sign, and attach TXR-1906 concerning lead-based paint hazards).

(approximate)

Roof Type: Composite Age: 7 years Is there an overlay roof covering on the Property (shingles or roof covering placed over existing shingles or roof covering)? □ yes □ no ☑ unknown

Are you (Seller) aware of any of the items listed in this Section 1 that are not in working condition, that have defects, or are need of repair? use Ino If yes, describe (attach additional sheets if necessary):

### Section 2. Are you (Seller) aware of any defects or malfunctions in any of the following? (Mark Yes (Y) if you are aware and No (N) if you are not aware.)

Item	Υ	Ν	Item	Υ	Ν	Item	Υ	Ν
Basement			Floors			Sidewalks		
Ceilings			Foundation / Slab(s)			Walls / Fences		
Doors			Interior Walls			Windows		
Driveways			Lighting Fixtures			Other Structural Components		
Electrical Systems			Plumbing Systems					
Exterior Walls			Roof					

If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):

### Section 3. Are you (Seller) aware of any of the following conditions? (Mark Yes (Y) if you are aware and No (N) if you are not aware.)

Condition	Υ	Ν		Condition	Υ	Ν
Aluminum Wiring				Radon Gas		Х
Asbestos Components				Settling		C) (X)
Diseased Trees: Oak wilt				Soil Movement		Ŕ
Endangered Species/Habitat on Property		Ô		Subsurface Structure or Pits		
Fault Lines		Ŵ		Underground Storage Tanks		Ŕ
Hazardous or Toxic Waste		$\Box$		Unplatted Easements		₽
Improper Drainage		Ŵ		Unrecorded Easements		
Intermittent or Weather Springs		$\square$		Urea-formaldehyde Insulation		
Landfill		Ŷ		Water Damage Not Due to a Flood Event		ſ
Lead-Based Paint or Lead-Based Pt. Hazards				Wetlands on Property		D
Encroachments onto the Property		Ç		Wood Rot		
Improvements encroaching on others' property				Active infestation of termites or other wood	]	хП
				destroying insects (WDI)		V
Located in Historic District		Ô		Previous treatment for termites or WDI		Ô
Historic Property Designation		Ď		Previous termite or WDI damage repaired		ř
Previous Foundation Repairs		Х		Previous Fi <u>res</u>		X
(TXR-1406) 07-10-23 Initialed by: Buyer:		X		and Seller:	e 2 c	X of 7
meSmart International - Houston Galleria 1001 West Loop South, Ste	105 H	Ious	ton	, TX 77027 dotloop verified Princewill Ze	blon	

Concerning the Property at 5010 SHALE GROVE COURT, RICHMOND, TX 77407

Previous Roof Repairs	Х
Previous Other Structural Repairs	X
Previous Use of Premises for Manufacture of Methamphetamine	X

Termite or WDI damage needing repair								
Single Blockable Main Drain	in	Pool/Hot						
Tub/Spa*				L¥				

If the answer to any of the items in Section 3 is yes, explain (attach additional sheets if necessary):

\_\_\_\_\_

\*A single blockable main drain may cause a suction entrapment hazard for an individual.

Section 4. Are you (Seller) aware of any item, equipment, or system in or on the Property that is in need of repair, which has not been previously disclosed in this notice? Uses I use in the system of the system

Section 5. Are you (Seller) aware of any of the following conditions?\* (Mark Yes (Y) if you are aware and check wholly or partly as applicable. Mark No (N) if you are not aware.)

- Present flood insurance coverage.
- Previous flooding due to a failure or breach of a reservoir or a controlled or emergency release of water from a reservoir.
- Previous flooding due to a natural flood event.
- Previous water penetration into a structure on the Property due to a natural flood.
- Located U wholly U partly in a 100-year floodplain (Special Flood Hazard Area-Zone A, V, A99, AE, AO, AH, VE, or AR).
- Located wholly partly in a 500-year floodplain (Moderate Flood Hazard Area-Zone X (shaded)).
- □ ☑ Located □ wholly □ partly in a floodway.
- □ ☑ Located □ wholly □ partly in a flood pool.
- □ 🔽 Located □ wholly □ partly in a reservoir.

If the answer to any of the above is yes, explain (attach additional sheets as necessary):

#### \*If Buyer is concerned about these matters, Buyer may consult Information About Flood Hazards (TXR 1414).

For purposes of this notice:

"100-year floodplain" means any area of land that: (A) is identified on the flood insurance rate map as a special flood hazard area, which is designated as Zone A, V, A99, AE, AO, AH, VE, or AR on the map; (B) has a one percent annual chance of flooding, which is considered to be a high risk of flooding; and (C) may include a regulatory floodway, flood pool, or reservoir.

"500-year floodplain" means any area of land that: (A) is identified on the flood insurance rate map as a moderate flood hazard area, which is designated on the map as Zone X (shaded); and (B) has a two-tenths of one percent annual chance of flooding, which is considered to be a moderate risk of flooding.

"Flood pool" means the area adjacent to a reservoir that lies above the normal maximum operating level of the reservoir and that is subject to controlled inundation under the management of the United States Army Corps of Engineers.

(TXR-1406) 07-10-23	Initialed by: Buyer:	and Seller:		Page 3 of 7
HomeSmart International - Houston Galleria	1001 West Loop South, Ste 105	Houston, TX 77027	02/28/24 6:25 PM CST dotloop verified	Princewill Zeblon