

SURVEY OF LOT 30, BLOCK 60 WESTWOOD SHORES SECTION 2	
DCATED IN THEG.W. WILSONSURVE	EY ABSTRACT NO A-630
CASED ON THE T	
OLUME/CABINET <u>A</u>	
HE MAP RECORDS TRINITY	
EF :ARISTIDES GARCIA_G.F19666	•
TO ARISTIDES GARCIA HOMES, LLC AND STEWART T HEREBY CERTIFY THAT THIS SURVEY WAS MADE O BEST OF MY KNOWLEDGE, THIS PLAT CORRECTLY R THE TIME OF THE SURVEY AND THAT THERE ARE NO DVERLAPS DISCREPANCIES, OR CONFLICTS EXCEPT	ITTLE GUARANTY COMPANY. ON THE GROUND, AND TO THE REPRESENTS THE FACTS AT O VISIBLE ENCROACHMENTS,
BI 1	
10 Ba	STER
	24 - 10 M
MICHAEL WARREN R.P.L.S. # 4935	HAEL CRAIG WARREN
18	* 4935 ×
1 Per	AND SUDIE
	SOH
1) THE BEARINGS SHOWN HEREON ARE BASED ON N	JAD 83 TEXAS CENTRAL ZONE
2) THE SURVEYOR HAS NOT ABSTRACTED THE SUBJ	
3) THIS SURVEY RELIES ON THE TITLE COMMITMEN GUARANTY COMPANY (G.F. No. 19666) DATED OCT THINGS OF RECORDS.	T FROM STEWART TITLE
4) SURVEYOR HAS MADE NO INVESTIGATION OR INI EASEMENTS OF RECORD, ENCUMBRANCES, RESTR OWNERSHIP, TITLE EVIDENCE, OR ANY OTHER FAG AND CURRENT TITLE SEARCH MAY DISCLOSE.	RICTIVE COVENANTS,
5) PROPERTY SUBJECT TO THE RESTRICTIONS AS RE VOLUME 0911, PAGE 0758; & VOLUME 1016, PAGE 087 IRINITY COUNTY, TEXAS.	
6) ALL BUILDING TIES ARE PERPENDICULAR TO THE	E BOUNDARY LINE.
7) ALL ADJOINER DEED INFORMATION MAY NOT RE OWNER OR OWNERS.	PRESENT CURRENT
8) THE FENCE LINES SHOWN ARE SHOWN AT THE PC WERE MADE AND MAY MEANDER ALONG THE LI	
9) OTHER MINOR IMPROVEMENTS (SUCH AS LANDS) PRESENT, BUT NOT SHOWN	CAPING, LIGHTS, ETC) MAY BE
	[]
	LINE & SYMBOL LEGEND
	1) IRF= IRON ROD FOUND 2) IRS= IRON ROD SET, CAPPED
	"SURVTECH" 3) BL= BUILDING LINE 4) UE= UTILITY EASEMENT
67	5) DE= DRAINAGE EASEMENT 6) AE= ACCESS EASEMENT
	7) CM= CONTROL MONUMENT

"A Land Surveying Company"

P.O. BOX 1080 \ CONROE, TEXAS 77305-1080 936-539-5444 \ FAX 936-539-5442 email: SURVTECH@SURVCORP.COM TBPELS No. 10005100 LISURVEY IS BEING PROVIDED TO THE RECIPIENTS NAMED ABOVE AND NO LICENSE HAS BEEN CREATED, TO COPY THE SURVEY EXCEPT IN CONJUNCTION WITH THE ORIGINAL TRANSACTION, UNLESS OTHERWISE SHOWN, NO FLOODPLAIN CHECK WAS PERFORMED