

**4014 Tranquil Forest Updates and Maintenance:**

- The roof was replaced (2018)
- Underground power line was replaced with copper lines (2016-\$1554).
- Evaporator coil was replaced (2020-\$2300).
- Fence was replaced (2021-\$2500).
- Plywood laid at addict for storage (2015-\$500)
- Sprinkler system was installed (2010-\$1400)