Page 1 of 5 Date: March 10, 2020 Case No.: 20-06-0655A LOMR-F



Federal Emergency Management Agency

Washington, D.C. 20472

LETTER OF MAP REVISION BASED ON FILL DETERMINATION DOCUMENT (REMOVAL)

COMM	MUNITY AND MAP PANEL INFORMATION	LEGAL PROPERTY DESCRIPTION			
COMMUNITY	MONTGOMERY COUNTY, TEXAS (Unincorporated Areas) COMMUNITY NO.: 480483	A parcel of land, as described in the Quitclaim Deed recorded as Document No. 2017104568, in the Office of the County Clerk, Montgomery County, Texas The portion of property is more particularly described by the following metes and bounds:			
AFFECTED MAP PANEL	NUMBER: 48339C0575G				
	DATE: 8/18/2014				
LOODING SOURCE: DRY CREEK		APPROXIMATE LATITUDE & LONGITUDE OF PROPERTY:30.237338, -95.310870 SOURCE OF LAT & LONG: LOMA LOGIC DATUM	: NAD 83		

DETERMINATION

LOT	BLOCK/ SECTION	SUBDIVISION	STREET	OUTCOME WHAT IS REMOVED FROM THE SFHA	FLOOD ZONE	1% ANNUAL CHANCE FLOOD ELEVATION (NAVD 88)	LOWEST ADJACENT GRADE ELEVATION (NAVD 88)	LOWEST LOT ELEVATION (NAVD 88)
			Granger Pines Way	Portion of Property (Tract 2)	X (shaded)		-	143.2 feet

Special Flood Hazard Area (SFHA) - The SFHA is an area that would be inundated by the flood having a 1-percent chance of being equaled or exceeded in any given year (base flood).

ADDITIONAL CONSIDERATIONS (Please refer to the appropriate section on Attachment 1 for the additional considerations listed below.)

LEGAL PROPERTY DESCRIPTION
DETERMINATION TABLE (CONTINUED)
PORTIONS REMAIN IN THE FLOODWAY

FILL RECOMMENDATION
STATE LOCAL CONSIDERATIONS

This document provides the Federal Emergency Management Agency's determination regarding a request for a Letter of Map Revision based on Fill for the property described above. Using the information submitted and the effective National Flood Insurance Program (NFIP) map, we have determined that the described portion(s) of the property(ies) is/are not located in the SFHA, an area inundated by the flood having a 1-percent chance of being equaled or exceeded in any given year (base flood). This document revises the effective NFIP map to remove the subject property from the SFHA located on the effective NFIP map; therefore, the Federal mandatory flood insurance requirement does not apply. However, the lender has the option to continue the flood insurance requirement to protect its financial risk on the loan. A Preferred Risk Policy (PRP) is available for buildings located outside the SFHA. Information about the PRP and how one can apply is enclosed.

This determination is based on the flood data presently available. The enclosed documents provide additional information regarding this determination. If you have any questions about this document, please contact the FEMA Map Information eXchange (FMIX) toll free at (877) 336-2627 (877-FEMA MAP) or by letter addressed to the Federal Emergency Management Agency, Engineering Library, 3601 Eisenhower Ave Ste 500, Alexandria, VA 22304-6426.

Luis V. Rodriguez, P.E., Director Engineering and Modeling Division

Federal Insurance and Mitigation Administration

Page 2 of 5 Date: March 10, 2020 Case No.: 20-06-0655A LOMR-F



Federal Emergency Management Agency

Washington, D.C. 20472

LETTER OF MAP REVISION BASED ON FILL DETERMINATION DOCUMENT (REMOVAL)

ATTACHMENT 1 (ADDITIONAL CONSIDERATIONS)

LEGAL PROPERTY DESCRIPTION (CONTINUED)

Tract 2:

COMMENCING at a 1-1/4-inch iron pipe found, being the northeast corner of said called 420. 119 acre tract, being the northwest corner of a called Lot 1 of Pine Meadows, an unrecorded subdivision conveyed to Kemberley Ray by Warranty Deed recorded in Clerk's File No. 2008-099076, Montgomery County Official Public Records of Real Property, and being on the south right-of-way line of State Highway F.M. 3083 (based on a width of 100-feet); Thence, South 02°58'01" East, 322.12 feet to a point for corner being on the west line of said called Lot 1 and being on the east line of said called 420.119 acre tract; Thence, South 87°01'59" West, 20.01 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set, being the northeast corner and POINT OF BEGINNING of the herein described tract; Thence, South 02°57'57" East, 661.99 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set, being the southeast corner of the herein described tract; Thence, North 81°12'33" West, 503.46 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set, being the southwest corner of the herein described tract; Thence, North 06°27'54" East, 107.59 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 01°27'42" West, 98.67 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 01°27'42" West, 98.67 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 02°57'11" West, 280.36 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set, being the northwest corner of the herein described tract; Thence, North 87°01'48" East, 464.88 feet to the POINT OF BEGINNING.

Tract 3

COMMENCING at a 1-1/4-inch iron pipe found being the most easterly northeast corner of a called 65.2843 acre tract conveyed to Jerry W. Granger by Gift Deed recorded in Clerk's File No. 2019014161, Montgomery County Official Public Records, being the most northerly corner of said called 420.119 acre tract, and being on the south right-of-way line of State Highway F.M. 3083 (based on a width of 100-feet); Thence, South 02°55'38" East, 829.60 feet to a concrete monument (disturbed) found being on the interior line of said called 420. 119 acre tract and being on the east line of said called 40 acre tract; Thence, South 05°17'39" East, 333.41 feet to point for corner, being the southeast corner of said called 40 acre tract and being an interior corner of said called 420. 119 acre tract; Thence, South 08°00'27" East, 155.15 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set being the northwest corner and POINT OF BEGINNING of the herein described tract; Thence, North 84°36'20" East, 117.66 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 78°31'38" East, 52.07 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 86°04'00" East, 127.33 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 00°53'36" West, 308.92 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 01°26'48" East, 46.61 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 10°48'16" East, 32.39 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 34°26'08" East, 55.93 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 46°56'23" West, 125.00 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set, being the beginning of a non-tangent curve to the left; Thence, along said non-tangent curve to the left in an easterly direction, having a radius of 271.01 feet, a central angle of 95°22'24", an arc length of 451.11 feet, and a chord bearing North 89°15'11" East, 400.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 48°26'01" West, 125.00 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 34°39'55" East, 35.09 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 20°51'49" East, 35.09 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 07°03'43" East, 35.09 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 03°31'29" West, 38.48 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 04°08'08" West, 80.45 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 00°40'07" West, 51.77 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North

This attachment provides additional information regarding this request. If you have any questions about this attachment, please contact the FEMA Map Information eXchange (FMIX) toll free at (877) 336-2627 (877-FEMA MAP) or by letter addressed to the Federal Emergency Management Agency, Engineering Library, 3601 Eisenhower Ave Ste 500, Alexandria, VA 22304-6426.

Page 3 of 5 Date: March 10, 2020 Case No.: 20-06-0655A LOMR-F



Federal Emergency Management Agency

Washington, D.C. 20472

LETTER OF MAP REVISION BASED ON FILL DETERMINATION DOCUMENT (REMOVAL)

ATTACHMENT 1 (ADDITIONAL CONSIDERATIONS)

05°46'51" East, 51.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 12°14'12" East, 51.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 18°41'33" East, 51.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 25°08'54" East, 51.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 31°36'15" East, 51.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 38°03'37" East, 51.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 44°30'58" East, 51.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 50°58'19" East, 51.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 57°25'40" East, 51.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 63°53'01" East, 51.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 70°20'22" East, 51.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 76°47'43" East, 51.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 83°15'04" East, 51.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 89°42'25" East, 51.81 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 83°53'44" East, 51.02 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 81°02'53" East, 87.45 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 57°33'28" East, 58.24 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 86°38'01" East, 120.00 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set, being the northeast corner of the herein described tract; Thence, South 03°26'50" West, 43.50 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 05°27'13" West, 43.52 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 07°28'22" West, 43.52 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 09°29'31" West, 43.52 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 11°30'41" West, 43.52 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 13°31'50" West, 43.52 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 15°32'59" West, 43.52 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 17°34'08" West, 43.52 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 19°35'18" West, 43.52 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 21°36'27" West, 43.52 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 23°37'36" West, 43.52 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 25°38'45" West, 43.52 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 27°39'55" West, 43.52 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 28°57'34" West, 87.21 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 28°19'43" West, 172.23 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 28°38'09" West, 71.12 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set being the southeast corner of the herein described tract; Thence, South 67°35'27" West, 108.58 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 80°40'39" West, 103.32 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 53°47'36" West, 193.79 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set, being the beginning of a non-tangent curve to the right; Thence, along said non-tangent curve to the right in a southwesterly direction, having a radius of 321.01 feet, a central angle of 33°45'54", an arc length of 189.17 feet, and a chord bearing South 53°00'20" West, 186.45 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set, being the beginning of a reverse curve to the left; Thence, along said reverse curve to the left in a southwesterly direction, having a radius of 25.00 feet, a central angle of 84°35'12", an arc length of 36.91 feet, and a chord bearing South 27°35'41" West, 33.65 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 80°57'38" West, 50.23 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set being the beginning of a non-tangent curve to the left; Thence, along said non-tangent curve to the left in a southerly direction, having a radius of 1,025.03 feet, a central angle of 05°38'39", an arc length of 100.98 feet, and a chord bearing South 17°14'38" East, 100.94 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, South 86°34'22" West, 88.25 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set;

This attachment provides additional information regarding this request. If you have any questions about this attachment, please contact the FEMA Map Information eXchange (FMIX) toll free at (877) 336-2627 (877-FEMA MAP) or by letter addressed to the Federal Emergency Management Agency, Engineering Library, 3601 Eisenhower Ave Ste 500, Alexandria, VA 22304-6426.

Page 4 of 5 Date: March 10, 2020 Case No.: 20-06-0655A LOMR-F



Federal Emergency Management Agency

Washington, D.C. 20472

LETTER OF MAP REVISION BASED ON FILL DETERMINATION DOCUMENT (REMOVAL)

ATTACHMENT 1 (ADDITIONAL CONSIDERATIONS)

Thence, North 84°07'01" West, 64.53 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 75°43'35" West, 64.53 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 67°20'09" West, 64.53 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 58°56'42" West, 64.53 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 50°33'16" West, 64.53 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 42°09'50" West, 64.53 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 33°46'24" West, 64.53 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 25°22'57" West, 64.53 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 16°59'31" West, 64.53 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 08°36'05" West, 64.53 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 00°55'40" West, 59.18 feet to a 5/8-inch iron rod (with cap stamped "Manhard") set; Thence, North 00°54'26" East. 299.05 feet to the POINT OF BEGINNING.

DETERMINATION TABLE (CONTINUED)

LOT	BLOCK/ SECTION	SUBDIVISION	STREET	OUTCOME WHAT IS REMOVED FROM THE SFHA	FLOOD ZONE	1% ANNUAL CHANCE FLOOD ELEVATION (NAVD 88)	LOWEST ADJACENT GRADE ELEVATION (NAVD 88)	LOWEST LOT ELEVATION (NAVD 88)
	-		Granger Pines Way	Portion of Property (Tract 3)	X (shaded)	1		143.1 feet

PORTIONS OF THE PROPERTY REMAIN IN THE FLOODWAY (This Additional Consideration applies to the preceding 2 Properties.)

A portion of this property is located within the Special Flood Hazard Area and the National Flood Insurance Program (NFIP) regulatory floodway for the flooding source indicated on the Determination/Comment Document while the subject of this determination is not. The NFIP regulatory floodway is the area that must remain unobstructed in order to prevent unacceptable increases in base flood elevations. Therefore, no construction may take place in an NFIP regulatory floodway that may cause an increase in the base flood elevation, and any future construction or substantial improvement on the property remains subject to Federal, State/Commonwealth, and local regulations for floodplain management. The NFIP regulatory floodway is provided to the community as a tool to regulate floodplain development. Modifications to the NFIP regulatory floodway must be accepted by both the Federal Emergency Management Agency (FEMA) and the community involved. Appropriate community actions are defined in Paragraph 60.3(d) of the NFIP regulations. Any proposed revision to the NFIP regulatory floodway must be submitted to FEMA by community officials. The community should contact either the Regional Director (for those communities in Regions I-IV, and VI-X), or the Regional Engineer (for those communities in Region V) for guidance on the data which must be submitted for a revision to the NFIP regulatory floodway. Contact information for each regional office can be obtained by calling the FEMA Map Assistance Center toll free at (877) 336-2627 (877-FEMA MAP) or from our web site at http://www.fema.gov/about/regoff.htm.

This attachment provides additional information regarding this request. If you have any questions about this attachment, please contact the FEMA Map Information eXchange (FMIX) toll free at (877) 336-2627 (877-FEMA MAP) or by letter addressed to the Federal Emergency Management Agency, Engineering Library, 3601 Eisenhower Ave Ste 500, Alexandria, VA 22304-6426.

Page 5 of 5 Date: March 10, 2020 Case No.: 20-06-0655A LOMR-F



Federal Emergency Management Agency

Washington, D.C. 20472

LETTER OF MAP REVISION BASED ON FILL DETERMINATION DOCUMENT (REMOVAL)

ATTACHMENT 1 (ADDITIONAL CONSIDERATIONS)

FILL RECOMMENDATION (This Additional Consideration applies to the preceding 2 Properties.)

The minimum NFIP criteria for removal of the subject area based on fill have been met for this request and the community in which the property is located has certified that the area and any subsequent structure(s) built on the filled area are reasonably safe from flooding. FEMA's Technical Bulletin 10-01 provides guidance for the construction of buildings on land elevated above the base flood elevation through the placement of fill. A copy of Technical Bulletin 10-01 can be obtained by calling the FEMA Map Assistance Center toll free at (877) 336-2627 (877-FEMA MAP) or from our web site at http://www.fema.gov/mit/tb1001.pdf. Although the minimum NFIP standards no longer apply to this area, some communities may have floodplain management regulations that are more restrictive and may continue to enforce some or all of their requirements in areas outside the Special Flood Hazard Area.

STATE AND LOCAL CONSIDERATIONS (This Additional Consideration applies to all properties in the LOMR-F DETERMINATION DOCUMENT (REMOVAL))

Please note that this document does not override or supersede any State or local procedural or substantive provisions which may apply to floodplain management requirements associated with amendments to State or local floodplain zoning ordinances, maps, or State or local procedures adopted under the National Flood Insurance Program.

This attachment provides additional information regarding this request. If you have any questions about this attachment, please contact the FEMA Map Information eXchange (FMIX) toll free at (877) 336-2627 (877-FEMA MAP) or by letter addressed to the Federal Emergency Management Agency, Engineering Library, 3601 Eisenhower Ave Ste 500, Alexandria, VA 22304-6426.