

CRASH CHAMPIONS #0361 FAIRBANKS

We Believe The Difference is Trust 14641 Northwest Freeway, Houston, TX 77040 Phone: (281) 404-3353 Workfile ID:

44df1045

Final Bill

RO Number: 361004704

Customer:

Insurance:

Adjuster:

Estimator:

Nilson Lazo

ARMSTRONG

ALLSTATE FIRE AND CASUALTY

Phone:

Create Date:

5/21/2024

9274 BLANKENSHIP DR

HOUSTON, TX 77080-2913

Allstate Fire and Casualt

Claim:

000755543436H01

Loss Date:

5/19/2024

(832) 441-6882

Northbrook

Deductible:

1,000.00

2022 TOYO Corolla SE w/Continuously Variable Transmission 4D SED 4-2.0L Gasoline Port/Direct Injection Silver

VIN:

5YFS4MCE6NP101729

Interior Color:

Mileage In: 25,419

Vehicle Out:

5/31/2024

License:

State:

TPX9404

TX

Exterior Color:

Production Date:

Silver 8/2021

Condition:

Mileage Out:

Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Туре	Paint
1	E01		FRONT BUMPER & GRILLE						
2	E01	Repair	Bumper cover w/o hybrid w/o Apex				3.0	Body	3.0
3	E01		Add for Clear Coat						1.2
4	S01		Basecoat reduction						(0.5)
5	E01	Overhaul	O/H bumper assy			OEM	3.4	Body	
6	E01	Remove/Replace	LT Cover extn	1	75.00T	A/M	0.0	Body	
7	E01	Remove/Replace	RT Cover extn	1	75.00T	A/M	0.0	Body	
8	S02	Sublet	ADAS CALIBRATION	1	350.00	Other			
9	E01		RADIATOR SUPPORT						
10	E01	Remove/Replace	Rear shield	1	189.00T	A/M	0.4	Body	
11	E01		ELECTRICAL						
12	E01	Remove/Replace	TPMS sensor	4	350.00T	A/M	0.0	Body	
13	E01		WHEELS						
14	E01	Remove/Replace	LT/Front Wheel, alloy 18"	1	425.00T	RCY	0.3	Body	
15	E01	Remove/Replace	RT/Rear Wheel, alloy 18"	1	425.00T	RCY	0.3	Body	
16	E01	Remove/Replace	RT/Front Wheel, alloy 18"	1	425.00T	RCY	0.3	Body	
17	E01	Remove/Replace	LT/Rear Wheel, alloy 18"	1	425.00T	RCY	0.3	Body	
18	E01	Remove/Replace	Wheel Lock kit and lugs	1	200.00T	A/M			
19	E01		TIRES						
20	501	Remove/Replace	DNLP 225/40R18 SP Sport 5000 BW 88V	4	1,000.00T	Other	0.0	Body	
21	E01		FRONT SUSPENSION						
22	E01	Remove/Replace	RT Splash shield	1	34.19T	OEM	1.4	Mech	
23	E01	Remove/Replace	LT Splash shield	1	34.19T	OEM	1.4	Mech	
24	E01	Remove/Install	LT Caliper assy				1.0	Mech	
25	E01	Remove/Install	RT Caliper assy				1.0	Mech	
26	E01	Sublet	4WA - Four Wheel Alignment	1	99.95	Other			

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 361004704

2022 TOYO Corolla SE w/Continuously Variable Transmission 4D SED 4-2.0L Gasoline Port/Direct Injection Silver

27	S02	Remove/Replace	RT Axle nut	1	9.14T	A/M			
28	E01		PILLARS, ROCKER & FLOOR						
29	E01	Remove/Install	RT Rocker molding US built w/o APEX				1.3	Body	
30	E01	Remove/Install	LT Rocker molding US built w/o APEX				1.3	Body	
31	E01	Repair	RT Lower panel US built w/o night shade				1.0	Body	1.0
32	E01	Repair	LT Lower panel US built w/o night shade				1.0	Body	1.0
33	E01		REAR SUSPENSION						
34	E01	Remove/Replace	RT Backing plate US built	1	34.19T	OEM	1.6	Mech	
35	E01	Remove/Replace	LT Backing plate US built	1	34.19T	OEM	1.6	Mech	
36	E01	Remove/Install	RT Caliper US built				1.1	Mech	
37	E01	Remove/Install	LT Caliper US built				1.1	Mech	
38	E01		VEHICLE DIAGNOSTICS						
39	E01	Repair	Pre-repair scan				0.5	Mech	
40	E01	Repair	Post-repair scan				0.5	Mech	
41	E01		Flex Additive	1	4.35T	Other			
42	S02		Fuel Surcharge	1	5.00T	Other			

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts		425.00			4,169.25
Labor, Body			56.00	12.6	705.60
Labor, Refinish			56.00	5.7	319.20
Labor, Mechanical			100.00	11.2	1,120.00
Material, Paint					239.40
Miscellaneous					449.95
Subtotal					7,003.40
Sales Tax					363.71
Grand Total					7,367.11
Deductible					(1,000.00)
Net Total					6,367.11

Estimate Version	Total \$
Original	7,210.06
Supplement S01	(208.25)
Supplement S02	365.30
Insurance Total \$:	6,367.11
Received from Insurance \$:	0.00
Balance due from Insurance \$:	6,367.11
Customer Total \$:	1,000.00
Received from Customer \$:	0.00
Balance due from Customer \$:	1,000.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, DEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

CRASH CHAMPIONS #0361 FAIRBANKS

14641 Northwest Freeway, Houston, TX 77040

Customer - ARMSTRONG

70193Z

Phone: (281) 404-3353

Payment Receipt (Complete)

Receipt Number: 361004704-CP-001 Date Received: 5/30/2024

Received By: Orlis Gutierrez

RO Number: 361004704

Owner Name: ARMSTRONG, Vehicle Year: 2022 Exterior Color: Silver

Insurance: ALLSTATE FIRE AND Vehicle Make: TOYO VIN: 5YFS4MCE6NP101729

CASUALTY INSURANCE COMPANY

Claim Number: 000755543436H01 Vehicle Model: Corolla SE w/Continuousl... License Plate: TPX9404

Payment Type: Visa/MC/Discover \$ 1,000.00

Received From:

Memo:

Check/Auth. Number:

Total Balance Due: \$ 1,000.00

Payments Received: \$ 1,000.00

Remaining Balance: \$ 0.00