

Seller's Disclosure Notice Concerning the Property at 20250 Smithfield Crossing Lane Katy Page 2
(Street Address and City)

2. Does the property have working smoke detectors installed in accordance with the smoke detector requirements of Chapter 766, Health and Safety Code? Yes No Unknown. If the answer to this question is no or unknown, explain (Attach additional sheets if necessary):

* Chapter 766 of the Health and Safety Code requires one-family or two-family dwellings to have working smoke detectors installed in accordance with the requirements of the building code in effect in the area in which the dwelling is located, including performance, location, and power source requirements. If you do not know the building code requirements in effect in your area, you may check unknown above or contact your local building official for more information. A buyer may require a seller to install smoke detectors for the hearing impaired if: (1) the buyer or a member of the buyer's family who will reside in the dwelling is hearing impaired; (2) the buyer gives the seller written evidence of the hearing impairment from a licensed physician; and (3) within 10 days after the effective date, the buyer makes a written request for the seller to install smoke detectors for the hearing impaired and specifies the locations for the installation. The parties may agree who will bear the cost of installing the smoke detectors and which brand of smoke detectors to install.

3. Are you (Seller) aware of any known defects/malfunctions in any of the following? Write Yes (Y) if you are aware, write No (N) if you are not aware.

- | | | |
|---|--|---|
| <input checked="" type="checkbox"/> Interior Walls | <input checked="" type="checkbox"/> Ceilings | <input checked="" type="checkbox"/> Floors |
| <input checked="" type="checkbox"/> Exterior Walls | <input checked="" type="checkbox"/> Doors | <input checked="" type="checkbox"/> Windows |
| <input checked="" type="checkbox"/> Roof | <input checked="" type="checkbox"/> Foundation/Slab(s) | <input checked="" type="checkbox"/> Sidewalks |
| <input checked="" type="checkbox"/> Walls/Fences | <input checked="" type="checkbox"/> Driveways | <input checked="" type="checkbox"/> Intercom System |
| <input checked="" type="checkbox"/> Plumbing/Sewers/Septics | <input checked="" type="checkbox"/> Electrical Systems | <input checked="" type="checkbox"/> Lighting Fixtures |
| <input checked="" type="checkbox"/> Other Structural Components (Describe): | | |

If the answer to any of the above is yes, explain. (Attach additional sheets if necessary):

4. Are you (Seller) aware of any of the following conditions? Write Yes (Y) if you are aware, write No (N) if you are not aware.

- | | |
|--|---|
| <input checked="" type="checkbox"/> Active Termites (includes wood destroying insects) | <input checked="" type="checkbox"/> Previous Structural or Roof Repair |
| <input checked="" type="checkbox"/> Termite or Wood Rot Damage Needing Repair | <input checked="" type="checkbox"/> Hazardous or Toxic Waste |
| <input checked="" type="checkbox"/> Previous Termite Damage | <input checked="" type="checkbox"/> Asbestos Components |
| <input checked="" type="checkbox"/> Previous Termite Treatment | <input checked="" type="checkbox"/> Urea-formaldehyde Insulation |
| <input checked="" type="checkbox"/> Improper Drainage | <input checked="" type="checkbox"/> Radon Gas |
| <input checked="" type="checkbox"/> Water Damage Not Due to a Flood Event | <input checked="" type="checkbox"/> Lead Based Paint |
| <input checked="" type="checkbox"/> Landfill, Settling, Soil Movement, Fault Lines | <input checked="" type="checkbox"/> Aluminum Wiring |
| <input checked="" type="checkbox"/> Single Blockable Main Drain in Pool/Hot Tub/Spa* | <input checked="" type="checkbox"/> Previous Fires |
| | <input checked="" type="checkbox"/> Unplatted Easements |
| | <input checked="" type="checkbox"/> Subsurface Structure or Pits |
| | <input checked="" type="checkbox"/> Previous Use of Premises for Manufacture of Methamphetamine |

If the answer to any of the above is yes, explain. (Attach additional sheets if necessary):

WOOD EYES IN FRONT NEED REPAIR
DAMAGED WOOD ON EVE DL

* A single blockable main drain may cause a suction entrapment hazard for an individual.