Concerning t	the Property	at
--------------	--------------	----

9021 GAYLORD DR UNIT 79 HOUSTON, TX 77024

	-	- 1				1100010	14, 17, 11	027		
Underground Lawn Sprinkl			V	aut	omati	c manual	areas co	vered:		
Septic / On-Site Sewer Fac	cility		Vi	f yes,	attach	Information	About Or	n-Site Sewer Facility (TXR-140)7)	
Water supply provided by: Was the Property built before (If yes, complete, sign, Roof Type:	and a	attach	vell MUI _ yes no TXR-1906	O c o u conce	o-op Inknov erning	unknown vn lead-based	other:	ards).		
Is there an overlay roof covering)?yes no	cover _unkr	ing or nown	n the Prop	perty	_ Age (shing	les or roof	covering	placed over existing shingle	oxim s or	ate) roof
Are you (Seller) aware of a are need of repair? yes	any of no	f the it If yes	ems listed , describe	in thi (attac	s Sec h add	tion 1 that a	re not in v	working condition, that have ceary):	efect	s, or
Section 2. Are you (Selle aware and No (N) if you a	er) aw	are of	any defe	cts or	malf	unctions in	any of th	e following? (Mark Yes (Y) i	f you	ı are
Item	Y	N	Item	Item			YN	Item	Y	N
Basement		V	Floors	Floors				Sidewalks		V
Ceilings			Foundation / Slab(s)					Walls / Fences		
Doors		V	Interior	Walls			V	Windows	\top	4
Driveways		V	Lighting Fixtures					Other Structural Components		
Electrical Systems		V	Plumbir	Plumbing Systems						V
Exterior Walls		V	Roof						+	
Section 3. Are you (Seller you are not aware.)	r) awa	are of	any of the	e follo	wing	conditions	? (Mark Y	es (Y) if you are aware and	No (I	N) if
Condition				Y	N	Conditio	n		Υ	N
Aluminum Wiring	Aluminum Wiring			V		Radon G			+-	0
Asbestos Components					V	Settling		· · · · · · · · · · · · · · · · · · ·		1
Diseased Trees:oak wilt					V	Soil Move	ement		+-	
Endangered Species/Habitat on Property					1	Subsurfa	ce Structu	re or Pits	+	
Fault Lines					1		und Stora			
Hazardous or Toxic Waste				1		Easemer				
Improper Drainage				V	Unrecord	ed Easem	ents		1	
Intermittent or Weather Springs				V	Urea-forn	naldehyde	Insulation		17	
Landfill				V			Due to a Flood Event	1	V	
Lead-Based Paint or Lead-Based Pt. Hazards						on Proper				
Encroachments onto the Property			V	Wood Ro			1	~		
Improvements encroaching	on oth	ners' p	roperty		1	The second secon	estation of ginsects (termites or other wood WDI) *		V
Located in Historic District					V			for termites or WDI		
Historic Property Designation					V			WDI damage repaired	1	
Previous Foundation Repairs	s				V	Previous				V
Previous Roof Repairs				V	Termite o	WDI dam	nage needing repair		0	
Previous Other Structural Repairs				V			ain Drain in Pool/Hot			
Previous Use of Premises fo of Methamphetamine	r Man	ufactu	ire		V	Γ.,	(1000)		<u> </u>	

(TXR-1406) 09-01-19

Initialed by: Buyer: _

and Seller:

Page 2 of 6

Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com

9021 Gaylord St