

Having trouble viewing this email? [View it in your browser.](#)

PRODUCT REGISTRATION



Turn to the exper

Today's date: Aug 15, 2021

CONFIRMATION

MELISSA VARNON,

Thank you for your recent heating and cooling purchase. Your candid feedback is important to us. Please click on "Rate Your Experience" below. We hope you will share with us – and the world via our Web site – your Carrier HVAC experience.

Please note that you will have 30 days to rate your installing contractor from the link below.

Your registration confirmation number is **Z004843377289C**

Rate your experience

Equipment Owner

MELISSA VARNON
505 COUNTY ROAD 1660
LIBERTY, TX 77575
US
9363469059
MAVARNON@YAHOO.COM

Equipment Location

505 COUNTY ROAD 1660
LIBERTY, TX 77575
US
9363469059
MAVARNON@YAHOO.COM

Dealer Information

Southeast Texas Air Conditioning and Heating
130 West St
7132034536
Liberty TX
77575
US
7132034536

Type of purchase

Replacement of Existing Equipment

Application Type

Residential Single Family

Installed products

Model	Serial	InstallationDate	Coverage	End Date
FX4DNF037L00	2821F18604	8/11/2021	Enhanced Parts Warranty	08/11/2031

If your new system ever needs a repair, ask your servicing dealer to only use **Factory Authorized Parts™**

Designed for Easy Install & Service, Engineered for Quality

Factory Authorized Parts™ have been designed and built specifically for Carrier®, Bryant® or Payne® equipment. These parts are the perfect fit, restoring equipment to it's original performance.

- U.L. & C.S.A. qualified

8/17/2021, 5:13 AM

- Preserves the original manufacturer's warranty
- Preserves the original efficiency of the system
- Meets rigorous factory run life design specifications

Having Trouble?

In most cases, your installing dealer is the best source for your registration information. For example, they will have accurate serial numbers for your new equipment as well as information to ensure they are properly selected as your installing dealer.

[Privacy Policy](#) | [Terms of Use](#) | [Unsubscribe](#)

A Carrier Company

© 2020 Carrier. All Rights Reserved

Southeast Texas Air Conditioning and Heating

130 West St.

Liberty, Texas 77575

Office: 936-336-2675 Fax: 936-336-9650

Cell: 713-203-4536

INVOICE# 1593

☒ RESIDENTIAL
☐ COMMERCIAL

☐ INSTALL
☐ SERVICE

☐ SERVICE
☐ AGREEMENT

☒ HEATING ☒ COOLING ☐ REFRIGERATION ☐ OTHER

☒ COMPLETE ☐ INCOMPLETE (explain)

EQUIPMENT MAKE MODEL SERIAL NUMBER

AIR HANDLER CARRIER FX4DNF051
0821F18604

AIR FILTER INFO:

DESCRIPTION OF OUR SERVICE

REMOVE EXISTING 3TON
AIR HANDLER, SECONDARY
PAN + HEATER.

INSTALL CARRIER 3TON
410A AIR HANDLER WITH
+15 KW HEAT STRIP.

TO INCLUDE

- ① FILTER DRYER
- ② SECONDARY PAN
- ③ OVERFLOW SWITCH
- ④ CONNECT TO EXISTING DUCTWORK
+ DRAIN LINES
- ⑤ PULL VACUUM + RECHARGE SYSTEM

PROFESSIONAL RECOMMENDATIONS

NOTES

INVESTMENT SUMMARY

SUBTOTAL 3158.47

Rate X Miles

The charges were explained to me and the work was done to my complete satisfaction. I have read and understand the terms outlined on the reverse side of this agreement. I have the authority to order the above work and do so order as outlined above. It is agreed that the seller will retain title to any equipment or material furnished until final & complete payment is made, and if settlement is not made as agreed, the seller shall have the right to remove same and the seller will be held harmless for any damages resulting from the removal thereof.

X

AUTHORIZED SIGNATURE

DATE

Service Call

Mileage

Diagnostic
Fee

Parts & Labor


8.25% Tax
If Applicable

TOTAL
AMOUNT DUE

THIS IS YOUR INVOICE - PLEASE PAY TECHNICIAN TODAY - THANK YOU

Brighteyes Enterprise, Inc.

395 County Road 608
Dayton, TX 77535



Invoice

DATE	INVOICE NO.
11/14/2024	30253

BILL TO	INSTALLATION LOCATION
Stuart & Melissa Varnon 505 CR 1660 Liberty, TX 77575	Stuart & Melissa Varnon 505 CR 1660 (Fregia Settlement Rd) Liberty, TX 77575

PAID
11/15/2024

ITEM	DESCRIPTION	TERMS	REP
		Due on receipt	TM
		COST	TOTAL
Service Call	Inspected septic system to determine if system is operating properly per customer's telephone call reporting sprinklers aren't working. Removed and cleaned external and internal filters on aerobic compressor, removed aerobic discharge pump, checked float switches and cleaned intake screen/filter and replaced pump back into aerobic pump tank, and inspected liquid color and content in aerobic system tankage to determine if cleaning is necessary.	0.00	0.00
Aerobic Discharge Pump/FS	Remove and replace existing aerobic system high pressure water/effluent discharge pump and a new float switch. Includes one year warranty.	1,200.00	1,200.00
Float Switch Alarm Pump L... Fujimac 80	Remove and replace existing alarm float switch in aerobic pump tank. Replace existing compressor with new Fujimac 80 Compressor with two (2) year warranty.	200.00 800.00	200.00 800.00
Alarm sound sight device	Installed new sound and sight device in control panel.	125.00	125.00
New Clearstream lid - 20" lid	Install new 20" Clearstream tank lid.	125.00	125.00
Vacuum 1500 gals.	Vacuum out 1500 gals. of septic fluid and transport to a State approved septic disposal site. Control Ticket # 308432	575.00	575.00

Thank you & God Bless, Brighteyes staff.

Total \$3,025.00

Payments/Credits \$0.00

Balance Due \$0.00

Phone #

936-258-3080

E-mail

Web Site

www.brighteyestexas.com