

Houston's Best Air Heat TACLB96596C

2321 May Apple St
Baytown, TX 77523-8504 USA
hbac713@yahoo.com

Estimate

ADDRESS
Isaac Delcid

ESTIMATE 156
DATE 06/05/2025
EXPIRATION DATE 07/01/2025

DATE	SERVICE	DESCRIPTION	QTY	RATE	AMOUNT
	Maintenance and Reapirs	7214 Shady Arbor Houston TX. 77040 All supply ducts needs to be hung up properly and repaired, sealed properly, some supply flex need to be reattached and sealed at the supply plenum and at the supply boxes, safety float switch needs to be replaced, thermostat not operating and needs to be replaced, insulation on copper line needs to be replaced, primary drain line needs to be re-ran properly and replace insulation, secondary drain pan can be cleaned, system needs a maintenance done to it, outdoor needs cleaning, drain lines need to be cleared, and filters replaced, return plenum needs to be resealed properly to the air handler,	1	1,600.00	1,600.00

SUBTOTAL					1,600.00
TAX					0.00

TOTAL					\$1,600.00

Accepted By

Accepted Date