

ENERGY PLUS

Visual Inspections Completed
by Quality 3rd Party Inspectors

Duct Blast Test
Blower Door Test
Energy Seal Package
R-38 Insulation
R-6 Insulated Duct System
Radiant Barrier Decking

HERS Index Score
CFL Bulbs (95%)
16 Seer AC

Vinyl Double Pane Triple Low E Windows
Pex Plumbing System with Mana Block
Programmable Thermostat 7 stat with dehumidification
Energy Star Rated
Continuous Perforated Soffit and Ridge Vent Attic
Ventilation