



Improvement List

PROPERTY ADDRESS: 1 Tangle Brush Dr, Spring, TX 77381

Please list below any improvements, updates, or renovations that you have done to the property with approximate dates:

Improvement:	Approx Cost	Approx Date Completed
Painted dining room, kitchen, 1/2 bath, laundry		03/2019
installed new carpet in all bedrooms		03/2019
replaced all light bulbs		03/2019
replaced front patio		03/2019
replaced garbage disposal		02/2019
replaced back patio ceiling fan fixture	200	03/2018
installed Rainsoft water purifier system		09/2016
replaced built-in bookcase in living room		08/2016
resurfaced back patio	200	spring 2017
painted exterior trim/siding and repaired where necessary		03/2019
pathlights along sidewalk	50	11/2016
3 new toilets		08/2016
reconfigured closet rods/shelving in all closets	450	
added walkway to back yard	300	05/2018
Knobs on all cabinets in the kitchen, laundry room & bathrooms		
New fixtures in the sinks in the master bathroom		