## **Home Condition Summary**



## 14322 Ellis Springs Ln Humble, TX 77396

**Evaluation Date:** February 2019 **Renovation Date:** April 2019

Year Built: 2009



Exterior	Key System Facts	Condition Checklist	Repairs and Renovations
	Siding type: Brick	<ul> <li>✓ Garage doors, sensors and openers are operational</li> <li>✓ Foundation and siding showed no evidence of leaks or damage</li> </ul>	<ul><li>Locks rekeyed</li><li>Basic landscaping</li><li>Paint touched up</li></ul>
Interior & Appliances	Key System Facts	Condition Checklist	Repairs and Renovations
	Appliances: Stainless Range type: Electric	<ul> <li>✓ Appliances are operational</li> <li>✓ Outlets, switches, ceiling fans and smoke detectors are operational</li> </ul>	<ul> <li>New paint: living room ceiling, bedroom 2, bedroom 3, bedroom 4, garage</li> <li>New range</li> </ul>

This Home Condition Summary is intended to provide you with an overview of the current condition of the home systems and components. This Home Condition Summary is for informational purposes only. The Home Condition Summary is not intended to be technically exhaustive or considered to be a guarantee or warranty, express or implied, regarding the condition of the property, items and systems. The Home Condition Summary should not be considered a substitute for a comprehensive property inspection report conducted by a licensed inspector.

## **Home Condition Summary**



## 14322 Ellis Springs Ln, Humble, TX 77396

Roof	Key System Facts	Condition Checklist	Repairs and Renovations
	<b>Type:</b> Shingle	<ul><li>✓ Checked for leaks or gaps in flashing</li><li>✓ Checked for loose or damaged materials</li></ul>	• No repairs needed
Plumbing & Water Heater	Key System Facts	Condition Checklist	Repairs and Renovations
	Brand: Bradford White Type: Gas Capacity: 40 gallons	<ul><li>✓ Verified system operation</li><li>✓ Checked plumbing distribution lines</li></ul>	• No repairs needed
HVAC	Key System Facts	Condition Checklist	Repairs and Renovations
	Brand: Lennox Furnace type: Gas	<ul><li>✓ Verified system operation</li><li>✓ Verified temperature splits</li></ul>	<ul><li>System serviced by licensed specialist</li><li>Coils cleaned</li><li>Filters replaced</li></ul>

This Home Condition Summary is intended to provide you with an overview of the current condition of the home systems and components. This Home Condition Summary is for informational purposes only. The Home Condition Summary is not intended to be technically exhaustive or considered to be a guarantee or warranty, express or implied, regarding the condition of the property, items and systems. The Home Condition Summary should not be considered a substitute for a comprehensive property inspection report conducted by a licensed inspector.