

# Williford Land Surveying

710 East Commerce Street · Mexia, Texas 76667 Ph: 254-562-2837 · Fx: 254-562-2867 Clint Williford RPLS#5973.

**Legal Description** 

For Therion Real Estate II T. S. Walker Survey, Abstract No. 965 City of Buffalo Leon County, Texas

All that certain lot, tract or parcel of land, part of the T. S. Walker Survey, Abstract No. 965, City of Buffalo, Leon County, Texas and being all of the certain called 1/3 acre described in a Deed of Trust to Ricky Sims, Trustee from Gilbert A. Cardenas and Lupe G. Cardenas on October 4, 2005 and recorded in Volume 1228, Page 192 of the Official Records of Leon County, Texas and being more completely described as follows, to-wit:

BEGINNING at a 1/2" iron rod (set) for the East corner of the above mentioned 1/3 acre tract, the North corner of a called 72 ft. x 117 ft. Tract No. Two conveyed to Jeffery Rudolph Rodell in Volume 1018, Page 602 and being in the Southwest line of Center Street, from which a 1/2" iron rod (found) capped "Stanger" bears South 24 deg. 41 min. 08 sec. East - 244.21 ft.;

THENCE South 58 deg. 45 min. 07 sec. West with the Southeast line of the 1/3 acre tract and the Northwest line of the Rodell tract, a distance of 123.88 ft. to a 1/2" iron rod (set) for the West corner of same, the South corner of the 1/3 acre tract and being in the Northeast line of a called one acre Tract Two conveyed to David Ferguson and wife, Carolyn Ferguson on March 16, 2004 and recorded in Volume 1168, Page 332, from which a fence corner bears North 25 deg. 00 min. 54 sec. West - 8.3 ft.;

THENCE North 25 deg. 00 min. 54 sec. West with the Southwest line of the 1/3 acre tract and the Northeast line of the Ferguson tract, a distance of 141.56 3. to a 1/2" iron rod (set) for the West corner of the 1/3 acre tract and being the South corner of a called 1/2 acre tract conveyed to Fred L. Gilliam in Volume 685, Page 86;

THENCE North 58 deg. 45 min. 07 sec. East with the Northwest line of the 1/3 acre tract and the Southeast line of the Gilliam tract, a distance of 124.70 ft. to a 1/2" iron rod (set) for the East corner of same, the North corner of the 1/3 acre tract and being in the Southwest line of said Center Street;

THENCE South 24 deg. 41 min. 08 sec. East with the Northeast line of the 1/3 acre tract and the Southwest line of Center Street, a distance of 141,65 ft. to the place of beginning and containing 0.40 acre of land.

The bearings recited herein are based on the northerly Northeast line of a called 10.80 acre tract surveyed by Stanger Surveying Fairfield, LLC on March 30, 2009 under Job No. FO9021.

I James C. Williford, Registered Professional Land Surveyor No. 5973, do hereby certify that the legal description hereon was prepared from an actual survey made on the ground under my direction and supervision.

James C. Williford Registered Professional Land Surveyor No. 5973

August 18, 2009

Job No. 09-084 Book: 16/34

Plat accompanies legal description

EXHIBIT A



#### TEXAS ASSOCIATION OF REALTORS® **SELLER'S DISCLOSURE NOTICE**

©Texas Association of REALTORS®, Inc. 2018

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

201 S Center Street

CONCERNING THE PR	ROP	ERT	Y A	Γ				-	3uffa	alo, T	X 75831			
DATE SIGNED BY SE	LLE	RAN	ID IS	SN	OT	A S	UBSTITUTE FOR A	NY	INSI	PECT	TION OF THE PROPERTY AS IONS OR WARRANTIES THE SELLER'S AGENTS, OR ANY	BU	IYE	R
Seller is is not o	-						unoccupied (by Sellmate date) or nev				since Seller has occupied the F	rop	erty	?
Section 1. The Proper	rty h	as t	he it	em	s m	arke	d below: (Mark Yes	(Y)	, No	(N), c	· -	·		
Item	Υ	N	U		Ite	m		Y	N	U	Item	Y	N	U
Cable TV Wiring							Propane Gas:		V		Pump: sump grinder		1	
Carbon Monoxide Det.	1	V				فيتهم فالمنطقة والم	ommunity (Captive)		1		Rain Gutters		/	
Ceiling Fans							Property		1		Range/Stove	,		
Cooktop		/				ot Tu			/		Roof/Attic Vents		/	
Dishwasher		1			Int	ercc	m System		1		Sauna	*******	1	
Disposal		/			Mi	CFOV	vave		1		Smoke Detector	1		
Emergency Escape Ladder(s)		~	ű,		Oi	ıtdo	or Grill		1		Smoke Detector - Hearing Impaired		1	
Exhaust Fans	-	3/			Pa	tio/E	Decking		V		Spa		East	
Fences		1			Ph	ımbi	ng System	IJ	1		Trash Compactor		V	
Fire Detection Equip.		1			Po	ol	N. H. S. C.		1		TV Antenna		V	
French Drain		1			Po	ol E	quipment		W		Washer/Dryer Hookup	/		
Gas Fixtures	2				Po	ol M	laint. Accessories	_	2		Window Screens		/	
Natural Gas Lines	1				Po	ol H	eater		2		Public Sewer System	2		
						,	(a. do		/4					
Item				Y	N	U					nal Information			
Central A/C		<del></del>					electric gas number of units: 10 yrs.							
Evaporative Coolers					V		number of units:							
Wall/Window AC Units				<u>/</u>			number of units; 2							
Attic Fan(s)					V		if yes, describe:							
Central Heat				/			✓ electric gas number of units:						·,	
Other Heat					V		if yes, describe:							
Oven		_	<u>/</u>			number of ovens: / electric gas other:						,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	100	
Fireplace & Chimney				V		wood gas log	-	<del> </del>		other:			<del>174</del>	
Carport			_		V				chec					
Garage				/			attached vnot	atta	chec					
Garage Door Openers			_		V		number of units:				number of remotes:			
Satellite Dish & Controls							ownedlease						- Academic	
Security System			_		V		owned leased		**********				_	
Solar Panels				V		owned leased							n	
Water Heater ,			_			electricgas		her:		number of units:	mak disentange	صدينا ويام		
Water Softener					1		owned leased from:							N
Other Leased Items(s)					V		if yes, describe:						<del></del>	

Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com

Ruchel Anderson Real Estate, 413 Main St Teague TX 75860

Elizabeth C. Ferrari

## 201 S Center Street

Basement	Concerning the Propert	y at				Burraic	), IX 758.	51		
Water supply provided by: \$\sigma\$ clip \$\text{well}\$ well \$\text{MUD}\$ co-op_unknown_other:  Was the Property built before 1978? \$\sigma\$ so no_unknown (if yes, complete, sign, and attach TAR-1414)  Was the Property built before 1978? \$\sigma\$ so no_unknown (if yes, complete, sign, and attach TAR-1414)  Was the Property built before 1978? \$\sigma\$ so no growth of the property (shingles or roof covering placed over existing shingles or roof covering)? \$\sigma\$ yes \$\sigma\$ no_unknown  Are you (Sellor) aware of any of the items listed in this Section 1 that are not in working condition, that have defects, of are need of repair? \$\sigma\$ yes \$\sigma\$ no if yes, describe (attach additional sheets if necessary):  Section 2. Are you (Sellor) aware of any defects or malfunctions in any of the following?: (Mark Yes (Y) if you are neaware and No (N) if you are not aware.)  Rem	T		w/	aut	omat	cmanual	areas co	vered:		
west in Property out to Brock 1978? yes _ no _ unknown (if yes, complete, sign, and attach TAR-1906 concerning lead-based paint hazards).  Roof Type:Asta/_Sh_ast/_ConcertificalAge:/O_K_S	Septic / On-Site Sewer	Facility	Vi	f yes,	attac	h Informatior	About Or	-Site Sewer Facility (TAR-1	407)	
Section 2. Are you (Seller) aware of any defects or malfunctions in any of the following?: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Item Y N Sasement Y N Sidewalks Walls / Fences Cellings Priveways Plumbing Systems Roof Wilneways Plumbing Systems Plumbing Systems Roof Wilneways Plumbing Systems Plumbing Systems Roof Wilneways Plumbing Systems Roof Wilnewa	(If yes, complete, si Roof Type:	gerore 1978 gn, and atta fashal + of covering unknov	?	ou conce المرما perty	inkno erning Age (shing	wn   lead-based  : <u>/ 0</u>    les or roof	paint haza / 火 5 , covering	ards). (application (application) (appl		
Item Y N Sasement Y N Sidewalks Sidewalks Walls / Fences Windows Other Structural Components Plumbing Systems Plumbing Systems Plumbing Systems Other Structural Components Previous Foundation Repairs Previous Roof Repairs Previous Previous Previous Property Setting Walls Other Structural Repairs Previous Foundation Repairs Previous Property Underground Storage Tanks Underground Storage Tanks Underground Storage Tanks Underground Flooding Into the Structures Previous Flooding Into the Property Wood Roof Active Infersition District Previous Flooding Into the Property Wood Roof Repairs Wood Roof Repairs Previous Flooding Into the Property Wood Roof Active Infersition Office Structure of Pits Uncated in Floodway (If yes, atlach TAR-1414) Wood Roof Active Infersition District Wood Roof Previous Flooding Into the Property Wood Roof Active Infersition Office Infersition Wood Roof Previous Flooding Into the Property	Are you (Selfer) aware are need of repair?y	of any of thesno If	e items listed yes, describe	in thi (attac	s Sec h add	tion 1 that a litional sheet	re not in v s if necess	vorking condition, that have ary):	defec	cts, or
Basement Ceilings Doors Driveways Driveways Electrical Systems Exterior Walls Exterior Walls Exterior Walls Floors Foundation / Slab(s) Interior Walls Ughling Fixtures Plumbing Systems Roof  Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition Y N Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Weste Ingroper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Lead-Based Paint or Lead-Based Pt. Hazards Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in 100-year Floodplain (If yes, attach TAR-1414) Previous Flooding into the Structures Vood Rot Active infestation of termites or other wood destroying insects (WDI) Previous Flooding on the Property Previous Flooding into the Structures Previous Flooding into the Structures Previous Flooding on the Property Previous Flooding into the Property Previous Flooding into the Structures Previous Flooding into the Property Previous Flooding into the Property Previous Flooding into the Property Previous Flooding into the Structures Previous Flooding into the Structures Previous Flooding into the Structures Previous Flood in Historic District  Floors Foundation / Slab(s) Walls Walls / Frences Windows Other Structural Components Windows Other Structural Repairs Radon Gas Sattling Previous Flood Previou	aware and No (N) if you	eller) aware u are not a	ware.)	cts or	malf	unctions in	any of the	following?: (Mark Yes (Y	) if yo	u are
Ceilings		YN			~~~~		YN		1	YN
Doors Driveways Driveways Electrical Systems Exterior Walls Exterior Walls Exterior Walls  Ext			-				V			6
Driveways Electrical Systems Exterior Walls  If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):  Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition  V N Aluminum Wiring Asbestos Components Previous Roof Repairs Previous Roof Repairs Previous Other Structural Repairs		V				s)	· V	Walls / Fences		2
Electrical Systems   Plumbing Systems   Roof   Roof	**************************************	V	p-1	-					17-7	1
Exterior Walls  If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):  Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition  V N Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Located in 100-year Floodplain (If yes, attach TAR-1414) Previous Flooding onto the Property Previous Flooding into the Structures Previous Flooding onto the Property Prev					**************		V	Other Structural Compone	nts	V
If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):  Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition  Aluminum Wiring  Asbestos Components  Diseased Trees: oak wilt  Endangered Species/Habitat on Property  Hazardous or Toxic Waste  Improper Drainage  Landfill  Lead-Based Paint or Lead-Based Pt. Hazards  Landfill  Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property  Improvements encroaching on others' property  Located in 100-year Floodplain  (If yes, attach TAR-1414)  Previous Flooding into the Structures  Previous Flooding into the Property  Located in Historic District  Water Penetration  Wetlands on Property  Previous Flooding into the Property  Previous Flooding onto the Property  Previous Flooding onto the Property  Located in Historic District		V		ig Sys	stems		2			
Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition Y N Aluminum Wiring Y N Asbestos Components Y Previous Foundation Repairs Previous Roof Repairs Previous Gepairs Previous Other Structural Repairs Previous Previous Other Structural Repairs Previous Conference of Repairs Previous Roof Repairs Previous Gooff Repairs Previous Other Structural Repairs Previous Gooff Repairs Previous Other Structural Repairs Previous Rooff Repairs Previous Gooff Repairs Previous Go	Exterior Walls	1	Roof		~					
Asbestos Components  Asbestos Components  Diseased Trees: oak wilt  Endangered Species/Habitat on Property  Fault Lines  Hazardous or Toxic Waste  Improper Drainage  Intermittent or Weather Springs  Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property  Improvements encroaching on others' property  Located in Floodway (If yes, attach TAR-1414)  Previous Flooding into the Structures  Previous Foundation Repairs  Previous Roof Repairs  Previous Other Structural Repairs  Radon Gas  Settling  Soil Movement  Subsurface Structure or Pits  Underground Storage Tanks  Unplatted Easements  Unrecorded Easements  Urrecorded Easements  Urrea-formaldehyde Insulation  Watar Penetration  Wetlands on Property  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous Flooding onto the Property  Located in Historic District  Value of Repairs  Previous Roof Repairs  Previous Roof Repairs  Previous Citer Structural Repairs  Radon Gas  Settling  Soil Movement  Underground Storage Tanks  Underground Storage Tanks  Unplatted Easements  Unrecorded Easements  Urrecorded Easements  Wetlands on Property  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous Flooding onto the Property  Previous Fires  Value of Repairs  Previous Roof Repairs  Previous Ctreatment of termites or WDI  Previous termite or WDI damage repaired  Previous Fires	you are not aware.)	ller) aware	of any of the		· · · · · · · · · · · · · · · · · · ·			es (Y) if you are aware an		· · · · · · · · · · · · · · · · · · ·
Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District  Previous Gother Structural Repairs Previous Gother Structural Repairs Previous Gother Structural Repairs Previous Cother Structural Repairs Previous Other Structural Repairs  Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unplatted Easements Unrea-formaldehyde Insulation Water Penetration Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires				Y	N	the state of the s				N
Diseased Trees: oak wilt  Endangered Species/Habitat on Property  Fault Lines  Hazardous or Toxic Waste  Intermittent or Weather Springs  Landfill  Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property  Improvements encroaching on others' property  Located in 100-year Floodplain  (If yes, attach TAR-1414)  Located in Floodway (If yes, attach TAR-1414)  Previous Previous Flooding into the Structures  Verevious Structure or Pits  Underground Storage Tanks  Underground Storage Tanks  Underground Storage Tanks  Unrecorded Easements  Urea-formaldehyde Insulation  Water Penetration  Wetlands on Property  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous Flooding onto the Property  Located in Historic District  Previous Fires					V					N
Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District  Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Unrea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous termite or WDI damage repaired Previous Fires		114			1					1
Fault Lines  Hazardous or Toxic Waste  Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property  Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District  Settling Soil Movement Vulver-formal denotes Vulned Fred Easements Unrecorded Easements Unrecorded Easements Unrecorded Easements Water Penetration Water Penetration Wetlands on Property Vood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous Fires		the same of the sa			1					1/
Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District  Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Unrecorded Easements Unrecorded Easements Water Penetration Wetlands on Property  Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous Flooding onto the Property Previous Flooding onto the Property Located in Historic District  Previous Fires		Jitat on Pro	perty		1	The state of the s	38			V
Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District  Subsurface Structure or Pits Underground Storage Tanks Underground Storage	Account of the contract of the	lo S			1					1
Intermittent or Weather Springs  Landfill  Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property  Improvements encroaching on others' property  Located in 100-year Floodplain  (If yes, attach TAR-1414)  Located in Floodway (If yes, attach TAR-1414)  Previous Flooding into the Structures  Previous Flooding onto the Property  Located in Historic District  Underground Storage Tanks  Unplatted Easements  Unrecorded Easements  Unrea-formaldehyde Insulation  Water Penetration  Wetlands on Property  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI  Previous Fires				-	1			a as Diša		V
Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414)  Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District  Unplatted Easements Unrecorded Easeme		nrings		17.7	/					V
Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414)  Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District  Unrecorded Easements Urrea-formaldehyde Insulation Water Penetration Wetlands on Property  Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous Flooding onto the Property Previous Fires		pringo								1
Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Vesent Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District  Urea-formaldehyde Insulation Water Penetration Wetlands on Property  Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous Flooding onto the Property Previous Fires		d-Based Pt	Hazards							14
Improvements encroaching on others' property  Located in 100-year Floodplain (If yes, attach TAR-1414)  Located in Floodway (If yes, attach TAR-1414)  Present Flood Ins. Coverage (If yes, attach TAR-1414)  Previous Flooding Into the Structures  Previous Flooding onto the Property  Located in Historic District  Water Penetration  Water Penetration  Wetlands on Property  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI  Previous Flooding onto the Property  Previous Fires		******	11020.00							
Located in 100-year Floodplain  (If yes, attach TAR-1414)  Located in Floodway (If yes, attach TAR-1414)  Present Flood Ins. Coverage (If yes, attach TAR-1414)  Previous Flooding into the Structures  Previous Flooding onto the Property  Located in Historic District  Wetlands on Property  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI  Previous termite or WDI damage repaired  Previous Fires						***************************************		modaum	-	1
(If yes, attach TAR-1414)  Located in Floodway (If yes, attach TAR-1414)  Present Flood Ins. Coverage (If yes, attach TAR-1414)  Previous Flooding into the Structures  Previous Flooding onto the Property  Located in Historic District  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI  Previous termite or WDI damage repaired  Previous Fires								tv		1
Located in Floodway (If yes, attach TAR-1414)  Present Flood Ins. Coverage (If yes, attach TAR-1414)  Previous Flooding into the Structures  Previous Flooding onto the Property  Located in Historic District  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI  Previous termite or WDI damage repaired  Previous Fires		-			1			-,		12
Present Flood Ins. Coverage (If yes, attach TAR-1414)  Previous Flooding Into the Structures Previous Flooding onto the Property Located in Historic District  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires			AR-1414)		2	Wood Rot				1.7
Previous Flooding Into the Structures Previous Flooding onto the Property Previous Flooding onto the Property Located in Historic District Previous Fires Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires					1				T de	V
Previous Flooding onto the Property  Located in Historic District  Previous termite or WDI damage repaired  Previous Fires			<u> </u>							
Located in Historic District Previous Fires	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~				1		White the same of			1
TAD 4400 co of 45					1			V		1
(TAR-1406) 02-01-18 Initialed by: Buyer:, and Seller:, Page 2 of 5	(TAR-1406) 02-01-18	Initia	led by: Buyer:		1	and Se	ller:	4	Page 2	of 5

#### 201 S Center Street Buffalo, TX 75831

Concerning the Property at

Historic P	roperty Designation		Termite or WDI damage needing repair	1
Previous Use of Premises for Manufacture of Methamphetamine		ture	Single Blockable Main Drain in Pool/Hot Tub/Spa*	
If the ans	wer to any of the items in Sec	ction 3 is yes, explain (a	attach additional sheets if necessary):	***************************************
which ha	. Are you (Seller) aware of s not been previously disc	any item, equipment, closed in this notice	suction entrapment hazard for an individual.  or system in or on the Property that is in ne yes  in o If yes, explain (attach additio	ed of repair,
necessary	/):			
Section 5 not aware Y N	Room additions, structural	modifications, or other	(Mark Yes (Y) if you are aware. Mark No (No alterations or repairs made without necessary ding codes in effect at the time.	
	Name of association: _ Manager's name: Fees or assessments a Any unpaid fees or ass	are: \$ essment for the Prope ore than one associatio	Phone:  per and are: mandatory rty? yes (\$ ) no n, provide information about the other association	
_ ✓	with others. If ves, complete	e the following:	s courts, walkways, or other) co-owned in undiv	
_1	Any notices of violations of Property.	f deed restrictions or g	overnmental ordinances affecting the condition of	or use of the
			indirectly affecting the Property. (Includes, but taxes.)	is not limited
/	Any death on the Property to the condition of the Prop		ns caused by: natural causes, suicide, or accide	int unrelated
_ 1	Any condition on the Prope	rty which materially aff	ects the health or safety of an individual.	
	hazards such as asbestos,	radon, lead-based paid cates or other docume	ntenance, made to the Property to remediate er nt, urea-formaldehyde, or mold. ntation identifying the extent of the remediation ( iation).	
	Any rainwater harvesting sy water supply as an auxiliary		roperty that is larger than 500 gallons and that u	ses a public
	The Property is located in a	propane gas system se	ervice area owned by a propane distribution syste	m retailer.
	Any portion of the Property	that is located in a gro	undwater conservation district or a subsidence d	istrict.
(TAR-1406)	) 02-01-18 Initialed	I by: Buyer:,	and Seller:,	Page 3 of 5

Concerning the Prop	erty at		201 S Center Buffalo, TX		
				sheets if necessary):	
	/				
Section 7. Within t regularly provide in	has has not atta he last 4 years, have spections and who a fine if yes, attach of	e you (Seller) i	eceived any writte	en inspection reports fr or otherwise permitted l	om persons who
Inspection Date	Туре	Name of Insp			No. of Pages
Fection 8. Check ar Homestead Wildlife Manag	roperty. A buyer shouny tax exemption(s) were ment	ld obtain inspec	tions from inspector	ion of the current conditions chosen by the buyer.  for the Property: Disabled Disabled Veteran	n or the
Other:	_	· ignoonton ar		Unknown	
Anon the Claim was	made ryes \( \bullet \) no	r yes, explain:		ned the proceeds to man	
equirements or Cha	Property have work pter 766 of the Healt ets if necessary):	h and Safetv C	ode?* unknown	n accordance with the	smoke detector nknown, explain.
installed in according performa	lance with the requiremance, location, and power	ents of the buildir er source require	ng code in effect in the ments, if you do not i	ellings to have working smoke e area in which the dwelling know the building code requ ficial for more information.	is located
tamily who will re- impairment from a the seller to instal	side in the dwelling is he licensed physician; and	earing-impaired; ( (3) within 10 days hearing-impaire	2) the buyer gives the after the effective dat d and specifies the lo	(1) the buyer or a member of a seller written evidence of a e, the buyer makes a written cations for installation. The problem detectors to install.	the hearing request for
eller acknowledges the broker(s), has instru	nat the statements in t ucted or influenced Se	his notice are tr ller to provide ir	ue to the best of Se accurate informatio	eller's belief and that no p n or to omit any material i	erson, including nformation.
ignature of Seller		Date	Signature of Seller		Date
inted Name:			-		
AR-1406) 02-01-18	Initialed by: Bu		and Seller:		Page 4 of 5

Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com

McDonnell

#### ADDITIONAL NOTICES TO BUYER:

- (1) The Texas Department of Public Safety maintains a database that the public may search, at no cost, to determine if registered sex offenders are located in certain zip code areas. To search the database, visit <a href="www.txdps.state.tx.us">www.txdps.state.tx.us</a>. For information concerning past criminal activity in certain areas or neighborhoods, contact the local police department.
- (2) If the Property is located in a coastal area that is seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the Property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information.
- (3) If the Property is located in a seacoast territory of this state designated as a catastrophe area by the Commissioner of the Texas Department of Insurance, the Property may be subject to additional requirements to obtain or continue windstorm and hail insurance. A certificate of compliance may be required for repairs or improvements to the Property. For more information, please review *Information Regarding Windstorm and Hail Insurance for Certain Properties* (TAR 2518) and contact the Texas Department of Insurance or the Texas Windstorm Insurance Association.
- (4) This Property may be located near a military installation and may be affected by high noise or air installation compatible use zones or other operations. Information relating to high noise and compatible use zones is available in the most recent Air Installation Compatible Use Zone Study or Joint Land Use Study prepared for a military installation and may be accessed on the Internet website of the military installation and of the county and any municipality in which the military installation is located.
- (5) If you are basing your offers on square footage, measurements, or boundaries, you should have those items independently measured to verify any reported information.

(6) The following providers currently provide service to the Property:	
Sewer: City of Buffalo Water: City of Ruffalo	phone #:
Cable:	phone #:phone #:
Trash: CITY of BuffALo  Natural Gas:	phone #:phone #:
Phone Company:	phone #:
Propane: N/A Internet: N/A	phone #:phone #:

(7) This Seller's Disclosure Notice was completed by Seller as of the date signed. The brokers have relied on this notice as true and correct and have no reason to believe it to be false or inaccurate. YOU ARE ENCOURAGED TO HAVE AN INSPECTOR OF YOUR CHOICE INSPECT THE PROPERTY.

The undersigned Buyer acknowledges receipt of the foregoing notice.

Signature of Buyer	Date	Signature of Buyer	Date
Printed Name:		Printed Name:	

(TAR-1406) 02-01-18

Page 5 of 5



### APPROVED BY THE TEXAS REAL ESTATE COMMISSION ADDENDUM FOR SELLER'S DISCLOSURE OF INFORMATION ON LEAD-BASED PAINT AND LEAD-BASED PAINT HAZARDS AS REQUIRED BY FEDERAL LAW

10-10-11

	ONCERNING THE PROPERTY AT	201 S Cer	iter Street	Buffalo
			(Street Address a	* /
	based paint that may place yo may produce permanent net behavioral problems, and impaiseller of any interest in reside based paint hazards from risk known lead-based paint hazards prior to purchase."  NOTICE: Inspector must be prosecuted by the property of the property	ung children at risk of prological damage, in red memory. Lead pointial real property is assessments or inspect. A risk assessment perly certified as required part of palint and property certified as required palint and property certified palint	I that such property may f developing lead poison including learning disabilities also poses a parequired to provide the ections in the seller's post or inspection for possible ired by federal law.  D-BASED PAINT HAZARD	esidential real property on which as present exposure to lead from leading. Lead poisoning in young children littles, reduced intelligence quotient, articular risk to pregnant women. The buyer with any information on lead-seession and notify the buyer of any e lead-paint hazards is recommended of the commended of the property (explain):
	(b) Seller has no actual 2. RECORDS AND REPORTS A	nowledge of lead-base	ed paint and/or lead-based	paint hazards in the Property.
	(a) Selfer has provided and/or lead-based pa	the purchaser with int hazards in the Prop	all available records and erty (list documents):	reports pertaining to lead-based paint
G.	(b) Seller has no repor Property. BUYER'S RIGHTS (check one box		ng to lead-based paint an	id/or lead-based paint hazards in the
	Buyer waives the opport lead-based paint or lead-t lead-based paint or lead-t lead-t lead-based paint or lead-t lead-based paint or lead-t lead-based paint or lead-t lead-based paint or lead-based paint le	unity to conduct a risk assed paint hazards. effective date of this ad-based paint or lead written notice within 1	contract, Buyer may have d-based paint hazards an	n of the Property for the presence of the Property inspected by inspectors e present, Buyer may terminate this date of this contract, and the earnest
D.	BUYER'S ACKNOWLEDGMENT (  1. Buyer has received copies	Buyer. check applicable boxes of all information listed	): above.	
E.	(a) provide Buyer with the fe addendum; (c) disclose any know records and reports to Buyer pe provide Buyer a period of up to	Erokers have informed the colors approved particles approved paint are read-based paint are read-based to days to have the	imphlet on lead poison nd/or lead-based paint ha I paint and/or lead-based Property inspected; and	ons under 42 U.S.C. 4852d to: ning prevention; (b) complete this zards in the Property; (d) deliver all if paint hazards in the Property; (e)
F.	adaption in at least 2 years lollor	/ing the sale, Brokers a /: The following perso	re aware of their responsib ons have reviewed the in rided is true and accurate.	ility to ensure compliance.  nformation above and certify, to the  Namell 31 March
Buy	ər	Date	Seller Tommy T McDonnell	Date DBA Therion Real Estate II, LLC
Buye	er	Date	Seller	Date 4:2:19
Othe	r Broker	Date	Listing Broker Elizabeth C. Ferrari	Date

(TAR 1906) 10-10-11

TREC No. OP-L