3/20/2019



City:

County: State: **GROVES** 

Inside City Limits

## TEXAS DEPARTMENT OF INSURANCE

Regulatory Policy Division - Windstorm Inspections Program (104-WS) 333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104 (800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

## Certificate of Compliance

Date of Construc	tion: 09-06-20	006			
Application ID:	438188 Certificate Number:		r: 380377		
Occupancy Type	Residential Building Type:		e: House		
Certificate Type:					
Certificate Detail:					
Certificate Date:					
Appointed Quali	fied Inspector/TDI I	nspector:			
Roof Partial	Re-Roof Octob	er 3, 2006 A <sub>l</sub>	ppointed Qualified Inspecto	r HURRICANE RITA/EXCLUDE	PATIO COVER
Location of Prop	erty to be Insured:				
•					
Street:					
Lot:					
Block: Trac	t or Addition:				
5400 BEAUMON	ΓAVE				

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 - 5.4011.

**JEFFERSON** 

**TEXAS** 

Inland I - INLAND I - 2003 IRC Intl Residential Code