



TEXAS DEPARTMENT OF INSURANCE

Regulatory Policy Division - Windstorm Inspections Program (104-WS)

333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104
(800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

Date of Construction: 07-21-2016
Application ID: 2052117 **Certificate Number:** 2052117
Occupancy Type: Residential **Building Type:** House

Certificate Type:

Certificate Detail:

Certificate Date:

Appointed Qualified Inspector/TDI Inspector:

Alterations Replace Door(s) September 13, 2016 Appointed Qualified Inspector Number of Doors: 1,
Location: 1 REAR

Location of Property to be Insured:

Street:

Lot:

Block: Tract or Addition:

5316 Lazymist Ct

City:

County:

State:

Dickinson GALVESTON TEXAS

Inside City Limits Inland I - Inland I - International Residential Code, 2006 Edition (Amended with 2006 Texas Revisions)

2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.