



# TEXAS DEPARTMENT OF INSURANCE

## Regulatory Policy Division - Windstorm Inspections Program (104-WS)

333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104  
(800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

## Certificate of Compliance WPI-8

**Date of Construction:** 07-25-2016

**Application ID:** 2055662      **Certificate Number:** 2055662

**Occupancy Type:** Residential      **Building Type:** House

### Certificate Type:

### Certificate Detail:

### Certificate Date:

### Appointed Qualified Inspector/TDI Inspector:

Alterations      Replace Window(s)      October 14, 2016      Appointed Qualified Inspector      Number of Windows:  
8, Location: 2 Front, 1 Left, 2 Rear, 3 Right

### Location of Property to be Insured:

### Street:

### Lot:

### Block:      Tract or Addition:

5316 Lazymist Ct

### City:

### County:

### State:

Dickinson      GALVESTON      TEXAS

Inside City Limits      Inland I - Inland I - International Residential Code, 2006 Edition (Amended with 2006 Texas Revisions)

2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.