99 S. Greenprint Circle  Being Lot One (1), in Blook Three (3), of WOODLANDS CREEKSIDE  PARK WEST SECTION SEVEN (7), an addition in Harris County, Texas, according to the map or plat thereof recorded In/under Film Code  No. 645246 of the Map/Plat Records of Harris County, Texas.				→ title guaranty company
LEGEND  O 5/8" ROD FOUND  O 1/2" ROD SET  O 1" PIPE FOUND  IS "X" FOUND/SET  GROW HAIL FOUND  FOR CORNER  COMODITIONER  PE COUPMENT  TE RANSFORMER  POOL  BERICK COLUMN  POWER POLE  A UNICEPROLE  A UNICEPROLE  OVERHEAD ELECTRIC  OVERHEAD ELECTRIC  OVERHEAD ELECTRIC  OVERHEAD ELECTRIC  CHAIN LINK  WOOD FENCE  CHAIN LINK  WOOD FENCE  OVERHEAD ELECTRIC  BROW FENCE  CHAIN LINK  WOOD FENCE  DOUBLE SIDED  WOOD FENCE  DOUBLE SIDED  WOOD FENCE  DOUBLE SIDED  DOUBLE SIDED  DOUBLE SIDED  WOOD FENCE  CONCRETE  EDGE OF GRAVEL  CONCRETE  COVERED AREA	20° CARAS  LOT 2  CMO 143.28°	12.E N 12	WOODD DECK  19.4  19.4  19.4  19.5  10.7  WOODD DECK  19.5  10.7  10.7  WOODD DECK  10.7  10.7  10.7  10.7  WOODD DECK  10.7	C COO C C C C C C C C C C C C C C C C C
		S. GREENPI	RINT CIRCL	E
NOTE: PROPERTY SUBJECT TO TERMS, CONDITIONS, AND EASEMENTS CONTAINED IN INSTRUMENT RECORDED IN FILM CODE NO. 645246, C.F. NOS. V-591732, 20120210476, 20120210838  NOTE: BEARINGS, EASEMENTS AND BUILDING LINES ARE BY RECORDED PLAT UNLESS OTHERWISE NOTED. FLOOD NOTE: According to the F.I.R.M. No. 48201C0070 L, this property does lie in Zone X and does not lie within the 100 year flood zone.  This survey is made in conjunction with the information provided by Stewart Title Company. Use of this survey by any other parties and/or for other purposes shall be at user's own risk and any loss resulting from other use shall not be the responsibility of the undersigned. This is to certify that I have on this date made a correct and accurate survey on the ground of the property. The plat hereon is a correct and accurate representation of the property lines and dimensions are as indicated; location and type of buildings are as shown; and EXCEPT AS SHOWN, there are no visible and apparent encroadments or profrusions on the ground.				
Acco	epted by: Purchaser	Drawn By:JA  Soale:1" = 30'  Date:03/21/15  GF No.:1520191633/88=00424935		35 66 68800

Job No. 1503498

JOSH CONNALLY R.P.L.S. NO. 5766

Purchaser