





SELLER'S DISCLOSURE NOTICE

NCERNING THE PROPERTY AT	8731 Sunny Gallop Dr, Tomball, TX 77375 (Street Address and City)		
	ANY INSPECTIONS OR WARRANTIES THE	OF THE PROPERTY AS OF THE DATE SIGNED BY E PURCHASER MAY WISH TO OBTAIN. IT IS NOT	
ler $\ \square$ is $\ ec{oldsymbol{arepsilon}}$ is not occupying the Pr	operty. If unoccupied, how long since S	Never Seller has occupied the Property? Occupied	
The Property has the items checked I	below [Write Yes (Y), No (N), or Unknown	n (U)]:	
γRange	N Oven	YMicrowave	
γDishwasher	UTrash Compactor	U Disposal	
Y Washer/Dryer Hookups	U Window Screens	U Rain Gutters	
Y Security System	U Fire Detection Equipment	U Intercom System	
	YSmoke Detector		
yer is aware that security system es not convey with sale of home.	Smoke Detector-Hearing Impair	red	
ikset 914 lock will be replaced	U Carbon Monoxide Alarm		
pon close.	N_Emergency Escape Ladder(s)		
TV Antenna	Cable TV Wiring	Satellite Dish	
Y Ceiling Fan(s)	UAttic Fan(s)	YExhaust Fan(s)	
Y Central A/C	Y Central Heating	N_Wall/Window Air Conditioning	
Y_Plumbing System	NSeptic System	UPublic Sewer System	
Y Patio/Decking	N_Outdoor Grill	Y Fences	
NPool	N Sauna	N_SpaN_Hot Tub	
N Pool Equipment	N Pool Heater	U Automatic Lawn Sprinkler System	
Fireplace(s) & Chimney N (Wood burning)		Fireplace(s) & Chimney N (Mock)	
Υ Natural Gas Lines		U Gas Fixtures	
N Liquid Propane Gas	N_LP Community (Captive)	N LP on Property	
Garage: Y Attached	N Not Attached	N Carport	
Garage Door Opener(s):	γ Electronic	U Control(s)	
Water Heater:	Y Gas	N Electric	
Water Supply: N_City		 Co-op	
,	nknown Age:	8 to 10 years (approx.)	
	above items that are not in working cor Unknown. If yes, then describe. (Attacl	ndition, that have known defects, or that are in hadditional sheets if necessary):	

oes the property have working smoke detectors instal	(Street Address and	omball, TX 77375 Page 2 8-7-2017 d City)	
		o this question is no or unknown, explai	
Seller has never occupied this property. Seller encourage verify all information relating to this property.	es Buyer to have their own	inspections performed and	
chapter 766 of the Health and Safety Code requires or installed in accordance with the requirements of the brocluding performance, location, and power source reception for the source of the source in your area, you may check unknown above or conception of the hearing as seller to install smoke detectors for the hearing impaired; (2) the burlicensed physician; and (3) within 10 days after the effection of the hearing impaired and specifies the cost of installing the smoke detectors and which branches	uilding code in effect in juirements. If you do no ontact your local building g impaired if: (1) the buy yer gives the seller writted ective date, the buyer main he locations for the instal	the area in which the dwelling is located to know the building code requirements in official for more information. A buyer mayer or a member of the buyer's family when evidence of the hearing impairment from the saw written request for the seller to installation. The parties may agree who will be	
re you (Seller) aware of any known defects/malfunction you are not aware.	,	·	
N Interior Walls N Ceiling	js .	N Floors	
N Exterior Walls N Doors		NWindows	
N Roof N Found	ation/Slab(s)	NSidewalks	
N Walls/Fences N Drivey	<i>r</i> ays	N_Intercom System	
N Plumbing/Sewers/Septics N Electri	cal Systems	NLighting Fixtures	
the answer to any of the above is yes, explain. (Attach Seller has never occupied this property. Seller encourage verify all information relating to this property.		•	
re you (Seller) aware of any of the following conditions	? Write Yes (Y) if you are a	ware, write No (N) if you are not aware.	
N Active Termites (includes wood destroying insects) N Previous Stru	N Previous Structural or Roof Repair	
N Active Termites (includes wood destroying insects		uctural or Root Repair	
N Termite or Wood Rot Damage Needing Repair	Hazardous o	uctural or Roof Repair or Toxic Waste	
	N Asbestos Co	or Toxic Waste	
N Termite or Wood Rot Damage Needing Repair	Asbestos Co	or Toxic Waste	
N Termite or Wood Rot Damage Needing Repair Previous Termite Damage	Asbestos Co	or Toxic Waste mponents	
N Previous Termite Damage Previous Termite Damage Previous Termite Treatment	N Urea-formale	or Toxic Waste mponents dehyde Insulation	
N Termite or Wood Rot Damage Needing Repair N Previous Termite Damage N Previous Termite Treatment N Previous Flooding	N Asbestos Co	r Toxic Waste mponents dehyde Insulation Paint	
N Termite or Wood Rot Damage Needing Repair N Previous Termite Damage N Previous Termite Treatment N Previous Flooding N Improper Drainage	N Asbestos Co N Urea-formalo N Radon Gas N Lead Based F	r Toxic Waste mponents dehyde Insulation Paint Viring	
N Termite or Wood Rot Damage Needing Repair N Previous Termite Damage N Previous Termite Treatment N Previous Flooding N Improper Drainage N Water Penetration	N Asbestos Co N Urea-formalo N Radon Gas N Lead Based F	r Toxic Waste mponents dehyde Insulation Paint Viring	
N Termite or Wood Rot Damage Needing Repair N Previous Termite Damage N Previous Termite Treatment N Previous Flooding N Improper Drainage N Water Penetration N Located in 100-Year Floodplain	N Asbestos Col N Urea-formalo N Radon Gas N Lead Based F N Aluminum W N Previous Fire N Unplatted Ea	r Toxic Waste mponents dehyde Insulation Paint Viring es asements Structure or Pits	
N Termite or Wood Rot Damage Needing Repair N Previous Termite Damage N Previous Termite Treatment N Previous Flooding N Improper Drainage N Water Penetration N Located in 100-Year Floodplain N Present Flood Insurance Coverage	N Asbestos Col N Urea-formalo N Radon Gas N Lead Based F N Aluminum W N Previous Fire N Unplatted Ea	r Toxic Waste mponents dehyde Insulation Paint Viring es asements Structure or Pits e of Premises for Manufacture of	
N Termite or Wood Rot Damage Needing Repair N Previous Termite Damage N Previous Termite Treatment N Previous Flooding N Improper Drainage N Water Penetration N Located in 100-Year Floodplain N Present Flood Insurance Coverage N Landfill, Settling, Soil Movement, Fault Lines	N Asbestos Color N Urea-formalo N Radon Gas N Lead Based F N Aluminum W N Previous Fire N Unplatted Ea N Subsurface S Previous Use N Methamphe	r Toxic Waste mponents dehyde Insulation Paint Viring es asements Structure or Pits e of Premises for Manufacture of tamine	

Sell	er's Disclosure Notice Concerning the Property at8731 Sunny Gallop Dr, Tomball, TX 77375Page 3 8-7-2017			
5.	Are you (Seller) aware of any item, equipment, or system in or on the Property that is in need of repair? Yes (if you are aware) No (if you are not aware) If yes, explain. (Attach additional sheets if necessary):			
	Seller has never occupied this property. Seller encourages Buyer to have their own inspections performed and verify all information relating to this property.			
6.	Are you (Seller) aware of any of the following? Write Yes (Y) if you are aware, write No (N) if you are not aware.			
	Room additions, structural modifications, or other alterations or repairs made without necessary permits or not in compliance with building codes in effect at that time.			
	Y Homeowners' Association or maintenance fees or assessments.			
	Any "common area" (facilities such as pools, tennis courts, walkways, or other areas) co-owned in undivided interest with others.			
	Any notices of violations of deed restrictions or governmental ordinances affecting the condition or use of the N Property.			
	Any lawsuits directly or indirectly affecting the Property.			
	N Any condition on the Property which materially affects the physical health or safety of an individual.			
	Any rainwater harvesting system located on the property that is larger than 500 gallons and that uses a public water supply as an auxiliary water source.			
	Υ Any portion of the property that is located in a groundwater conservation district or a subsidence district.			
	If the answer to any of the above is yes, explain. (Attach additional sheets if necessary): HOA: Saddlebrook Ranch CA, Inc C/O Moonlite Property Management, Inc - \$490 Annual assessment, \$150 disclosure fee, \$125 transfer fee, \$100 capital improvement, \$100 Maintenance quote See HOA Addendum Property is located in Harris-Galveston Subsidence District Seller has never occupied this property. Seller encourages Buyer to have their own inspections performed and verify all information relating to this property.			
7.				
8.	This property may be located near a military installation and may be affected by high noise or air installation compatible use zones or other operations. Information relating to high noise and compatible use zones is available in the most recent Air Installation Compatible Use Zone Study or Joint Land Use Study prepared for a military installation and may be accessed on the Internet website of the military installation and of the county and any municipality in which the military installation is located.			
1-	authorized signer on behalf of Opendoor Property N LLC 50n Cline 05/30/2019			
ignati	JON CLURE 05/30/2019 ure of Seller Date Signature of Seller Date			
The u	indersigned purchaser hereby acknowledges receipt of the foregoing notice.			
Signatu	ure of Purchaser Date Signature of Purchaser Date			