

Texas Department of Insurance

Regulatory Policy Division - Windstorm Inspections Program (104-WS) 333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104 (800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

Date of 0	Constructio	n : 03-05-2	2019	
Applicat	ion ID:	2150761	Certificate Number	: 2150761
Occupar	cy Type:	Residential	Building Type:	House
Certificate Type:				
Certificate Detail:				
Certificate Date:				
Appointed Qualified Inspector/TDI Inspector:				
New	New (Enti	re Building)	May 29, 2019	Appointed Qualified Inspector
Location of Property to be Insured:				
Street:				
Lot:				
Block:	Tract o	r Addition:		
5822 Pe	can Park			
City:				
County				
State:				
Hitchcoo	k Gal	veston TE	XAS	
Inside C	ity Limits	Inland I - INL	LAND I - International	Residential Code, 2006 Edition (Amended with 2006 Texas Revisions)

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the ongoing improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.