

Inside City Limits

## TEXAS DEPARTMENT OF INSURANCE

Regulatory Policy Division - Windstorm Inspections Program (104-WS) 333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104 (800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

## Certificate of Compliance WPI-8

				VVPI-8		
Date of	Construction:	04-15-20	19			
Applica	tion ID: 2	154209 <b>C</b>	ertificate Number:	2154209		
Occupa	incy Type:	Residential	Building Type:	House		
Certificate	Туре:					
Certificate	Detail:					
Certificate	Date:					
Appoint	ted Qualified In	spector/TDI In	spector:			
New	New (Entire E	Building) .	July 24, 2019	Appointed Qualified Inspector		
Locatio	n of Property to	o be Insured:				
Street:						
Lot:						
Block:	Block: Tract or Addition:					
5814 PE	ECAN PARK DR	IVE				
City:						
County:	:					
State:						
Hitchcoo	ck Galvest	on TEXA	S			

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the ongoing improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.

Inland I - INLAND I - International Residential Code, 2006 Edition (Amended with 2006 Texas Revisions)