

Texas Department of Insurance

Regulatory Policy Division - Windstorm Inspections Program (104-WS) 333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104 (800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

			\	NPI-8 '	
Date of Construction	n: 10-	07-2008			
Application ID:	515079	Certificate Nun	nber:	455809	
Occupancy Type:	Resider	ntial Building	Туре:	House	
Certificate Type:					
Certificate Detail:					
Certificate Date:					
Appointed Qualified	Inspector/	TDI Inspector:			
Roof Entire Re-F	Roof N	ovember 10, 2008	Appo	pinted Qualified Inspecto	or HURRICANE IKE
Location of Property	y to be Insu	ıred:			
Street:					
Lot:					
Block: Tract or	Addition:				
1807 9TH STREET					
City:					
County:					
State:					
WINNIE CHAM	BERS	TEXAS			
Inside City Limits	Inland I -	INI AND L. 2006 IR	C Intl Re	sidential Code	

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.