TEXAS REALTORS

SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2018

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

CONCERNING THE P	RC	PE	ER"	ΓΥ	AT_	2	5012	le	E,L	20	76	Λd	کا	Trai	11	<u>۲.</u>	,5	erin	<u>a</u> .	<u></u> 11	- 386
CONCERNING THE PROPERTY AT 3012 & E. Lequals Trail Dr., Spring 71381, THIS NOTICE IS A DISCLOSURE OF SELLER'S KNOWLEDGE OF THE CONDITION OF THE PROPERTY AS OF THE DATE SIGNED BY SELLER AND IS NOT A SUBSTITUTE FOR ANY INSPECTIONS OR WARRANTIES THE BUYER MAY WISH TO OBTAIN. IT IS NOT A WARRANTY OF ANY KIND BY SELLER, SELLER'S AGENTS, OR ANY OTHER AGENT.									Υ												
Seller is □ is not the Property? □ 10/14/	0 200	CCL 5	іру	ing	the	Pro	perty	. If u	noccupie (&	ed (app	by rox	Sel ima	ller ate	r), how lo date) o	ng s or	ince	Selle never	er has r occu	occi	aiqu H	ed ne
Section 1. The Prope This notice does not es	rty tab	ha lish	is t	: he e ite	i te n ms t	ns r o be	narke oonv	ed bel eyed.	ow: (M The con	ark trac	Ye tw	e s (' ill de	Y), ete	, No (N), ermine whi	or U	nkn ems	own will &	(U).) will not	conv	∕ey.	
Item	Υ	N	U		Iten	า		·		ΤΫ́	N	U] [Item		····			Υ	N	П
Cable TV Wiring				-			Propa	ne Ga		TÓ				Pump: [T SIJ	mn	Па	rinder	Ė	X	
	Ø			_							_			Rain Gu			<u> </u>	maci	Z		
					-LP Community (Captive) -LP on Property			盲	_	饲		Range/S									
Cooktop	Ø				Hot							同		Roof/Att					X		
Dishwasher	ď,			_			n Sys	tem						Sauna						図	
Disposal	D			_	Mici					X				Smoke	Dete	ctor		•	図		
Emergency Escape Ladder(s)		Q			Outdoor Grill				Ø			Smoke Impaired	Dete			earing		Ø			
Exhaust Fans	B			F	Patio/Decking			K				Spa						M	П		
Fences		Ó						沤				Trash C	omp	acto	r			×			
Fire Detection Equip.	Ø,			Г					×		Ī	TV Ante			-		卤				
French Drain											Ī	Washer		er Ho	ookur						
		ZÍ.			Poo	Ma	aint. A	cces	sories		M			Window							
Natural Gas Lines		A		L	Poo	He	ater				Ž			Public S	ewe	Sy	stem				
Item				v	N	Ų		^	ddition	al I	nfe	`rm		lon					,		_
Central A/C				M			Mel		gas					of units:	3						_
Evaporative Coolers					N				units:	·	Hai	HIDE	2 Ι (oi ariita.	<i></i>					—	\dashv
Wall/Window AC Units				d	Ĭ				units:												-
Attic Fan(s)					Ø	_			cribe:										- ·		\dashv
Central Heat				囡	_				Zygas	1	nur	mbe		of units:	i			·			\dashv
Other Heat				X			if ves	s desc	cribe: 4	1672		hr	CA	electric	,	- .		-			\dashv
Oven		-		M			num	ber of	ovens.	1	(9	- (1	electric	П	ias	□ of l	her			\dashv
Fireplace & Chimney				M			DLW	ood	M gas I	oas	: F	1 m	oc	k 🔲 oth	er:	,		1011			-
Carport				X			🔀 at	tache	d 🗖 no	t at	tac	hec	d								7
Garage				N					d 🗖 no								***				1
Garage Door Openers									units:					umber of	remo	otes	· 0).)		_	
Satellite Dish & Controls	3			`Z					leas					DICH			WOV	24			1
Security System				X					☐ leas												7
Solar Panels							☐ ov	vned	□,leas	ed 1	ror	n									7
Vater Heater				区					⊠gas						num	ber	of ur	its: 🖏			
Water Softener					K				leas												
Other Leased Item(s)							if yes														
(TXR-1406) 02-01-18		lni	tiale	ed b	y: Bı	ıyer:			ar	nd S	elle	r: 📆	か		7			Pa	ae 1	of 5	_

	Concerning the Property at 30126 E Legends Trail Dr., Spring TX 77386								
TUnderground Lawn Sprinkler - 1/11/11 11 11 18	Underground Lawn Sprinkler 🗓 🗆 🖾 automatic 🗀 manual areas covered: 🚾 🔥								
Septic / On-Site Sewer Facility									
Water supply provided by: City Well MUD Co-op Unknown Other: AC A-									
Was the Property built before 1978? ☐ yes ☑ no ☐ unknown									
(If yes, complete, sign, and attach TXR-1906 concerning lead-based paint hazards).									
Roof Type: HTD Still GIES Age: 2005 / 14 yes/> (approximate)									
Is there an overlay roof covering on the Property (shingles or roof covering placed over existing shingles or roof									
covering)? ☐ yes ☒ no ☐ unknown	J. 1.	Ji iii igi	co or root concerning placed over existing stilligle	:5 UI	1001				
Are you (Seller) aware of any of the items in	sted i	ın this	Section 1 that are not in working condition, the	nat I	nave				
delects, or are need of repair? \(\sigma\) yes \(\mu^2\)-no	If y∈	es, de	scribe (attach additional sheets if necessary):						
•									
Section 2. Are you (Seller) aware of any	defe	cts o	r malfunctions in any of the following?: (M	ark	Yes				
(Y) if you are aware and No (N) if you are n	ot av	vare.)							
Italian IV III									
Item Y N Item			Y N Item	Y	N				
Basement			□ ☐ Sidewalks		A				
Ceilings		ab(s)			Æ				
Doors			□ ☑ Windows		N.				
Driveways Lighting F			Other Structural Components		<u> </u>				
Electrical Systems D D Plumbing	Syste	ems							
Exterior Walls 🔲 🖾 Roof									
Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)									
Condition	Υ	N,	O - u disti - u						
			I LONGITION	v	N				
Aluminum vvirina	1	X	Condition Previous Foundation Repairs		N				
Aluminum Wiring Asbestos Components	<u>D</u> N		Previous Foundation Repairs		区				
Asbestos Components		図	Previous Foundation Repairs Previous Roof Repairs		图图				
Asbestos Components Diseased Trees: oak wilt .		M	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs		区区区				
Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property			Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas		医				
Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines		N N N	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling		医 医				
Asbestos Components Diseased Trees: oak wilt for Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste		的 図 図 図 図 図 図 の の の の の の の の の の の の の	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement		N N N N N N N N N N N N N N N N N N N				
Asbestos Components Diseased Trees: oak wilt formula endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage		以 成 図 図 図 図 図 図 図 図 の の の の の の の の の の の の の	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits		阿阿阿阿阿阿				
Asbestos Components Diseased Trees: oak wilt frame in a control oak wilt frame in a co			Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks		印度阿瓦西西西西				
Asbestos Components Diseased Trees: oak wilt for Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill		y m chá a a a a	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements		ACT BE COM BE				
Asbestos Components Diseased Trees: oak wilt for Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards		MAN WAR MAN	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements		MACTOR MANDED				
Asbestos Components Diseased Trees: oak wilt cendangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property		医过过回过过时国国 国	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation		四国国际国际国际国际 国				
Asbestos Components Diseased Trees: oak wilt for Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property		A K W W W W K K B B K	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation Water Penetration		deres de la				
Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain		医过过回过过时国国 国	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation		C C C C C C C C C C C C C C C C C C C				
Asbestos Components Diseased Trees: oak wilt cendangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TXR-1414)		区 超过过过过过过过过	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation Water Penetration Wetlands on Property		d d d d d d d d d d d d d d d d d d d				
Asbestos Components Diseased Trees: oak wilt cendangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TXR-1414) Located in Floodway (If yes, attach TXR-1414)		以 医 每回回回回回回回回回回回回回回回回回回回回回回回回回回回回回回回回回回回	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot		प्रवाद्य विषय विषय विषय विषय				
Asbestos Components Diseased Trees: oak wilt centered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TXR-1414) Located in Floodway (If yes, attach TXR-1414) Present Flood Ins. Coverage		区 超过过过过过过过过	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood		d d d d d d d d d d d d d d d d d d d				
Asbestos Components Diseased Trees: oak wilt centered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TXR-1414) Located In Floodway (If yes, attach TXR-1414) Present Flood Ins. Coverage (If yes, attach TXR-1414)		G G B B B B B B B B B B B B B B B B B B	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI)		ष प्रवाद्यात्रात्रात्रात्रात्रात्रात्रात्रात्रात्र				
Asbestos Components Diseased Trees: oak wilt cendangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TXR-1414) Located in Floodway (If yes, attach TXR-1414) Present Flood Ins. Coverage (If yes, attach TXR-1414) Previous Flooding into the Structures		ष द प छ खख्षेप्रणणेष्ट्रेष्ठाष्ट्रष्ट्र	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI		व व्यवविष्यात्रवात्रवात्रवात्रवात्रवात्रवात्रवात्रव				
Asbestos Components Diseased Trees: oak wilt cendangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TXR-1414) Located in Floodway (If yes, attach TXR-1414) Present Flood Ins. Coverage (If yes, attach TXR-1414) Previous Flooding into the Structures Previous Flooding onto the Property		BE GREEN WRENTER	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or WDI damage repaired		ष्व क्षेत्रक्षिक्षिक्षेत्रक्षेत्रक्षेत्रक्षेत्र				
Asbestos Components Diseased Trees: oak wilt cendangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TXR-1414) Located in Floodway (If yes, attach TXR-1414) Present Flood Ins. Coverage (If yes, attach TXR-1414) Previous Flooding into the Structures		ष द प छ खख्षेप्रणणेष्ट्रेष्ठाष्ट्रष्ट्र	Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI		व व्यवविष्यात्रवात्रवात्रवात्रवात्रवात्रवात्रवात्रव				

Concerni	ng the Property at 30126 E Legends Tr Dr., Spring TX 17386
ľ	s Use of Premises for Manufacture Single Blockable Main Drain in Pool/Hot Tub/Spa*
If the ar	swer to any of the items in Section 3 is yes, explain (attach additional sheets if necessary):
	A single blockable main drain may cause a suction entrapment hazard for an individual.
of repa	4. Are you (Seller) aware of any item, equipment, or system in or on the Property that is in need ir, which has not been previously disclosed in this notice? ☐ yes ☐ no If yes, explain (attach all sheets if necessary):
Section you are	5. Are you (Seller) aware of any of the following (Mark Yes (Y) if you are aware. Mark No (N) if not aware.)
Y N	Room additions, structural modifications, or other alterations or repairs made without necessary permits, with unresolved permits, or not in compliance with building codes in effect at the time.
	Homeowners' associations or maintenance fees or assessments. If yes, complete the following: Name of association: CONMONTY ASSET NOWNERS INC. Manager's name: Phone: 18 - 152 1155 Fees or assessments are: \$ 925 per yes and are: 2 mandatory 0 voluntary Any unpaid fees or assessment for the Property? 0 yes (\$) Inc. If the Property is in more than one association, provide information about the other associations below or attach information to this notice.
o g	Any common area (facilities such as pools, tennis courts, walkways, or other) co-owned in undivided interest with others. If yes, complete the following: Any optional user fees for common facilities charged? yes no If yes, describe:
	Any notices of violations of deed restrictions or governmental ordinances affecting the condition or use of the Property.
	Any lawsuits or other legal proceedings directly or indirectly affecting the Property. (Includes, but is not limited to: divorce, foreclosure, heirship, bankruptcy, and taxes.)
	Any death on the Property except for those deaths caused by: natural causes, suicide, or accident unrelated to the condition of the Property.
	Any condition on the Property which materially affects the health or safety of an individual.
	Any repairs or treatments, other than routine maintenance, made to the Property to remediate environmental hazards such as asbestos, radon, lead-based paint, urea-formaldehyde, or mold. If yes, attach any certificates or other documentation identifying the extent of the remediation (for example, certificate of mold remediation or other remediation).
	Any rainwater harvesting system located on the Property that is larger than 500 gallons and that uses a public water supply as an auxiliary water source.
	The Property is located in a propane gas system service area owned by a propane distribution system retailer.
JØ	Any portion of the Property that is located in a groundwater conservation district or a subsidence district.
(TXR-1406) 02-01-18 Initialed by: Buyer: and Seller: Bu, Page 3 of 5

Concerning the Prop	erty at <u>30124</u>	e E Legend	STrail DI	Spring TX	<u>77386</u>
		Section 5 is yes, ex			
-					
Section 6. Sell	er 🔏 has 🗆 has	not attached a s	urvey of the Prop	erty.	
Section 7. With persons who re	nin the last 4 ye egularly provide	ars, have you (S	eller) received arwho are either lic	ny written inspec censed as inspec	ction reports from ctors or otherwise te the following:
Inspection Date	Туре	· Name of Inspec	tor		No. of Pages
Note: A buyer sh		ne above-cited repoi l'obtain inspections i			tion of the Property.
冷 Homestead		otion(s) which you Senior Citizen	Disa	bled	perty:
☐ VVIIdilīte IVIai ☐ Other:	nagement	☐ Agricultural	∐ Disa □ Unk	ıbled Veteran nown	
	you (Seller) e	ver filed a claim			th any insurance
•	-	was socied was	anda for a alaba	. for donor t.	Alex December 15
∍xample, an ins≀	ırance claim or a	settlement or awa	ard in a legal prod	eeding) and not i	the Property (for used the proceeds
to make the repa	iirs for which the	claim was made?	☐ yes ⊿⊠ no If y	es, explain:	
detector require	ments of Chapte	iave working smol r 766 of the Health onal sheets if neces	and Safety Code	alled in accordance?* □ unknown	ce with the smoke □ no ⊠yes. If no
installed in acco including perfom	rdance with the requance, location, and p	ty Code requires one-fa irements of the buildin ower source requirement above or contact your lo	g code in effect in the nts. If you do not know	e area in which the d the building code req	welling is located,
family who will i impairment from seller to install s	reside in the dwelling a licensed physician; moke detectors for th	smoke detectors for the g is hearing-impaired; (and (3) within 10 days a e hearing-impaired and smoke detectors and wh	the buyer gives the fter the effective date, a specifies the locations	e seller written eviden the buyer makes a writ s for installation. The j	ce of the hearing ten request for the
Seller acknowledgincluding the brokmaterial information	(er(s), has instruc	nents in this notice of the contract of the co	are true to the besi Seller to provide in	t of Seller's belief a naccurate informat	and that no person, tion or to omit any
Bell Signature of Selle	mi	7.31-19 Date	Signature of So	eller	7-/31/19 Date
Printed Name:) i NSUi	Printed Name:		24.0
(TXR-1406) 02-01-18	Initialed b		and Seller: (*)	M.G	Page 4 of 5

ADDITIONAL NOTICES TO BUYER:

- (1) The Texas Department of Public Safety maintains a database that the public may search, at no cost, to determine if registered sex offenders are located in certain zip code areas. To search the database, visit www.txdps.state.tx.us. For information concerning past criminal activity in certain areas or neighborhoods. contact the local police department.
- (2) If the Property is located in a coastal area that is seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the Property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information.
- (3) If the Property is located in a seacoast territory of this state designated as a catastrophe area by the Commissioner of the Texas Department of Insurance, the Property may be subject to additional requirements to obtain or continue windstorm and hail insurance. A certificate of compliance may be required for repairs or improvements to the Property. For more information, please review Information Regarding Windstorm and Hail Insurance for Certain Properties (TXR 2518) and contact the Texas Department of Insurance or the Texas Windstorm Insurance Association.
- (4) This Property may be located near a military installation and may be affected by high noise or air installation compatible use zones or other operations. Information relating to high noise and compatible use zones is available in the most recent Air Installation Compatible Use Zone Study or Joint Land Use Study prepared for a military installation and may be accessed on the Internet website of the military installation and of the county and any municipality in which the military installation is located.
- (5) If you are basing your offers on square footage, measurements, or boundaries, you should have those

items independently measured to verify any reporter	ed information.
(6) The following providers currently provide service to	
Electric: RELIANT	phone #: 1-866 - 222 7100
Sewer: AERONGC	phone #: 936 - 3218191
Water: AQUA TX	phone #: 1-877 - 987 2782
Cable: DISH & XFINITI	phone #: 1-800 - 8949131 /1-800 934648
Trash: <u>REPUBLIC SERVICE</u>	phone #: 713 - 635 6666
Natural Gas: CENTER POINT	phone #: 1-877 - 711 208 2
Phone Company: ATT	phone #:
Propane: NO NE	phone #:
Internet: XFIMTI	phone #: 1-800 9346489
	Seller as of the date signed. The brokers have relied on son to believe it to be false or inaccurate. YOU ARE DUR CHOICE INSPECT THE PROPERTY.
The undersigned Buyer acknowledges receipt of the fo	regoing notice.
Signature of Buyer Date	Signature of Buyer Date
Printed Name:	Printed Name:

(TXR-1406) 02-01-18

Page 5 of 5