Throughout Home

- 1. All doors have new satin nickel lever style door hardware and satin nickel hinges
- 2. All electrical face plates updated to white

Level 01

- 1. Foyer
 - a. New hardwood flooring
 - b. New hardwood stairs
 - c. New 8in baseboards
 - d. New chandelier
 - e. Walls painted, ballustrade refinished
- 2. Office
 - a. New hardwood flooring
 - b. New 8in baseboard
 - c. Walls and millwork painted
 - d. New ceiling fixture
- 3. Dining Room
 - a. New chandelier
 - b. Central ceiling speakers added with local volume control
 - c. Walls painted
- 4. Living Room
 - a. New hardwood flooring
 - b. New 8in baseboard
 - c. New built-in entertainment center
 - d. Wall sconces added above entertainment center
 - e. New ceiling fan
 - f. New tile on fireplace
 - g. Walls and millwork painted
- 5. Kitchen
 - a. New hardwood flooring
 - b. New 8in baseboard
 - c. New 4x10 kitchen island
 - d. New quartz countertops and ss sink
 - e. New subway tile backsplash
 - f. New ss appliances including wall oven, microwave, and range.
 - g. SS Range hood added and vented to outside
 - h. Walls and millwork painted
 - i. New chandeliers and pendants
- 6. ½ Bath
 - a. New hardwood flooring
 - b. New 8in baseboard
 - c. New vanity and mirror
 - d. New light fixture

Level 02

- 1. Foyer
 - a. New carpet
 - b. New baseboard
 - c. New can lights
 - d. Walls painted
- 2. MA Bed
 - a. New hardwood flooring
 - b. New baseboard
 - c. Can lights added
 - d. New ceiling fan
 - e. Built-in dresser
 - f. Walls painted
- 3. MA Bath
 - a. New floor tile in bath and closet with matching tiled shower
 - b. New frameless shower glass with satin nickel ladder style hardware
 - c. New vanity, vanity top, faucets, and mirror frame
 - d. New glass sliding doors into closet
 - e. Walls and millwork painted
- 4. Front Bedroom
 - a. New carpet
 - b. New baseboard
 - c. Walls and millwork painted
- 5. Rear Bedroom
 - a. New carpet
 - b. New baseboard
 - c. Walls and millwork painted
- 6. Bonus Room
 - a. New carpet
 - b. New baseboard
 - c. Walls and millwork painted
- 7. Full Bath
 - a. New framed mirror
 - b. Walls painted