# Remodeling Details: 11510 Del Monte Dr.

# Plumbing:

- Met Plumbing, 1005 Airline Dr Suite A, Katy, TX 77493, 281-599-3336
- All new western toilets. 2 year warranty. Toilets have glazed p-traps for better performance and a 3' flush valve. Drain lines and sewer system is in good condition.
- All new pipes: Replace all the galvanized pipe in the home, Uponor Pex and Brass fittings were used inside walls and attic, 1/4 turn emergency shut off valve was installed as well, new supply line to every fixture, new ice maker box and washer machine box was installed. 10 year transferable warranty. See attachment from Met Plumbing.

## Air Conditioning:

- Courtesy Air Conditioning & Heating, Inc., 3780 Tanglewild Ste 101, Houston, TX 77063, 281-496-9450 Contact: Mike Roach (he is excellent, btw!!)
- 7-18-19: Replaced upstairs AC condenser and coil, new condenser pad, replaced drain pan, added aqua guard switch, new supply plenum, and replaced thermostat
- 9-25-18: Replaced downstairs AC, coil and thermostat

# <u>Pool:</u>

- The Pool Depot, Chris, 11211 Richmond Avenue, Suite B104, Houston, TX 77082, 281.484.8840 Office
- Pool equipment: New pump and Filter repair
- They clean the pool weekly for ~\$195 per month

# Landscaping:

- Daryl Brooks: 936-224-0858
- All trees trimmed
- New mulch, New St. Augustine grass in yard
- Weekly grass serviced by Lorenzo, 832-863-1108

# Foundation Repair:

- Allied Foundation Specialists, Inc. 4906 Luella Ave, Deer Park TX 77536, 281-479-4760
- 24 piers installed on the front portion of the house
- Lifetime transferrable warranty document and map of piers

## Major Remodeling:

- Jeon Designs, Complete Remodeling & Design, 713-377-6636
- Carpet: All new carpeting and padding, upstairs & downstairs
- Painting: House completely repainted including walls, ceilings, trim, builtins, vanities and closets
- New vanity tops & faucets: Upstairs Jack & Jill bath and Master bath
- Master shower and bathtub completely re-tiled with polished Carrara marble look; All new plumbing and fixtures and new glass shower door; New shower chrome trim + valve; New chrome tub filler fixture
- Tile grout refreshed and sealed (original tile installed in 2009)
- All new electrical outlets throughout the house
- New master closet metal rods
- New staircase banister, iron rods, rail, step refresh
- Refinish back French doors and new locks installed
- Refinished front door
- Kitchen:
  - Freshly painted cabinets (solid wood cabinets)
  - New backsplash
  - Under cabinet lighting
  - 2009 all new appliances
  - 2009 new granite

### Miscellaneous:

- New Toilet paper holders
- New light fixtures: Master bath and vanity, powder bath, kitchen area, dining room
- New fans: All upstairs bedrooms and family room
- New front door lock set & keypad
- New garage entry door

	281-4 TACLB# 008060E	ewilde Ste 101 • Houst 196-9450 • 713-460	)-8874				
NAME Beth M		EMERGENCY SERVICE	TECHAAL	SAW	EEK BEGINNING MILEAGE	MEMBER	
STREET 11510 Del Monte DR					ENDING MILEAGE	TIME IN_ TIME OUT	
CITY L/ STAFFT ZIP-7-						1025 1110 KEY LOCK	
COOLING	MAKE MOD	EL SERIAL NUMBER	(713) (281) WORK PHON	105	-4045	CT WARRANTY	
CHECK LIST			(713) (281) ADVERTISING		·····		
	Courteev'e	Achitection Agroomant			DEC	CI RES. CI COMM.	
D SUCTION PSI		Arbitration Agreement		QTY.		CRIPTION	
	(allves ( Courtesy ) and Custome	ng inc., including it's agents, employees an er mutually agree to submit to binding arb	itration any	1-	Conter	sen	
CHECK THE STARTING CAPABILITIES	that relate to or involve or arise of	oever arising in any way whatsoever betwee ut of the purchase sale use repair service	en them and	1.	Pail		
AMPS      CONDENSER COIL	possession of any air conditioning	or heating good or service as well as any a ted thereto, except for any and all claims G	-utoc lle hne		<u> </u>		
INSPECT COIL & CHECK FIN COND	or may have for any amount ow	red by Customer or services rendered or	hine shoop				
DENT "F LVG"F	rederal Arbitration Act. 9 U.S.C. 1-	bitration ("Disputes for Arbitration"), purs -16, or the Texas General Arbitration Act, Te.	v Civ Prac		Condenser PAS		
D LEAK D CHARGE	a Hem. Lode Chs. 1/1-173, inc	luding applicable amendments and other w of the United States, or the common law	channes to				
I FAN AND MOTOR	of rexas, as may be applicable. Co	ourtesy and Customer further mutually arre	e that hind-		DIA.	PAN	
D VOLTS D AMPS	accordance with the procedures	Business Bureau in Houston, Harris Count and rules of the Better Business Bureau s	shall he the		55	1- Float	
□ INSPECT CONTACTS □ FAN PULLEYS (ADJUST BELT)	ment to arbitrate may be specifical	pute for Arbitration described above; that i lly enforced by a court only in Harris County	their agree-		AS	. A. M.	
CHECK, LUB BEARINGS & MOTOR	that such a court may enter on en	forceable judgement on any arbitration awa	ard.		714	2.4 Guard Switc	
INSPECT COIL & CHECK FIN COND.	Dean Pilot Assembly	TING CHECK LIST ELECTRICAL FURNA	050		2-Sticks	ST8XI AMA	
	Check heat exchanger  Adjust air and gas mixture	most of the above	LES		2-Stick	3/4 Pile	
INSPECT DRAIN LINES	Check pressure on gas valve     Set blower control	t i Check heat strips i i Check breakers and fuses for AM	AP draw		1 11	1. 11/2. 1	
CLEAN DIRTY	Temp comes on Temp goes	I CELEMONTER INCOMESTER			1-STICK	118X1 AMAR	
ELECTRICAL COMP'TS	□ Check blower □ Check fan belt	C) Charle for proper oir flow			Supp	14 Plonum	
CI OVERLOAD CI PRESS SWITCH	Check all safety controls     Check vent for obstructions	HEAT PUMPS most of the above			1:00	of 600 Stat	
FOR PROPER SIZE AND DEFECTS	Lubricate blower motor & all movir     Check & adjust for proper temperat				TTLDV	1-600 VIA	
D O.K. D REPLACE	Check filters	and adjust if needed PMS: \$69 95					
THIS IS A PREVENTATIVE	Check all electrical connections     Check voltage for proper AMP draw	Each additional unit: \$59 95		1	Lugart	-	
MAINTENANCE INSPECTION ONLY Any repairs will require additional	Check evaporator coil il accessible     Check burners and heat exchanger			lotal Parts & I	abor		
charges on parts, labor & materials. NO WARRANTY ON DRAIN LINES.	Check for gas leaks (from the gas c to the furnace parts)	MAINTENANCE INSPECTION ock Any repairs will require addi charges on parts, labor & ma	itional		8 <sup>1</sup> /4% Sale	s Tax	
Description of Work TAUSTALLA CONCENSOR AN WARRAUTY FOR	Vew 3 Ton Vew 3	14 Efficiency Am os with A to year	and the first two property and the second	slad v St. v St.	ANd And	WESSOR	
Recommendations and Addition	mal Work	ing 16/2×20 2 Coi	/				
		labor warranty on all					
		Recommended work not done					
Customer Approval x						and a second	

Ø D											
CO		Tanglewild	DITIONING e Ste 101 • Housto 9450 • 713-460-	on TX,	7706		BBB				
TACLB# 008060E EMERGENCY SERVICE 7 DAYS A WEEK											
NAME BETH HE	Telle Mulphy TECHY					BEGINNING MILEAGE	DATE -25-18				
STREET 1510 DE	el Monte DR					ENDING MILEAGE	TUME IN TIME OUT				
H H	STATE	X	<sup>ZIP</sup> 77617	HOME PHON (713) ( <del>281)</del>		5-4045	KEY LOCK				
COOLING	MAKE	MODEL					C) WARRANTY				
CHECK LIST		_		ADVERTISING			D NORMAL				
COMPRESSOR			ration Agreement	A	QTY.	DESC	CRIPTION				
D VOLTS PSI	Courtesy Air Condition tatives ("Courtesy") a	ning & Heating inc., in and Customer mutually	cluding it's agents, employees and y agree to submit to binding arbit	represen-	1 1-	SCHUTCEI	att- NIC				
ELECTRICAL CONNECTIONS     CHECK THE STARTING	and all disputes of any	/ kind whatsoever arisi	ing in any way whatsoever between purchase, sale, use, repair, service,	them and	1	Decin h	ALLA				
	possession of any air	conditioning or heatin	a and or service as well as any an	d all actu-	7-	DIGT WA	and TU/C				
CONDENSER COIL	or may have for any	amount owed by Cur	g good of schole as well as any and o, except for any and all claims Coustomer or services rendered or g "Disputes for Arbitration"), pursua	bloo oboo		n h					
□ ENT "F LVG "F □ REFRIGERANT	reueral Arbitration Ac	1. 9 U.S.C. 1-16. or the	Civ Dran	/-	Conder	SER					
LEAK     CHARGE     SUPERHEAT	those statutes, or the common law of the United States, or the common law of the State										
D FAN AND MOTOR	of Texas, as may be applicable. Courtesy and Customer further mutually agree that bind- ing arbitration before the Better Business Bureau in Houston, Harris County, Texas in accordance with the procedures and rules of the Better Business Bureau shall be the exclusive means of resolving Dispute for Arbitration described above; that their agree-										
ELECTRICAL CONNECTIONS     INSPECT CONTACTS											
FAN PULLEYS (ADJUST BELT)     CHECK, LUB BEARINGS & MOTOR	ment to arbitrate may be specifically enforced by a court only in Harris County, Texas and that such a court may enter on enforceable judgement on any arbitration award.										
EVAPORATOR COIL	HEATING CHECK LIST										
□ ENT TD "F_LVG TD "F □ CONDENSATE AREAS	Clean Pilot Assembly     Check heat exchanger		ES								
INSPECT DRAIN PAN	Adjust air and gas mixture     Check pressure on gas valve     Set blower control										
	Set blower control     Temp comes on		draw								
ELECTRICAL COMP'TS	Set gas limit     Check blower										
D OVERLOAD D PRESS SWITCH	Check fan belt     HEAT PUMPS     Check all safety controls     most of the above										
FOR PROPER SIZE AND DEFECTS	<ul> <li>Check vent for obstruct</li> <li>Lubricate blower moto</li> <li>Check &amp; adjust for pro</li> </ul>	r & all moving parts	Check from Check unit for proper cycling								
	Check filters  Check vent pipe for lea		and adjust if needed PMS: \$69 95								
THIS IS A PREVENTATIVE	Check all electrical co     Check voltage for prop	nnections	Each additional unit: \$59.95								
Any repairs will require additional	Check evaporator coil it accessible     THIS IS A PREVENTATIVE     MAINTENANCE INSPECTION ONLY					Total Parts & Labor					
charges on parts, labor & materials. NO WARRANTY ON DRAIN LINES.	Check for gas leaks (from the gas cock to the lurnace parts)     Any repairs will require additional charges on parts, labor & materials.				81/4% Sales Tax TOTAL						
Description of Work											
ACI	VIAGNOSTIC	5									
ANSTALL A New 3 Ton Condenser And Coil trom American											
Standard - Comes with A 10 Year Compressor + Parts WAVranty From											
HUMERICAN STANDARD 1552-FIGAT											
Recommendations and Addition	al Work					ADUA Gu	Atch DRSing				

# I YEAR Thirty (30) days labor warranty on all work performed

Customer Approval x \_

Recommended work not done at this time x

Still

IStic

I acknowledge the satisfactory completion of above describe work x \_

Regulated by Texas Dept. of Licenses & Regulations. P.O. Box 12157, Austin, TX 78711, 1-800-803-9202, 512-463-6599, www.license.state.tx.us

Seon Designs

Complete Renovations and Design (713) 377-6636

Compass Concierge LLC

kari.riddle@compass.com

90 5th Ave 3rd floor

New York, NY 10011

(936) 270-8788

### INVOICE# 001142

Appointment: Invoice Date: Customer ID: August 24, 2019 August 26, 2019 00032

Beth Murphy 11510 Del Monte Dr Houston, TX 77077 (713) 705-4045 bethmurp@gmail.com

Shaw Altitude 4002 - iceland 1/2" 6# Padding Schluter 1/2" Square (Shower trim) Tile 12x24 Polished Carrara Marble Look (shower) Shower Floor Mosaic Horizontal Sconces 304242280 56" White Ceiling Fans 550, 60" FR Fan 140 Light Fixtures (Dining, Breakfast, M Bath) Widespread Faucet Grout Refresh Burgler Bars Removal

Paint Wall, Ceiling, Trim, Interior Doors (primer/paint inc) Paint Kitchen Cabinets (special Primer to hide stain, incl.) Paint Laundry Cabinets (special Primer to hide stain, incl.) Swap To Soft-Close Hardware in the Kitchen Carpet Installation, KOOL Glide and Power Stretch Back Door Replacement, Glass Swap + Paint Both Outside Repair Brick at the top of Front Porch (scaffolding invlvd) Replace Tile in Master Shower, build new pan, new, nitch Frameless Shower Glass Door with Chrome Hardware Plumber to connect drain and fixtures (shower + 3 vanit.) Electr. Outlets/Switches, 5 Ceiling fans, 6 fixtures MB Door, New Closet Shelves, Metal Rods, Attic Door Stairrcase Banister, Iron Rods, Rail, Step Refinish, Fr Door Vanity Replacements, New Sinks, Plumbing, Backsplash

Seon Designs

Complete Renovations and Design (713) 377-6636

### INVOICE# 001143

Appointment: Aug Invoice Date: Aug Customer ID: 0003

August 24, 2019 August 26, 2019 00032

Beth Murphy 11510 Del Monte Dr Houston, TX 77077 (713) 705-4045 bethmurp@gmail.com

Compass Concierge LLC 90 5th Ave 3rd floor New York, NY 10011 (936) 270-8788 kari.riddle@compass.com

> Air Filter (20x30) Toilet paper holders Light Fixtures difference between estimate and actual Polished Carrara Marble 12x24 (estimate) Door Stops Front Door Dual Lock-Set + Key Pad (matching key) Rear Doors Lock-Sets + matching key Shower Chrome Trim + Valve (Customer Satisfaction) New Chrome Tub Filler Fixture (Customer to provide) Garage Door Masonite Single Pre-Hung Door RH In-Swing Subway Tile and Grout Additional Closet Rods (courtesy)

Kitchen LED \$300

added 1 for Garag

Additional patches and Texture to rid of build in PT hold 3 Recessed Lights in Upstairs Bath + Undermount LED Kit Install new set of risers to decrease overlap of cur. Treads LockSmith install and program front locks + 2 Back Doors Grout Re-Fresh for Upstairs Bath and Shower Wall Shower Bathrub re-tile labor Fix the leak under the tub (estimate) Touch up Paint after tile work around the tub Kitchen hardware treatment and fix Credit for Soft Close hardware Door del., build-out thresh, install, paint, install locks Window Glass Repair (breakfast area) Refinish AC return grid and Doorbell on Second Floor Remove Backsplash in the kitchen, replace sheet., install

#### Part 2, added items, change order

I declare that the information mentioned above is true and correct to the best of my knowledge.
Signature
Date



**Billing Address** Beth Murphy 11510 Del Monte Drive Houston, TX 77077 USA 1005 Airline Dr Suite A Katy, TX 77493 M37282 TACLB2785C 281-599-3336 Estimate 23186229 Job 242532 Estimate Date 7/18/2019 Technician PAUL RAMIREZ Customer PO

Job Address

Beth Murphy 11510 Del Monte Drive Houston, TX 77077 USA

**Estimate Details** 

Repipe whole house : Estimate is to replace all the galvanized pipe in the home, uponor pex and brass fitting will be used inside walls and attic, 1/4 turn emergency shut off valve will be installed as well, new supply line to every fixture, new ice maker box and washer machine box will be installed.

10 year transferable warranty Uponor pex and brass fittings Sheetrock not included Price includes taxes, materials Andy labor



Billing Address Compass Concierge LLC 90 rth Ave 3rd FL New York, NY 10011 USA 1005 Airline Dr Suite A Katy, TX 77493 M37282 TACLB2785C 281-599-3336 Estimate 23313718 Job 242878 Estimate Date 8/19/2019 Technician PAUL RAMIREZ Customer PO

Job Address Beth Murphy 11510 Del Monte Drive Houston, TX 77077 USA

**Estimate Details** 

Western toilets : Did diagnostic to the toilet in master bathroom, toilet is from 2007. The flush valve is shocked it doesn't flush properly causing a weak flush not allowing water to flow the right way to make a full flush. Toilet in half bathroom by the stairs has the same issue is not flushing correctly. The one upstairs didn't flush at all internal parts are bad. Recommended replacement of toilets with a 2 year warranty. Our toilets have glazed ptraps for better performance and a 3' flush valve. Drain lines and sewer system is good condition.

### Task # Description

1

WESTERN GOOD BASIC ELONGATED FRONT TOILET

# **Allied Foundation Specialists Inc.**

Lifetime Service Agreement Date 1/19/2011

# Allied Foundation Specialists has installed: ( $\mathcal{24}$ ) Exterior Driven

Concrete Piers and/or () Interior Driven Concrete Piers. Address: 11510 DEL MONTE DE HOUSTON, TX 77077

Allied Foundation issues a transferable Limited Lifetime Service Agreement for the area of the foundation that has been underpinned by our company.

If a structure is partially underpinned, settlement may occur in areas not underpinned by Allied, such as the remainder of the perimeter and/or interior of the building. Allied Foundation provides a warranty for the area where piers are installed. The remaining structure not supported by underpinning may move independently and could require additional pier work in the future. Any new installation of piers or repair outside of our service area and agreement will be at an extra cost to the Owner.

Soil conditions, particularly during periods of extended dry weather, may result in new or additional settlement. We do not guarantee that the structure will not experience additional movement. This warranty provides that Allied will re-raise or adjust settled areas where the work has been installed. Our warranty does not include additional underpinning in other areas not supported by our piers.

Access for Exterior piers under warranty will require excavation of some or all piers underpinned by Allied at no cost to the Owner. Any Interior Breakouts and excavation for adjustments, Owner will be responsible for moving furniture, floor removal and replacement. If pier adjustments need to be made by tunneling under the foundation, there will be a \$95/foot (warranty rate only) charge to gain access to the interior piers.

As a result of raising or adjusting piers, new cracks in sheetrock, tile, grout and all rigid surfaces, seen or unseen, can occur. Allied assumes responsibility for the foundation alone. No other part of the structure, interior or exterior, such as doors, windows, cabinets, decks, landscaping, roofs, plumbing, drain lines and electric is covered and is the sole responsibility of the Owner.

Drain lines of any kind: PVC, ABS, or Cast Iron must be properly maintained. Cast Iron and ABS sewer lines deteriorate and leak over a period of time. Our company will void the warranty if sewer lines are leaking under the foundation. Owner must maintain positive drainage away from the foundation with proper grading and control large tree root growth.

This warranty will become Null and Void if any major structural changes have been made after the foundation has been repaired.

Allied Foundation Specialists Inc.

4906 Luella Ave. Deer Park, Texas 77536

281-479-5247 Office

slab82@alliedfoundation.net

281-476-4760 Fax

www.crackedslab.com

