**Property Condition Report** 

**Case Number:** 512-274084

Contract Area: 2D

Address:

**Current Step:** 

1c-Ready to Show Condition

17102 FOREST LN

Step Date:

10/24/2019

City, St Zip: PLANTERSVILLE, TX 77363-0000

**HOC:** Denver

Property Condition Report				
Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-ConditioneHeating/Furnace:HVAC System Duct:	r: OK Missing Missing	HVAC tested and functional?:	N/A	No Central HVAC. Window unit only. Window unit is functional.
Electrical Wiring:Other:Other:	OK Damaged N/A	Electric supply tested and functional?:	Yes	Property successfully energized with generator bypass. One outlet smokes and has burned in the past.
Stove/Range/Oven:Kitchen Cabinets:Other:	Damaged OK OK	Built-in appliances tested and functional?:	Yes	Refrigerator works. Stove is damaged. No space for dishwasher.
Plumbing: Sink: Other:	OK OK N/A	Water supply tested and functional?:	Yes	Plumbing holds pressure.
Water Heater:	ОК	Water heater functional?:	Yes	Water heater shows no signs of leaks. Drained.
Sewer/Septic System:Toilet:Other:	OK OK OK	Sanitary & plumbing system functional?:	Yes	Toilets force flushed with no backup. Antifreeze pour successful.
Roof: Other:	OK N/A	Roofing in acceptable condition?:	Yes	Roof appears in good condition with no active leaks.