

## **SELLER'S DISCLOSURE NOTICE**

©Texas Association of REALTORS®, Inc. 2019

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

CONCERNING THE PROPERTY AT							18418 Atasca Woods Way Humble, TX 77346-3205							
THIS NOTICE IS A DIS	SCLO LLEF	SUR NA S	RE (	OF S S N	OT	A SI	UBSTITUTE FOR A	TH	E C	ONDI PECT	TION OF THE PROPERTY AS TIONS OR WARRANTIES THE SELLER'S AGENTS, OR ANY	BU	JYE	R
Seller is is not o	ccup	ying	the				unoccupied (by Sel mate date) or ne				since Seller has occupied the l	orop	erty	?
Section 1. The Prope This notice does	rty h	as t	he i lish t	tem	s m	arke	d below: (Mark Ye	s (Y)	, No	(N),		y.		
Item	Y	N	U	1	Ite	m		ΙY	N	U	Item	Y	N	U
Cable TV Wiring	1			1			Propane Gas:		1		Pump: sump grinder		<b>/</b>	Ī
Carbon Monoxide Det.	1			1		_	ommunity (Captive)		1		Rain Gutters	1		
Ceiling Fans	1		T	1		AL 10040700	Property		1		Range/Stove	V		
Cooktop		1		1		ot Tu			1	b.,	Roof/Attic Vents	V		
Dishwasher	1	•		1	-	_	om System		1	47	Sauna		<b>/</b>	
Disposal	1			1			vave	1		14	Smoke Detector	V		
Emergency Escape Ladder(s)		~			O	utdo	or Grill		~		Smoke Detector - Hearing Impaired		~	
Exhaust Fans	-1		1	1	P	atio/[	Decking	1			Spa			V
Fences	7		$\vdash$	1			ing System	1		$\Box$	Trash Compactor		<b>/</b>	T
Fire Detection Equip.	J			1	$\overline{}$	ool	9 - ) - 1 - 1 - 1		1		TV Antenna		/	T
French Drain	~	1		1			quipment		J		Washer/Dryer Hookup	/		П
Gas Fixtures	+	~	1	1			laint. Accessories		J		Window Screens	V		Г
Natural Gas Lines			1	1			eater		1		Public Sewer System	1		
Hatarar Gao Emico														
Item				Y	N	U					onal Information			
Central A/C				/			✓electric gas	nun	nber	of un	its: 1			
Evaporative Coolers					<b>/</b>		number of units:							
Wall/Window AC Units					<b>/</b>	'	number of units:					18		
Attic Fan(s)		1990			<b>/</b>		if yes, describe:							
Central Heat				<b>/</b>				nun	nber	of un	its: 1			
Other Heat					<b>/</b>		if yes, describe:						_	
Oven				<b>/</b>			number of ovens:	1			ctrio gas other:			_
Fireplace & Chimney				<b>\</b>			✓woodgas lo			ock_	other: gas			
Carport					<b>✓</b>			atta	_					
Garage				<b>\</b>				atta	che	<u> </u>	number of remotes: 2			
Garage Door Openers				<b>\</b>			number of units:	1			number of remotes: 2			
Satellite Dish & Controls	S				<b>✓</b>		owned lease	_	_		200			
Security System				<b>\</b>	_		ownedlease					7.		
Solar Panels					<b>✓</b>		ownedlease				number of units: 1		. Bally pro	
Water Heater				<b>✓</b>	_		electricgas	_	ther:		number of units			
Water Softener					<b>✓</b>		ownedlease	a tro	om:					
Other Leased Items(s)			i .			<b>/</b>	if yes, describe:				2		_	
(TXR-1406) 09-01-19			Initia	led I	y: B	uyer	,	nd S	eller	So	P:	age '	1 of	6
JLA Realty, 5332 FM 1960 East Suite C I Mark Harden	Humble 7	TX 773	46 d with	zipFon	n® by	zipLogi	x 18070 Fifteen Mile Road, Fras	er, Mict		one: 2817 8026 <u>w</u>		eve Se	If Atas	CR

## 18418 Atasca Woods Way

Concerning the Property at					Humble, TX 77346-3205							
Underground Lawn Sprinkler				auto	automatic manual areas covered:							
					if yes, attach Information About On-Site Sewer Facility (TXR-1407)							
Water supply provided by:	Cit	h w	ell MU	D c	0-0D	unknown	-	ther			-	
Was the Property built before	re 19	78?	ves Vr	10 U	nknow	n anknown	—`	, iiici.				
(If yes, complete, sign,	and a	attach	TXR-1906	conce	ming	lead-based	pair	nt haza	rds).			
										roxim	ate)	
Roof Type: shingles Is there an overlay roof of	ove	ring or	the Pro	perty (	shing	es or roof	cov	ering	placed over existing shingle	es or	roof	
covering)?yes ✓ no	unkı	nown										
Are you (Seller) aware of a are need of repair? yes										defect	ts, or	
La constant de la con												
Section 2. Are you (Selle	r) av	vare of	any defe	ects or	malfu	inctions in	any	of the	e following? (Mark Yes (Y)	if you	ı are	
aware and No (N) if you ar				27.2		eric to April 1	•		,			
Item	TV	N	Item				Y	N	Item	TY	N	
Basement	+•		Floors					<del>                                     </del>	Sidewalks	十		
Ceilings	$\vdash$			ation /	Slah(s	1	Y		Walls / Fences			
Doors				r Walls					Windows		J	
Driveways	1			g Fixtu					Other Structural Component	s	J	
Electrical Systems	~	1		ing Sys							1	
Exterior Walls	1		Roof	ing Cyc	,,,,,,,,		1		THE REPORT OF THE PARTY OF THE	5 70	7 50	
	-	•			1-1-7-		1	ماده داد ماده داد	if necessary):			
If the answer to any of the it			tion 2 is y	es, exp	olain (a	ittach additi	onai	Sneets	s ii flecessary).		191,15	
· crack in dri	+	( C)	1 06-	HALA	1/2	ha 16 C	7716					
ten CICCIO IV	10	,,,	4 00	C/ W/.		Dodalle	10 (1.	1	Res .			
Section 3. Are you (Seller	rl au	vare of	any of th	ne follo	wina	conditions	2 (N	lark Y	es (Y) if you are aware and	No (	N) if	
you are not aware.)	, av	vale of	any or a	ie ione	, willing	Conditions	. ,		50 (1, 11 year are arrained	,	,	
				TY	N	Conditio	n			ΙY	N	
Condition	-					Radon G				<b>─</b>		
Aluminum Wiring Asbestos Components						Settling						
Diseased Trees: oak wilt	_					Soil Move	eme	nt				
Endangered Species/Habita		Proper	tv			Subsurfa			re or Pits			
Fault Lines		1 торо.	.7			Undergro	ound	Stora	ge Tanks		1	
Hazardous or Toxic Waste						Unplatted					/	
Improper Drainage		-				Unrecord	led I	Easem	ents		<b>/</b>	
Intermittent or Weather Spring	nas				1	Urea-forr	nald	ehyde	Insulation		/	
Landfill	.5-					Water Da	ma	ge Not	Due to a Flood Event	100	<b>/</b>	
Lead-Based Paint or Lead-B	ase	d Pt. Ha	azards		1	Wetlands	on	Proper	rty		<b>/</b>	
Encroachments onto the Pro					1	Wood Ro	ot			1.6	/	
Improvements encroaching	_		roperty			Active inf	esta	tion of	termites or other wood		٠,	
					<b>~</b>		destroying insects (WDI)					
Located in Historic District					<b>V</b>	✓ Previous treatment for termites or WDI			for termites or WDI	<b>/</b>		
Historic Property Designation					<b>/</b>	Previous termite or WDI damage repaired				<b>V</b>		
Previous Foundation Repairs					<b>✓</b>	Previous					<b>/</b>	
Previous Roof Repairs					<b>✓</b>				nage needing repair		~	
Previous Other Structural Repairs				W 1111		_		able Ma	ain Drain in Pool/Hot		1	
	•		10 to			Tub/Spa*			A commence of the second second	$\perp$		
Previous Use of Premises for	r Ma	nufacti	ure			gue se						
of Methamphetamine				2 - 1 Te 1	_							
								50				
(TXR-1406) 09-01-19	1	Initialed	by: Buyer:		<u> </u>	and S	eller	50	<u>\$</u> ,	age 2	of 6	

Concernin	g the Property a	t	Humble, TX 77346-32	
		items in Section 3 is yes, explant flamer bed, e		
Section 4.	Are vou (Selle	drain may cause a suction entraper) aware of any item, equipm	nent, or system in or on th	e Property that is in need of repai
necessary	30 20 350		<u></u>	, orpiani (attaon acational attach
				es (Y) if you are aware and chec
wholly or Y <u>N</u>	partly as applic	cable. Mark No (N) if you are	not aware.)	
	Present flood	insurance coverage (if yes, atta	ach TXR 1414).	
_ Z		ding due to a failure or bre		controlled or emergency release of
$\checkmark$	Previous flood	ling due to a natural flood even	t (if yes, attach TXR 1414).	
/	Previous wate TXR 1414).	er penetration into a structure	e on the Property due to a	a natural flood event (if yes, attac
_ ✓	Located wh	nolly partly in a 100-year () (if yes, attach TXR 1414).	floodplain (Special Flood H	azard Area-Zone A, V, A99, AE AC
V		nolly partly in a 500-year fl	oodplain (Moderate Flood H	azard Area-Zone X (shaded)).
	Located wh	nolly partly in a floodway (	if yes, attach TXR 1414).	
-	Locatedwh	nolly partly in a flood pool.		
	Located wh	nolly partly in a reservoir.		
	ver to any of the	above is yes, explain (attach a	dditional sheets as necessa	ry):
*For pu	rposes of this not	ice:	.80	TOTAL REPORT OF THE PROPERTY.
which i	e decianated as 7	ans any area of land that: (A) is id Zone A, V, A99, AE, AO, AH, VE e a high risk of flooding; and (C) n	or AR on the map: (B) has a	rate map as a special flood hazard area a one percent annual chance of flooding ay, flood pool, or reservoir.
area, w	hich is designate s considered to be	d on the map as Zone X (shaded a moderate risk of flooding.	d); and (B) has a two-tenths o	ce rate map as a moderate flood hazar f one percent annual chance of flooding
subject	to controlled inun	dation under the management of t	the United States Army Corps o	
under t	he National Flood	Insurance Act of 1968 (42 U.S.C.	Section 4001 et seq.).	Federal Emergency Management Agenc
of a rive	er or other waterco O-year flood, with	ourse and the adjacent land areas out cumulatively increasing the wa	s that must be reserved for the o hter surface elevation more than	
"Reser water o	voir" means a wat or delay the runoff	er impoundment project operated of water in a designated surface a	rea of land.	rps of Engineers that is intended to retai
(TXR-1406)	09-01-19	Initialed by: Buyer:	_,and Seller: <u>5</u> 05	_, Page 3 of

Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com

18418 Atasca Woods Way

Concerning the Pro	operty at		18418 Atasca Woods W Humble, TX 77346-320	
Section 10. Within persons who re	n the last 4	e inspections and	Seller) received any w	ritten inspection reports from d as inspectors or otherwise complete the following:
Inspection Date	Туре	Name of Inspe	ector	No. of Pages
Note: A buye	r should not rely A buyer sh	on the above-cited repo nould obtain inspections	orts as a reflection of the cur is from inspectors chosen by	rent condition of the Property. the buyer.
Section 11. Check	k any tax exemp	tion(s) which you (Se	ller) currently claim for the	Property:
/Homestead		Senior Citizen	Di Di Ui	sabled
Wildlife Mar	nagement	Agricultural	Man trian trial trial Di	sabled Veteran
Other:		. (1)1	Ui	nknown
_N/A		<u></u>	7 10 00 17	
Section 14. Does requirements of C	Chapter 766 of the	he Health and Safety	Code?* unknown no	yes. If no or unknown, explain.
installed in ad including perf	cordance with the formance, location,	requirements of the build and power source require	ling code in effect in the area	o have working smoke detectors in which the dwelling is located, e building code requirements in more information.
family who w impairment fro the seller to in	ill reside in the dwo om a licensed phys nstall smoke detect	elling is hearing-impaired ician; and (3) within 10 da tors for the hearing-impai	; (2) the buyer gives the seller ys after the effective date, the b	buyer or a member of the buyer's written evidence of the hearing buyer makes a written request for for installation. The parties may electors to install.
Seller acknowledge the broker(s), has i	es that the staten	nents in this notice are enced Seller to provide	true to the best of Seller's inaccurate information or to	belief and that no person, including omit any material information.
Signature of Seller	oughs S	elf 19/15/19 Date	Signature of Seller	Date
Printed Name: 54	even Obrsla	r Sett	Printed Name:	
(TXR-1406) 09-01-19		aled by: Buyer:	and Seller: VDS	, Page 5 of 6
	Produced with zipF	orm® by zipLogix 18070 Fifteen Mile	Road, Fraser, Michigan 48026 www.zipl.ogiz	COM Steve Self Atasca

## ADDITIONAL NOTICES TO BUYER:

- (1) The Texas Department of Public Safety maintains a database that the public may search, at no cost, to determine if registered sex offenders are located in certain zip code areas. To search the database, visit <a href="www.txdps.state.tx.us">www.txdps.state.tx.us</a>. For information concerning past criminal activity in certain areas or neighborhoods, contact the local police department.
- (2) If the Property is located in a coastal area that is seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the Property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information.
- (3) If the Property is located in a seacoast territory of this state designated as a catastrophe area by the Commissioner of the Texas Department of Insurance, the Property may be subject to additional requirements to obtain or continue windstorm and hail insurance. A certificate of compliance may be required for repairs or improvements to the Property. For more information, please review *Information Regarding Windstorm and Hail Insurance for Certain Properties* (TXR 2518) and contact the Texas Department of Insurance or the Texas Windstorm Insurance Association.
- (4) This Property may be located near a military installation and may be affected by high noise or air installation compatible use zones or other operations. Information relating to high noise and compatible use zones is available in the most recent Air Installation Compatible Use Zone Study or Joint Land Use Study prepared for a military installation and may be accessed on the Internet website of the military installation and of the county and any municipality in which the military installation is located.
- (5) If you are basing your offers on square footage, measurements, or boundaries, you should have those items independently measured to verify any reported information.

(6)	The following providers currently provide service to the	Property:	
	Electric: Reliant	4	phone #: 1-877-734-7243
	Sewer: MUD DISANT 152		phone #: 713-462-8906
	Water: Mun District 152		phone #: 713-462-8906
	Cable: Com(95)		phone #: 1 - 8 xx - 266-2278
	Trash: LT'S balbas Sovia		phone #: 936-258-9053
	Natural Gas: Center point		phone #: 1- x 20-332-7143
	Phone Company: N/A	4	phone #: N/A
	Propane: N/A		phone #: NIA
	Internet: Concast		phone #: 1-800-266-2278
			*

(7) This Seller's Disclosure Notice was completed by Seller as of the date signed. The brokers have relied on this notice as true and correct and have no reason to believe it to be false or inaccurate. YOU ARE ENCOURAGED TO HAVE AN INSPECTOR OF YOUR CHOICE INSPECT THE PROPERTY.

The undersigned Buyer acknowledges receipt of the foregoing notice.

Signature of Buyer	Date	Signature of Buyer	Date
Printed Name:		Printed Name:	
(TXR-1406) 09-01-19	Initialed by: Buyer:,	and Seller: 505 ,	Page 6 of 6
	Produced with zipForm® by zipLogix 18070 Fifteen Mile F	Road, Fraser, Michigan 48026 www.zipl.ogix.com	Steve Self Atasca